| ASS. REG. BY: (ASML                                  | 121004413 Rivf3 6450 ASSIGNMENT   |
|--|---|
|  | 2011 1019   |
| From: Date:  | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /                |
| Estimated Cost:                                      | Truck / Trailer or  |
| OTTP / WS / TP RES / OD RES / EVA / INV / MV         | *   |
| To Inspect Vehicle No: 4BH 1016                      | Make: McCGOCS HONZ V (TV 1/4 CO) c.c. 2/43  Colour A/C: Insured / Std / NI / NA |
| at Workshop m/s Gold Ball                            | Colodi  |
| of 1010, BUKIS MERCH LONG 3 #01-11                   | Sp. Keading 16 Py   |
| Insured: CT  | Eng/No:   |
| Policy No.   | C/No: WDF44760323201689   |
| Claims No.   | Gen. Cond: Good / Fair/ Poor / Burnt  |
| Sum Insured: Excess: 500                             | Steering: Inorder / Jammed / Leaked / Burnt or                                  |
| (Client's Record)                                    | Brake: horder / Jammed / Leaked / Burnt or                                      |
| Make of Veh:   | Modi: S/Rim / STD A/Rim or  |
| 1 · 1  | Tyre Size: F: 205/65R16   |
| (Policy Condition)                                   | R:  |
| Remark: The veh had commenced its N/S                | O/S BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /             |
| repair at the time of inspection.                    | TOYO / YOKO or CONTINEMIN   |
| Bal. or Market Value:                                | <u>Front</u> <u>Rear</u>  |
| IDAC Accident Rport: Consistent? : Yes or No         | R/Bal. mm / R/Bal. mm   |
| GIA / PR Seen: Consistent?: Yes or No                | L/Bal mm L/Bal f mm   |
| Est. Repairs: days Res.: Yes or No                   | D.O.A. 01 04 21   |
| Lum Sum: % 3 Val.: Yes or No                         | Survey held at GOLDREU  |
| CA / (REV, / REP. / 24 HRS                           | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or                     |
| Vehicle  | IN/OUT FREE!S & N/S REAR  |
| Date:Person Contacted:                               | The U/C / Chassis frame / Body Structure affected due to collision.             |
| Date / Time Action / Instruction  Repair   1 - 3 > 1 |   |
| 09/04/21@5.58pm revert to Jenny Lew                  | via Merimen   |
| - Color II. 1 Goldon Tever to colliny 2011           | ,   |
|  |   |
|  |   |
|  |   |
|  |   |
| 1 W  |   |
| Date/Time, File Pass to? Preli. Report               | Dave Of Banairi   |
|  | Days Of Repair:   |
| 1) : Final Report                                    | Resurvey No. of Trip: Survey Fee:   |
| Date/Time, File Return to?                           | Transportation:   |
| 2)   | Add Fee:: Site Insp (\$)s+Rs,si   |
|  |   |
|  | : Interview (\$) Photos   |
| Report Format :                                      | : Interview (\$ ) Photos : Tech. Invs (\$ ) Others                              |

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for Investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# **ACCIDENT STATEMENT**

Date of Submission 05/04/2021 15:30 (SGT) Date of Accident 01/04/2021 23:50 (SGT) Exact Location of Accident Blk 216B, Singapore Additional Location Information **CORPORATION RD** Country/State of Loss Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBH101B

#### INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner ENG CHOON ENTERPRISE PTE. LTD. Company Reg No 2XXXXX045N Email Address ..... info@hurryhurry.sg Mobile Phone No (Phone) +65-84851807 Alternative Phone No (Office) +65-84851807

### VEHICLE PARTICULARS

Manufacturer Mercedes Model Vito Variant ..... Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? Yes Vehicle Category Goods vehicle Transmission Auto 2143

### **INSURANCE COMPANY**

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd. Type of Coverage Comprehensive Fleet Policy ..... **Policy Number** WDF44760323201689 Cover Note Number

### DRIVER

Name of Driver YEO JIA CHUAN SXXXX196I



02/11/1986 e Of Birth ccupation Outdoor Date Of Driving Pass 31/12/2020 Driving experience 4 MONTHS Male Gender Mobile Number (Phone) +65-84851807 Alt. Phone Number Email Address info@hurryhurry.sg Address **APT BLK 373 CLEMENTI AVENUE 4** Address complement #07-200 Postcode 120373 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Friend Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Cross Junction Weather Conditions Clear **Road Surface** Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Yes Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? PASSENGER 1 Name JAMES KALDUS TAN Gender ..... Male **DETAILS OF POLICE ACTION** Was the accident reported to the police? Yes Police Station Name Queenstown Neighbourhood Police Centre Police Station Phone No (Phone) +65-18004719999 Alt. Police Station Phone No (Fax) +65-64715299 Police Station Address No. 3 Queensway #01-03 Singapore 149073 Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO THE POLICE REPORT T/20210402/2009 ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Was there any audio recorded?

**SLH4123T** 

SD CARD WITH TP.

Reasons for not uploading a video of the accident

| icle Manufacturer                       | Honda       |
|---|-------------|
| ahicle Model                            | Shuttle     |
| Vehicle Variant                         | -           |
| Vehicle Colour                          | -           |
| Vehicle Category                        | Private car |
| Name of Driver                          | -           |
| Contact Number                          | -           |
| Address                                 |             |
| Address complement                      | -           |
| Postcode                                | -           |
| Insurance Company Name                  | -           |
| Nature Of Damage                        | -           |
| Details of property damaged in accident | -           |
| No. Of Passenger (Including Driver)     | 1           |

# INJURED PERSONS DETAILS

# INJURED 1

| Name of injured person                              | UNKNOWN  |
|---|----------|
| Address   | -        |
| Address Complement                                  | _        |
| Post Code   |          |
| Approximate Age Years Old                           |          |
| Injuries Sustained                                  | -        |
| Injured person in which vehicle?                    | -        |
| Were seat belts worn?                               | SLH4123T |
|   | -        |
| Was this injured conveyed to hospital by ambulance? | -        |

#### SKETCH PLAN

# **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature


Date & Time: 5 APRIL 2011.

Driver's Signature (If driver is not the policyholder)

Date & Time

Reporting Name

Signature



# **Goldbell Engineering Pte Ltd** 8 Tuas Ave 18, Singapore 638892

**Insurer Reference: GBH101B** Repairer Reference: GBH101B

Date calculated: 06/04/2021 4:13 PM

**Full Report** Registration: GBH101B Printed: 06/04/2021 4:21 PM

# **Summary Information**

Claim

Location:

Printed by:

Singapore (SG)

Work Provider:

China Taiping Insurance

GBH101B

Catherine Chong Kai Ling Currency:

(Singapore) Pte Ltd SGD

02/04/21

25

25

Date of Incident: Hire Car Start:

Hire Car End:

Vehicle Details

Actual Repair Days:

Estimated Repair Time:

Claim Reference:

**Vehicle** 

Manufacturer:

Model: Sub Model:

Model Sheet Number:

Registration: VIN number:

Odometer:

**Model Specs** 

FROM 3161988/E827839 MULTI FUNC S-WHEEL **GLOVE BOX LOCKABLE ELEC FOLD DR MIRRORS** LED LIGHT SYSTEM MATRIX COMBI INSTR DRIVER'S SEAT COMF BATTERY 12V 95AH START & STOP SYSTEM WHEELS 6.5J X 16 ALU L/SLIDING DOOR

VAN

PREPARE OFF VEHICLE

MERCEDES-BENZ

VITO (W447) 114 CDI LONG

03 AJ 32 GBH101B

WDF44760323201689

162329

LOAD COMP LED LIGHT PARTITION PNL PREPAR **SMOKER PACKAGE** 

ELEC/HEATED D/MIRROR HIGH BEAM ASSISTANT LIGHT-/RAIN SENSOR **EMISSION STD EURO 6** 

**ALTERNATOR 200A** FILTER W/SEPARATOR SPARE WHEEL

**REAR WIPER** PASSENGER AIRBAG

CLEAR COAT HARD

ROOF CONTROL UNIT INTERIOR MIRROR AIR CONDITIONING

**AUDIO 15** 

TRIM LEATHERETTE PASSENGER TWO SEATER

**BLUEEFFICIENCY** 7-SPEED AUTOMATIK CRUISE CONTROL WOOD FLOOR

WEIGHT 3050KG HEAT ABS GLAZING CPL PAINTED BUMPER/MLDG

ADJ STEERING WHEEL GRILLE TRIM CHROMED REARVIEW CAMERA FRONT SPEAKER CHROME PACKAGE SERVICE CHEK 25000KM **FUEL TANK 70L** TYRE PRESSURE SENSOR TYRES 205/65 R16C TAILGATE GLAZED VEH W/VAN REGIST TWO COAT METALLIC


# Vehicle Condition

# **Vehicle Status**

Pre-Accident Damage: Date of Inspection:

# **Damage Areas**

All □ Underbody ✓



# Labour

| Codo                      | Time Base 10 WU/h                              | Price = 42 | Price = 42.00 SGD/h |  |
|---------------------------|--|------------|---------------------|--|
| Code                      | Description                                    | WU         |                     |  |
| 91-0660 ZAX               | CHECK SAFETY SYSTEM                            | 2.0        | 8.40                |  |
| 54-1011 01                | SHORT TEST                                     | 3.0        | 12.60               |  |
|                           | INCLUDES: CONNECT + DISCONNECT STAR            | 3.0        | 12.60               |  |
|                           | DIAGNOSIS,                                     |            |                     |  |
|                           | PRINT DATA,                                    |            |                     |  |
|                           | DELETE ERROR MEMORY                            |            |                     |  |
| 54-7989 01                | R + R BATTERY EARTH CABLE                      | 1.0        | 4.20                |  |
|                           | (WHEN DISCONNECTING ELECTRIC PLUG AND          |            |                     |  |
| C1 1110 01                | SOCKET CONNECTIONS)                            |            |                     |  |
| 61-1110 01                | RENEW LOWER ENGINE PROTECT                     | 3.0        | 12.60               |  |
| 88-1102 01                | R + R FRONT BUMPER                             | 7.0        | 29.40               |  |
| 88-1108 01<br>88-1400 ZAX | RENEW FRONT BUMPER (REMOVED)                   | 7.0        | 29.40               |  |
| 62-1258 01)               | TROTT BOTH ER ADJUST                           | 2.0        | 8.40                |  |
| 62-1258 01)               | R + R FRONT BUMPER SUPPORT                     | 1.0        | 4.20                |  |
| 82-4813 01                |  | 3.0        | 12.60               |  |
| 02-4013 01                | RENEW BOTH HEADLAMPS                           | 6.0        | 25.20               |  |
| 82-4887 01                | (BUMPER REMOVED)                               |            |                     |  |
| 02-4007 01                | ADDITION TO RENEW HEADLAMP                     | 4.0        | 16.80               |  |
| 82-1110 01                | (VEHICLE WITH LED HEADLAMP) ADJUST HEADLAMPS   |            |                     |  |
| 88-2154 01)               |  | 3.0        | 12.60               |  |
| 88-1858 01                | RENEW RADIATOR GRILLE (REMOVED)                | 1.0        | 4.20                |  |
| 30-1030-01                | R + R FRONT LOWER CROSSMEMBER (BUMPER REMOVED) | 3.0        | 12.60               |  |
| 88-2503 01                | R + R BONNET                                   |            |                     |  |
| 38-2508 01                |  | 9.0        | 37.80               |  |
| 38-4104 02                | RENEW BONNET (REMOVED)                         | 3.0        | 12.60               |  |
| 10 710 <del>7</del> 02    | R + R BOTH FRONT WINGS                         | 9.0        | 37.80               |  |
| 88-4716 01                | (BUMPER REMOVED)                               |            |                     |  |
| 8-4717 01)                | R + R RIGHT FRONT WHEELHOUSE SHELL             | 3.0        | 12.60               |  |
| 0 4/1/ 01)                | RENEW R/F WHEELHOUSE SHELL (REMOVED)           | 1.0        | 4.20                |  |

| Code           | Description   |       | WU       | Price SGD  |
|----------------|---|-------|----------|------------|
| 09-6820 02)    | RENEW CHARGE AIR COOLER   |       | 3.0      | 45         |
| 88-2792 01     | R + R LOWER FRONT SCREEN COVER                                  |       | 7.0      | 12.60      |
| 80-2732        | INCLUDES: R + R WIPER ARMS                                      |       | 7.0      | 29.40      |
| 91-2162 01)    | R + R PASSENGER AIRBAG  |       | 3.0      | 12.66      |
| 68-4901 01     | R + R LUGGAGE TRAY  |       | 3.0      | 12.60      |
| 68-4753 01     | R + R CENTRE CONSOLE  |       |          | 12.60      |
| 91-1905 01)    | R + R AIRBAG-/PRETENSIONING SYSTEM                              |       | 3.0      | 12.60      |
|                | CONTROL UNIT, RENEW IF NECESSARY                                |       | 5.0      | 21.00      |
| 91-2157 01     | R + R DRIVER AIRBAG UNIT,<br>RENEW AFTER CHECK                  |       | 3.0      | 12.60      |
| 68-1121 01     | R + R R/LOWER B-PILLAR TRIM INCLUDES: R + R UPPER B-PILLAR TRIM |       | 4.0      | 16.80      |
| 91-1012 01)    | R + R DRIVER SEAT BELT<br>(TRIM REMOVED)                        |       | 3.0      | 12.60      |
| 91-1042 01)    | R + R PASSENGER SEAT BELT<br>(TRIM REMOVED)                     |       | 3.0      | 12.60      |
| 91-1516 01     | RENEW DRIVER SEAT BELT LOCK                                     |       | 4.0      | 16.80      |
| NO NUMBER      | R + R FRT CTR SEAT BELT   |       | 3.0      | 12.60      |
| 91-1520 01     | RENEW PASSENGER SEAT BELT LOCK                                  |       | 4.0      | 16.80      |
| 72-6575 01     | R + R L/F DOOR TRIM   |       | 5.0      | 21.00      |
| 88-3226 01)    | R + R LEFT MIRROR   |       | 3.0      | 12.60      |
| 72-1595 01     | RENEW L/SLIDING DOOR  |       | 24.0     | 100.80     |
| 72-8487 01     | R + R L/DOOR SEAL   |       | 6.0      | 25.20      |
| 72-4570 01     | R + R L/SLIDING DOOR STRIKER PIN                                |       | 3.0      | 12.60      |
| 72-7806 01)    | R + R LEFT CENTRE GUIDE RAIL                                    |       | 6.0      | 25.20      |
| 72-7843 01)    | R + R L/LOWER SLIDING DOOR BRACKET                              |       | 7.0      | 29.40      |
| 72-7816 01)    | R + R L/LOWER SLIDING DOOR GUIDE RAIL                           |       | 8.0      | 33.60      |
| 60-1740 01     | R + R INTERIOR TRIMS FOR RENEWAL OF THE                         |       | 20.0     | 84.00      |
| 64 L           | L/SIDE PANEL  |       |          | , A        |
|                | (SLIDING DOOR, SEATS AND MATS REMOVED)                          |       |          |            |
| ACT CONTRACTOR | INCLUDES: R + R REAR HEADLINING                                 |       |          |            |
| 63-5772 02     | RENEW L/R SIDE PANEL  |       | 128.0    | 537.60     |
| 61-1740 ZAX    |   |       | 78.0     | 327.60     |
| 60-1750 ZAX    | R + R L/INTERIOR INSULATIONS, RENEW IF NECESSARY                |       | 2.0      | 8.40       |
| 88-8806 01)    | RENEW REAR BUMPER   |       | 2.0      | 8.40       |
| 40-2410 01)    | R + R R/R TYRE (WHEEL REMOVED)                                  |       | 3.0      | 12.60      |
| 40-2410 01)    | R + R TYRE (ADD/WORK)   |       | 1.0      | 4.20       |
| 40-2180 ZAX    | ADDITION TO R + R REAR TYRE (VEHICLE WITHOUT PRODUCTION TYRES)  |       | 1.0      | 4.20       |
| 40-2055 01     | BALANCE ONE WHEEL (WHEEL REMOVED)                               |       | 2.0      | 8.40       |
| 40-2181 ZAX    | ADDITION TO WHEEL BALANCING (FIT ADHESIVE WEIGHTS)              |       | 1.0      | 4.20       |
|                | Labour Cost   | Hrs   | wu       |            |
|                | Panel / Mechanical Labour                                       | 41.90 | 419.0    | 1,759.80   |
|                | Total of Labour   |       |          | 1,759.80   |
| Paint          |   |       |          |            |
| Paint Work     | CVCTEM A7T  | T:    | ma Dasis | 46 1101 /1 |

| Paint Work | SYSTEM AZT                       | Time Basis 10 WU/h |
|------------|----------------------------------|--------------------|
| Code       | Description - TWO COAT METALLIC  | WU Price SGD       |
|            | FRT BUMPER SUPPORT SURFACE PAINT | 6.0                |
|            | BONNET NEW PART PAINTING         | 23.0               |

| Paint Work   | SYSTEM AZT                                | Time Basis 10 WU/h |
|--|---|--------------------|
| Code   | Description - TWO COAT METALLIC           | WU Price SGD       |
|  | R/BONNET HINGE SURFACE PAINT              | 4.0                |
|  | L/SLIDING DOOR NEW PART PAINTING          | 29.0               |
|  | L/STEP BOARD REINF SURFACE PAINT          | 4.0                |
| The state of the s | L/RR SIDE PANEL NEW PART PAINTING         | 55.0               |
| and the same   | L/S PNL REINF CLOSER SURFACE PAINT        | 4.0                |
| The Marie and the Contract of the  | L/LOCK STRIKER REINF SURFACE PAINT        | 4.0                |
|  | L/LWR CLOSING PANEL SURFACE PAINT         | 4.0                |
| ( Year of The Land of  | L/CTR SILL SIDEMEMB SURFACE PAINT         | 4.0                |
|  | L/SILL BOX SURFACE PAINT                  | 4.0                |
|  | FRONT BUMPER NEW PART PAINT K1G/P         | 35.0               |
|  | L/OUT SLDG D/HANDLE NEW PART PAINT K1G/P  | 4.0                |
|  | L/SLDG DOOR HAND TRM NEW PART PAINT K1G/P | 4.0                |
|  | REAR BUMPER NEW PART PAINT K1G/P          | 33.0               |
|  | L/F WING SURFACE PAINT                    | 6.0                |
|  | R/F WING SURFACE PAINT                    | 6.0                |
|  | LEFT FRONT DOOR SURFACE PAINT             | 9.0                |
| Contract of the Contract of the  | BOOTLID/TAILGATE SURFACE PAINT            | 11.0               |

# **Paint Material Per Part**

| Code | Description                               | Price SGD |
|------|---|-----------|
| 0340 | FRT BUMPER SUPPORT SURFACE PAINT          | 9.96      |
| 0471 | BONNET NEW PART PAINTING                  | 72.76     |
| 0476 | R/BONNET HINGE SURFACE PAINT              | 0.50      |
| 1781 | L/SLIDING DOOR NEW PART PAINTING          | 99.07     |
| 2197 | L/STEP BOARD REINF SURFACE PAINT          | 1.99      |
| 3481 | L/RR SIDE PANEL NEW PART PAINTING         | 88.55     |
| 3503 | L/S PNL REINF CLOSER SURFACE PAINT        | 1.25      |
| 3505 | L/LOCK STRIKER REINF SURFACE PAINT        | 1.25      |
| 4299 | L/LWR CLOSING PANEL SURFACE PAINT         | 2.49      |
| 4301 | L/CTR SILL SIDEMEMB SURFACE PAINT         | 1.99      |
| 4303 | L/SILL BOX SURFACE PAINT                  | 3.74      |
| 0281 | FRONT BUMPER NEW PART PAINT K1G/P         | 142.20    |
| 1867 | L/OUT SLDG D/HANDLE NEW PART PAINT K1G/P  | 1.80      |
| 1869 | L/SLDG DOOR HAND TRM NEW PART PAINT K1G/P | 2.70      |
| 2581 | REAR BUMPER NEW PART PAINT K1G/P          | 134.10    |
| 0741 | L/F WING SURFACE PAINT                    | 11.70     |
| 0742 | R/F WING SURFACE PAINT                    | 11.70     |
| 1481 | LEFT FRONT DOOR SURFACE PAINT             | 27.64     |
| 2931 | BOOTLID/TAILGATE SURFACE PAINT            | 35.86     |

| Labour Cost - Paint            |             | Hrs   | WU    | <b>Price SGD</b>                      |
|--------------------------------|-------------|-------|-------|---------------------------------------|
| Factor                         | 42.00 SGD/h |       |       | · · · · · · · · · · · · · · · · · · · |
| Time Paint                     |             |       | 249.0 |                                       |
| Preparation Main Work Metal    |             | 2.50  | 25.0  | 105.00                                |
| Preparation Comp. Work Plastic |             |       |       | 105.00                                |
| Total                          | 40 1000     | 0.80  | 8.0   | 33.60                                 |
| iotai                          | 10 WU/h     | 28.20 | 282.0 | 1,184.40                              |

# Material Cost - Paint New Part Painting

New Part Painting - Plastic K1G/PUR Surface-/Blend Paint Material-constant Metal Preparation Material-constant Plastic **Total**  Price SGD 260.38 280.80 110.07 28.60 12.70 692.55

# **Spare Parts**

| Code |          | Description  | Part Number  | Part Source   | prices as at 2015-06-01<br>Price SGD |
|------|----------|--|--------------|---------------|--------------------------------------|
| 0281 | torn     | EDONT DUMBER   | 447 007 000  |               |                                      |
|      | louis    | FRONT BUMPER   | 447 885 0825 | 9999Original  | 816.00                               |
| 0293 | cal      | FRT LWR BUMPER<br>COVER  | 447 885 0136 | 9051Original  | 70.00                                |
| 0340 | 6/       | FRT BUMPER SUPPORT   | 447 620 0630 | Original      | 456.00                               |
| 0344 | cm       | R/F INN BUMPER REINF   | 447 880 0316 |               | 60.00                                |
| 0352 | Ne /     | R/F BUMPER BRACKET   | 447 880 0724 |               | 53.00                                |
| 0367 | nu/      | FRT LWR BUMPER BRKT  | 126 994 1345 |               | 15.00                                |
| 0410 | X        | GRILLE   | 447 888 3600 |               | 105.00                               |
| 0431 | +        | FRONT MANUFACT<br>BADGE  | 906 817 0416 |               | 0.00                                 |
| 0445 | 1        | UP/CVR RADIAT GRILLE   | 447 885 0236 | 9051 Original | 47.00                                |
| 0471 | 14/      | BONNET   | 447 880 7701 |               | 1,020.00                             |
| 0476 | 1        | R/BONNET HINGE   | 447 880 4600 |               | 54.00                                |
| 0542 | Tr.      | R/H-LAMP STRAP   | 447 905 1804 |               | 870.00                               |
| 0561 | 1        | LEFT HEADLAMP ASSY   | 447 906 2501 | 9             | 1,980.00                             |
| 0562 | Br/      | RIGHT HEADLAMP ASSY  |              |               | 1,980.00                             |
| 0842 |          | Manager and the control of the contr | 447 684 0277 | 3             | 95.00                                |
| 2.2  | Tuen 1   | COVER  | 117 001 0277 | original      |                                      |
| 1735 | . ×      | L/DOOR MIRROR ASSY   | 447 810 4316 | 9051 Original | 920.00                               |
| 1781 | buil!    |  | 447 730 4200 |               | 1,650.00                             |
| 1809 | ne -     | L/SLIDING DOOR SEAL  | 447 731 0900 |               | 220.00                               |
| 1821 | X,       | L/CTR GUIDE RAIL   | 447 760 0247 |               | 220.00                               |
| 1833 | '×       | L/CTR GUIDE RAIL   | 447 766 0237 |               | 180.00                               |
| 1843 | ?        | L/LOWER SLIDING RAIL   |              |               | 98.00                                |
| 1847 | 7        | L/LOWER CONNECTION   |              |               | 84.00                                |
| 1861 | 7        | L/LWR SLDG   | 447 760 1447 |               | 247.00                               |
|      |          | MECHANISM  |              |               | <b></b>                              |
| 1865 | *        | L/SLDG DOOR HAND<br>BRK  | 447 760 0234 | Original      | 75.00                                |
| 1867 | X        | L/OUT SLDG D/HANDLE  | 447 760 0159 | 9B27Original  | 60.00                                |
| 1869 | ×        | L/SLDG DOOR HAND<br>TRM  | 447 760 0116 |               | 35.00                                |
| 1877 | 7.       | L/R DOOR LOCK  | 447 730 3900 | Original      | 625.00                               |
| 1881 | X        | L/R DOOR STRIKER   | 447 730 0013 | Original      | 20.00                                |
| 1883 | 7        | L/INNER HANDLE   | 447 760 0048 |               | 120.00                               |
| 1885 | 7.       | L/R CONTACT PLATE  | 639 820 0011 | Original      | 25.00                                |
| 1887 | ?        | L/LOCKING SWITCH   | 639 820 0654 | Original      | 48.00                                |
| 2011 | ?        | L/SLIDING DOOR COVER   |              |               | 75.00                                |
| 2039 | MG       | L/DOOR TRIM CLIP   | 000 991 7171 | Original      |                                      |
| 2195 |          | L/R SILL TRIM  | 447 680 3106 |               | 37.50                                |
| 2197 | ?        | L/STEP BOARD REINF   | 447 730 2906 | Original      | 250.00                               |
| 2581 | rung     | REAR BUMPER  | 447 885 0038 |               | 90.00                                |
| 3281 | TI       | L/R LAMP   | 447 820 0564 | Original      | 980.00                               |
| 3475 |          |  | 012 989 1771 |               | 550.00                               |
| 3481 | 115      |  |              |               | 0.00                                 |
| J-01 | <b>b</b> | L/RR SIDE PANEL  | 447 630 2700 | Original      | 880.00                               |

| Extra                           | Total                   |                      | -           | 25,555.50  |
|---------------------------------|-------------------------|----------------------|-------------|--|
| f: OEM F<br>n: Non-(<br>u: Used | DEM Parts Subtotal      |                      |             | 0.00<br>25,555.50  |
| 1004                            | ram AIRBAG ECÚ (1)      | AIRBAG MODULE        | Original    | 80 120.00<br>300.00  |
| 1001                            | ALIGNNMENT (1)          | ALIGNNMENT           | Original    | THE CANADA STATE OF THE PARTY O |
| 1000                            | AIRBAG MODULE (1)       | MODULE               | Original    | 1,050.00   |
| 9659                            | AIRBAG/TENS C-UNIT      | 447 900 0900         | Original    | 0.00   |
| 9566                            | R/RR TYRE               | 205/65 R 16 C        | Original    | 620.00<br>195.00   |
| 9552                            | R/RR WHEEL              | 447 401 0301 7X4     | 45Original  | 580.00   |
| 8730                            | INTERCOOLER             | 447 501 1301         | Original    | 1,850.00   |
| 7445                            | ACT DRIVER AIRBAG       | 000 860 1402 91      | 16Original  |  |
| 4663                            | FRT CTR SEAT BELT       | 447 860 2585<br>9C94 | Original    | 720.00   |
|                                 | PASSENGER SEAT BELT     | 447 860 0700<br>9C94 | Original    | 720.00   |
| 4662                            | _                       | 447 860 3785<br>9C94 | Original    | 720.00   |
| 4661                            | DRIVER'S SEAT BELT      | 447 860 2969 90      |             | 80.00  |
| 4655                            | FRT CTR S-BELT LOCK     | 901 860 1169 90      | 051Original | 80.00  |
| 4654                            | A PASS BELT BUCKLE      | 447 860 2469 90      | 051Original | 80.00  |
| 4653                            | DRIVER'S BELT BUCKLE    | 447 860 0202 91      | 16Original  | 1,850.00   |
| 4325                            | ACT / PASSENGER AIRBAG  |                      | Original    | A STATE OF THE STA |
| 4323                            | ★ AIRBAG SYSTEM         | REPLACE              | Original    | 220.00   |
| 4303                            | L/SILL BOX              | 639 610 4500         | Original    | 1,100.00   |
| 4301                            | / 1 L/CTR SILL SIDEMEMB | 447 610 2510         | Original    | 160.00   |
| 4299                            | L/LWR CLOSING PANEL     | 639 610 0007         |             | 0.00   |
| 3505                            | L/LOCK STRIKER REINF    | 447 630 0916         |             | 0.00   |
| 3503                            | L/S PNL REINF CLOSER    | 447 620 0022         | Part Source | Price SGD  |
| code                            | , Description           | <b>Part Number</b>   | Dart Co     |  |

| Code | Description                               | Price SG |
|------|---|----------|
| 1002 | SEALANT (2) sealant                       |          |
| 1003 | ram hdlamp ECU (1) HEADLAMP ECU ? Invoice | 60 20.00 |
| 2039 | [E]: L/DOOR TRIM CLI P: x15               | 300.00   |
|      | Total Extras                              | 0.00     |
|      |   | ገ በጻድ    |

# Final Calculation

|  | SGD       | SGD       |
|--|-----------|-----------|
| parts<br>Total Parts   | 25,555.50 |           |
|  |           | 25,555.50 |
| Labour Time Base 10 WU/h   |           |           |
| Total 419.0 WU X 42.00 SGD/h Total of Labour                       | 1,759.80  |           |
|  |           | 1,759.80  |
| Total Of Extras  |           | 380.00    |
| Doint World Time Barre 40 mm (                                     |           | 360.00    |
| Paint Work Time Base 10 WU/h<br>Labour Cost 282.0 WU X 42.00 SGD/h |           |           |
| Material Cost  | 1,184.40  |           |
| Total Paint Including Material                                     | 692.55    | 1,876.95  |
| Pannin Cost Evaluates COT  |           | 2/07 0.33 |
| Repair Cost Excludes GST  GST (+7.0%)                              |           | 29,572.25 |
| Repair Cost Included GST   |           | 2,070.06  |
|  |           | 31,642.31 |

### **Comments**

\* - USER SUPPLIED DATA NN - NO MANUFACTURERS CODE EXISTS ) - WU PARTIAL INCL IN OTHER POSITIONS

### **Assessment Note**

No assessment notes entered.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Pasul
Ap 90010068

14 days

PIP

Excers: 500

Revert
08/04/21 @1350

Recy Sefore print

OneMotoring

PARF/COE Rebate for Registered Vehicle

| Owner ID Type:   | Company                                |
|--|--|
| Owner ID:  | 045N                                   |
| The first of the first the first of the firs |  |
| Vehicle No.:   | GBH101B                                |
| Vehicle to be Exported:  | No                                     |
| Intended Deregistration Date:  | 09 Apr 2021                            |
| Vehicle Make:  | MERCEDES BENZ                          |
| Vehicle Model:   |  |
| Primary Colour:  | VITO 114 CDI PANEL VAN LONG AT ABS 5DR |
| Manufacturing Year:  | Silver                                 |
| Engine No.:  | 2016                                   |
| Chassis No.:   | 65195033629504                         |
|  | WDF44760323201689                      |
| Maximum Power Output:  | 2 & 8 7 7                              |
| Open Market Value:   | \$38,181.00                            |
| Original Registration Date:  | 21 Feb 2017                            |
| First Registration Date:   | 21 Feb 2017                            |
| Transfer Count:  | 1                                      |
| Actual ARF Paid:   | \$1,910.00                             |
| 是我不是理解理解的证明的证明的证明。 中央社会 自己   |  |
| PARF Eligibility:  | No                                     |
| PARF Eligibility Expiry Date:  | -                                      |
| PARF Rebate Amount:  | \$0.00                                 |
| COE Expiry Date:   | 20 Feb 2027                            |
| COE Category:  | C - Goods Vehicle & Bus                |
| COE Period(Years):   | 10                                     |
| QP Paid:   | \$48,901.00                            |
| COE Rebate Amount:   | \$28,685.00                            |
| Total Rebate Amount:   | \$28,685.00                            |
|  |  |

The information contained herein is correct as at 09 Apr 2021

# **Mercedes-Benz Vito 114 CDI**

Overview

**Financial** 

Accessories

Similar

Research


**Photos** 

Map

PREMIUM AD



# OUR TRUSTED ADVISOR

















(+) Compare

(!) Report Error

# · More

### **Seller Information**

### SG Motor Link Pte Ltd

140 vehicles for sale. 157 sold in past 3 mths

♀ 15 Yishun Industrial Street 1 #01-08

Tel: 62508527 Search cars nearby

Jess 91147113 ΥK 90260360 Ben 91122958

Find out the market value of your existing car for free. Get started

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 06-Apr-2021 | Last Updated on: 06-Apr-2021



https://www.sgcarmart.com/used\_cars/info.php?ID=980556&DL=3392



1/2