

KV

Not Authair
 1/12/2021 \$4800h
 Remy After Pain
 9 days

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Vehicle No : SLV3778L
 Vehicle Model : Honda Freed

Date : 16.04.2021

Estimate Repair Cost

No.	Qty	Parts List Items	
1	1	Rear bumper	\$ 925.30 ✓
2	2	Rear bumper brackets	\$ 48.60 X
3	2	Rear bumper retainers	cl \$ 56.80 ✓
4	2	Rear bumper towing covers	\$ 66.40 X
5	2	Rear bumper reflectors	\$ 117.00 X
6	1 set	Rear bumper clips	\$ 40.00 ✓
7	1	Rear tailgate	Ry \$ 1,209.10 ✓
8	1	Rear tailgate centre logo	m \$ 42.90 ✓
9	1	Rear tailgate "HYBRID" emblem	\$ 74.10 ✓
10	1	Rear tailgate outer chrome handle	warp \$ 204.80 ✓
11	1	Rear tailgate lock	\$ 132.60 ✓
12	1	Rear tailgate weatherstrip	\$ 175.80 ✓
13	2	Rear tailgate dampers	\$ 331.60 X
14	1	Rear tailgate inner trim	288.40
15	2	Rear tailgate reflectors	my car \$ 321.80 ✓
16	1	Rear wiper arm	n/s car \$ 760.60 ✓
17	1	Rear wiper motor	\$ 57.10 X
18	2	Taillamps	\$ 378.90 X
19	2	Rear fender side trims	\$ 1,483.40 X
20	2	Rear fender trim clips	n/s my car \$ 2x585.00 ✓
21	1	Rear end panel	\$ 40.00 ✓
22	1	Rear end panel top garnish	\$ 507.20 ✓
23	1	Rear spare tyre top board	\$ 93.60 ✓
24	1	Rear spare tyre compartment	\$ 857.90 X
25	1	Rear exhaust silencer	R \$ 1,196.60 X
26	1	Rear exhaust silencer mounting	\$ 635.30 X
			\$ 82.50 X
		208 Total	\$ 10,469.90

Parts Special Nett Items

27	1	Rear number plate	\$ 60.00 455a
28	1	Rear windscreen sealant	\$ 40.00 ✓
29	1 set	Reverse sensor	\$ 200.00 ✓
30	1	Reverse camera	\$ 250.00 X
			\$ 550.00
		Total Parts	\$ 11,019.90

Labour

1	Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,200.00	900/-
2	To putty and respray painting on affected areas.	\$ 1,200.00	880/-
3	To remove, replace rear tailgate fittings to facilitate repair.	\$ 300.00	60/-
4	To remove, replace rear windscreen glass.	\$ 200.00	120/-
5	To remove, replace reverse sensor.	\$ 150.00	50/-
6	To remove, replace reverse camera.	\$ 150.00	40/-
7	To remove, replace rear exhaust silencer.	nn \$ 200.00	1/-
8	To check wiring and lightings.	\$ 80.00	20/-

Total Labour \$ 3,480.00

Total Parts and Labour \$ 14,499.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: