

Automobile
Hub.

SmX9528E. 2021 Feb.

Mercedes Benz GLA200

TP China.

WIN247787J196474.

Veron.

Rear Bumper Repair 1758 X

Rear Bumper Clips

50(SN) X

Rear Bumper Side Holder RH

88. X

Rear Bumper Lower Garnish.

457 X

Rear RH Fender Wheel Arc Garnish.

295 ✓

Rear RH Fender Wheel Arc Garnish Clips.

20(SN) ✓

Rear RH Wheel Rim. At

~~1280~~ 750(SN)

Panel Beating.

~~400~~ 200

Spony Painting.

~~400~~ 250

Wiring.

~~50~~ 30

To remove reverse sensor

~~100~~ 50

perform wheel alignment.

~~150~~ 80

5048.00

Labors: 610

total: 1645.50

L/S: 1.3K

03 Days

list: 295

len 10%: 265.50

S.N: 770

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: