

Messages

Claims



General & Workshop De	etails Vehicle & Driver I	Details Vehicle Condition	Taxes & Rati	o Parts & Labour	Miscellaneous			
	Summary							
General Details		V	Workshop Details					
Involving	TPVD BMW 528i (SKQ3002	PE) To	otal Rebate	0				
Date of Loss	2 April 2021	A	mount					
Time of Loss	16:45	N	ett Loss Amount	-\$68,339.00				
Loss Description	oss Description SHD3264U (INSD) REVERSED INTO SKQ3002E (TP) AT CARPARK		ssigned Worksho	LKK AUTO CONSU	ILTANTS PTE LTD (TP)			
Comment			ays of work ompletion *	20				

Messages

Claims



General & Workshop	Details <b>Ve</b>	hicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary				
Vehicle & Driver Det	tails						
/ehicle Registration#	SKQ3002E		Pur	chase Date	DD/MM/YYYY		
Registration State	SINGAPOF	RE	Reg	gistration Date *	19/11/2014		
Mileage	105104		Age	of Vehicle	6		
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMAT	on Dri	ver Details			
Manufacturing Year		2013		CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
				Driver Name	CHAN HONG POW		

CATEGORY	POLICY ASSESSMENT INFORMATION  INFORMATION		CAT	EGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD BMW	B.M.W.	Dat	Date of Birth 22 October 19		DD/MM/YYYY
Model	528i	528I A/T ABS AIRBAGS	Age	9	55	
Туре		•	Occ	cupation	Unknown	
Type of Paint				ucation alification	Other	•
Chassis No		WBA5A52090D284828		ving perience	0	
Engine No		B1420647N20B20A	Driv #	ver License		
Engine Capacity		1997	Lice	ense Type		~
Sum Insured		0	Lice Dat	ense Issue te		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	Singapore	
Address type	Personal Correspondence	~
Gender	Unknown	~
Marital status	Unknown	•
Identification #	S1721075J	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous			
			Summary					
Detailed Assessment		Со	Condition of Vehicle at time of survey					
Inspection Date *	07/04/2021	Ge	neral condition	Good	•			
Total Loss	Yes <b>No</b>	Ste	ering (Serviceable)	Yes	No			
Towing Charges	0		otbrake rviceable)	Yes	No			
Voluntary Excess	0		ndbrake rviceable)	Yes	No			
Compulsory Excess	0	En	gine Modification	Yes	No			
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	e-accident condition	Good	•			

0

#### Tyre Condition

Age of Tyres	
Front Tyre Size	255/30R21
Front left side	CONTINENTAL6mm
Front right side	CONTINENTAL6mm
Spare wheel	
Rear Tyre Size	255/30R21
Rear left side	CONTINENTAL6mm
Rear right side	CONTINENTAL6mm

Messages

Claims



General & Workshop D	etails	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous				
					Summary					
Tax Eligibility & Addit	ional [	Deduction for Parts								
Depr./Bttr%				vage%	0	0				
Discount%	10		Set	tlement%	100					
			Paint l	.abour/Material F	Ratio					
Paint Labour Ratio	Paint Labour Ratio 20		Ca	sh Loss	Yes	No				
Paint Material Ratio	80		Pal	t Supplied by AXA	Yes	No				
						Save				

Messages

Claims



Add		Approve	Deny	Submit	All							
EDIT	SR NO	QUAN MATER	IAL PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1	FRONT BUMPER	Damaged	0	1689	No	0	10	0	0	1520.1
	0	1	FRONT BUMPER CLIPS	Necessary	0	50	No	0	10	0	0	45
	0	1	FRONT BUMPER SIDE HOLDER RH	Necessary	0	85	No	0	10	0	0	76.5
	0	1	FRONT BUMPER SPONGE	Serviceable	0	0	No	0	0	0	0	0
	0	1	FRONT BUMPER LOGO	Necessary	0	89	No	0	10	0	0	80.1
	0	1	FRONT BUMPER SENSOR	Serviceable	0	0	No	0	0	0	0	0

	EDIT	SR NO	QUAN TITY	MATERIAI	L PART NAME	CONDITION		PRICE RKSHOP)	LIST P (SURV		SUPPL PARTS	EMENTARY	DEPR./ BTTR%	DISC OUNT%		SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
		0	1		HEADLAMP RH	Serviceable	0		0		No		0	0		0	0	0
Labo	ur																	
	Add		Approve		Deny	Submit All												
	EDIT	SR NO	REPAIR/	REPLACE R)	PART NAME	ESTIMATE LABOUR AMOUNT		ADJUSTED LABOUR AMOUNT		ESTIMATE PAINT AMOUNT		ADJUSTED PAINT AMOUNT	ACTIC (LABC		СОММЕ	ENT	REMOVE	
		0			PANEL BEATING	0		250		0		0	Revi	ewing				
		0			SPRAY PAINTING	0		250		0		0	Revi	ewing				
		0			WIRING	0		30		0		0	Revi	ewing				
		0			TO REMOVE FRONT BUMPER SENSOR	0		50		0		0	Revi	ewing				

ACT (PA

De



Messages

Claims



#### Assessment Details

General & Workshop Details Vehicle Condition Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary Add Submit All Approve Deny SR **ESTIMATED** ADJUSTED EDIT NAME COMMENT ACTION REMOVE NO AMOUNT AMOUNT

0

OF

REPAIR Reviewing 0

2

DAYS

DAYS



Messages

Claims



## Assessment Details

Details Vehicle & Driver	Details Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
\$0.00	А	djusted Claim Amoun	t \$2,301.70	
ESTIMATE	ADJUSTED			
\$0.00	\$1,721.70			
\$0.00	\$580.00			
	\$0.00 ESTIMATE \$0.00	\$0.00 A  ESTIMATE ADJUSTED  \$0.00 \$1,721.70	\$0.00 Adjusted Claim Amount  ESTIMATE ADJUSTED  \$0.00 \$1,721.70	\$0.00 Adjusted Claim Amount \$2,301.70  ESTIMATE ADJUSTED  \$0.00 \$1,721.70

Submit for Review



Messages


Claims



#### Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



## Assessment Details

General & Workshop D	etails	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Α	Adjusted Claim Amount	\$1,850.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous		\$0.00	\$1,850.00			

Submit for Review