



Pte Ltd

Teamwork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

REPAIR PERFORMA INVOICE

AIG

Vehicle number	SGL 8010Y
Make / Model	Toyota Vios
Chassis number	
Accident date	
Reference	

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	510.00 <i>de</i>
2	REAR BUMPER SIDE BRACKET	60.40 <i>X</i> <i>ny</i>
2	REAR BUMPER RETAINER	71.40 <i>ne</i>
1	REAR END PANEL	575.00 <i>bt</i>
1	REAR END PANEL TOP GARNISH	201.10 <i>cnr</i>
2	REAR TAILLAMP - <i>photo</i>	571.40 <i>cor</i>
2	REAR TAILLAMP PANEL	210.00 <i>Rp</i>
1	REAR EXHAUST SILENCER	596.00 <i>Rp</i>
2	REAR EXHAUST MOUNTING	80.40 <i>X ny</i>
2	REAR FENDER LH/RH	1410.00 <i>Rp</i>
2	REAR FENDER INNER TRIM	450.00 <i>X ny</i>
1	BOOTLID	511.00 <i>bt</i>
1	BOOTLID WEATHERSTRIP	175.80 <i>cut</i>
1	BOOTLID LOGO	48.10 <i>ne</i>
1	BOOTLID EMBLEM-VIOS	45.00 <i>ne</i>
1	BOOTLID EMBLEM-E	35.00 <i>ne</i>
1	BOOTLID EMBLEM - 1.5	40.00 <i>ne</i>
1	BOOTLID EMBLEM - S	38.00 <i>ne</i>
1	BOOTLID EMBLEM - VVTI	180.00 <i>ne</i>
1	BOOTLID OUTER GARNISH	130.00 <i>X ny</i>
1	BOOTLID LOCK	96.00 <i>bt</i>
1	BOOTLID LOCK STRIKER	55.00 <i>Rp</i>
2	BOOTLID HINGE	110.00 <i>Rp</i>
1	SPARE TYRE INNER CENTRE SPONGE	127.00 <i>X 2 X</i>
2	SPARE TYRE SIDE SPONGE	216.00 <i>X 2 X</i>
1	SPARE TYRE TOP BOARD	115.50 <i>R</i>
1	REAR FLOOR PANEL	668.00 <i>Rp</i>
		7326.10
Less 25%		1831.52
Subtotal		5494.58
Balance C/F		5494.58

3097.80
2323.35

<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	REAR NUMBER PLATE	60.00 30.00
1 SET	REAR BUMPER CLIP	80.00 30.00
1 SET	REAR FENDER INNER CLIP	60.00 20.00
1 SET	REAR END PANEL GARNISH CLIP	40.00 20.00
1	REAR JOINT SEALANT	120.00 40.00
1 SET	REAR REVERSE SENSOR	350.00 200.00
1	FLOOR INSULATOR	150.00 20.00
Subtotal		860.00 320
Balance C/F		6354.58
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK FRONT AND REAR WIRING AND LIGHTNING SYSTEM	120.00 30.00
2	REMOVE AND REFIT GARNISH ,LINING AND TRIM FOR REPAIR	200.00 60.00
3	REMOVE AND RENEW EXHAUST ASSY	200.00 20.00
4	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60.00
5	PANEL BEATING ON AFFECTED PANEL	1200.00 700.00
6	SPRAY PAINTING ON AFFECTED PANEL	1200.00 800.00
7	APPLY ANTI RUST ON AFFECTED PANEL	150.00 30.00
Subtotal		3270.00
Grand total		9624.58

Tanjin 097495749
'WP' 2/4/21 C/P

66 days

1/5 Resurvey after repair

Tanjin e 1khant.com

2323.35

320

1680

4323.35

45 \$ 3450

Repair limit \$ 2500
6 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: