

BM WHEELPOWER PTE. LTD.

R REF.: QX1543R
REF.: SKN1158T

CHINA TAIPING

MOTOR CLAIMS DEPARTMENT

Not Authorized
6/1 Day &
Recovery After Paint
3 days



DATE: 9/4/2021
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: TOYOTA ESTIMA
CHASSIS NO.: ACR507120881
ENGINE NO.: 2AZJ029338
YEAR MADE: 2013/2014
ACCIDENT DATE: 6 April 2021

IMATE FOR VEHICLE NO.: SKN1158T

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	TAILGATE WINDOW GLASS		1	\$ <i>Sm</i> X 1,000.00
2	TAILGATE WINDOW GLASS MOULDING		1	\$ <i>NA</i> X 150.00
3	TAILGATE		1	\$ <i>NA</i> X 1,700.00
4	TAILGATE WEATHERSTRIP		1	\$ <i>Sm</i> X 300.00
5	TAILGATE LAMP LH		1	\$ <i>Sm</i> X 400.00
6	TAILGATE CENTER LAMP		1	\$ <i>Sm</i> X 300.00
7	TAILGATE LAMP RH		1	\$ <i>Sm</i> X 400.00
8	TAILGATE HINGE LH		1	\$ <i>NA</i> X 60.00
9	TAILGATE HINGE RH		1	\$ <i>NA</i> X 60.00
10	TAILGATE LOCK		1	\$ <i>NA</i> X 400.00
11	TAILGATE TOYOTA LOGO		1	\$ <i>NA</i> ✓ 70.00
12	TAILGATE EMBLEM "ESTIMA"		<i>28</i> 1	\$ <i>NA</i> ✓ 60.00
13	TAILGATE EMBLEM "AERAS"		1	\$ <i>NA</i> — 70.00
14	TAIL LAMP LH		1	\$ <i>Sm</i> X 400.00
15	TAIL LAMP RH		1	\$ <i>Sm</i> X 400.00
16	REAR BUMPER		1	\$ <i>NA</i> ✓ 570.00
17	REAR BUMPER SPONGE		2	\$ <i>Sm</i> X 190.00
19	REAR BUMPER RETAINER LH		1	\$ <i>Sm</i> X 170.00
20	REAR BUMPER RETAINER RH		1	\$ <i>NA</i> X 170.00
21	REAR BUMPER CLIP		10	\$ <i>NA</i> ✓ 50.00
22	REAR BUMPER SENSOR		4	\$ <i>NA</i> X 1,000.00 X
23	REAR BUMPER REFLECTOR LH		1	\$ <i>Sm</i> X 60.00
24	REAR BUMPER REFLECTOR RH		1	\$ <i>Sm</i> X 60.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL: \$ 8,040.00
LESS 25%: \$ (2,010.00)
PARTS TOTAL: \$ 6,030.00

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
t 6262 8888 f 6452 5333
COMPANY REG. NO.: 200204110W

SPECIAL NETT

REAR NUMBER PLATE & HOLDER	1	\$	<i>Pr</i> X	50.00
WINDSCREEN SEALANT	1	\$	<i>nn</i> X	80.00
BODY SEALANT	1	\$	<i>nn</i> X	50.00

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS	\$	<i>3001</i>	1,800.00
TO REMOVE & REFIT TAILGATE GLASS	\$	<i>nn</i> X	100.00
TO CHECK & RECONNECT ALL NECESSARY WIRING	\$	<i>151</i>	80.00
TO REMOVE & REFIT ALL SENSOR	\$	<i>501</i>	150.00
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)	\$	<i>nn</i> X	150.00
TO REPAIR END PANEL	\$	<i>nn</i> X	150.00
TO APPLY ANTI RUST COATING	\$	<i>nn</i> X	80.00
TO SPRAY PAINT ON THE AFFECTED AREAS	\$	<i>4001</i>	1,600.00

TOTAL:	\$	10,320.00
7% GST:	\$	722.40
GRAND TOTAL:	\$	11,042.40