



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2021

ESTIMATE

NO : QUOT202103-000069(00)

DATE : 31/03/2021

POLICY NO : 999995580

VEH REG NO : SLP7899B

MAKE/MODEL : MERCEDES BENZ GLC250

4MATIC (R18 LED)

CHASSIS NO : WDC2539462F226286

ENGINE NO : 27492030970746

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLP7899B

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	1,850.00	1,850.00
2 Front bumper	1	980.00	980.00
3 Front bumper lower lid	1	260.00	260.00
4 Front bumper side retainer - LH	1	48.00	48.00
5 Front bumper sensor	1	138.00	276.00
6 Front bumper sensor seals	6	8.00	48.00
7 Front bumper clips	15	6.50	97.50
8 Front wheel arch garnish - LH	1	195.00	195.00
9 Front wheel arch garnish clips	8	6.50	52.00
			3,806.50
Add 10%			380.65
			4,187.15
LABOUR			
10 To remove and refit front bumper sensor	1	100.00	100.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat & straighten LH front fender, LH chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
13 To putty & spray on affected areas	1	800.00	800.00
			1,980.00

TOTAL S\$ 6,167.15

ADD GST @ 7% 431.70

GRAND TOTAL S\$ 6,598.85

SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED NINETY-EIGHT AND CENTS EIGHTY-FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE