



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2021

ESTIMATE

NO : QUOT202103-000069(00)

DATE : 31/03/2021

POLICY NO : 999995580

VEH REG NO : SLP7899B

MAKE/MODEL : MERCEDES BENZ GLC250
4MATIC (R18 LED)

CHASSIS NO : WDC2539462F226286

ENGINE NO : 27492030970746

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLP7899B


Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Headlamp assy - LH	1	1,850.00	1,850.00
2 Front bumper	1	980.00	980.00
3 Front bumper lower lid	1	260.00	260.00
4 Front bumper side retainer - LH	1	48.00	48.00
5 Front bumper sensor	2	138.00	276.00
6 Front bumper sensor seals	6	8.00	48.00
7 Front bumper clips	15	6.50	97.50
8 Front wheel arch garnish - LH	1	195.00	195.00
9 Front wheel arch garnish clips	8	6.50	52.00
			3,806.50
		Add 10%	380.65
			4,187.15
LABOUR			
10 To remove and refit front bumper sensor	1	100.00	100.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat & straighten LH front fender, LH chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,000.00	1,000.00
13 To putty & spray on affected areas	1	800.00	800.00
			1,980.00
		TOTAL	S\$ 6,167.15
		ADD GST @ 7%	431.70
		GRAND TOTAL	S\$ 6,598.85

SINGAPORE DOLLAR SIX THOUSAND FIVE HUNDRED NINETY-EIGHT AND CENTS EIGHTY-FIVE ONLY

XS \$ 4,448.60
 1,700.00
 7% \$ 2,748.60
 192.40
 \$ 2,941.00

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16

AIG BUILDING

SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 28/03/2021

ESTIMATE

NO : QUOT202103-000069(00)

DATE : 13/04/2021

POLICY NO : 999995580

VEH REG NO : SLP7899B

MAKE/MODEL : MERCEDES BENZ GLC250
4MATIC (R18 LED)

CHASSIS NO : WDC2539462F226286

ENGINE NO : 27492030970746

REG. DATE : 2017

Estimate Repair Cost to Vehicle No : SLP7899B

Description	Quantity	Unit Price	Amount
		S\$	S\$
SUPPLEMENTARY PARTS			
1 Front grille	1	215.00	215.00
2 Front bumper fog lamp cover - LH	1	55.00	55.00
			270.00
		Add 10%	27.00
			297.00
TOTAL			S\$ 297.00
ADD GST @ 7%			20.79
GRAND TOTAL			S\$ 317.79

SINGAPORE DOLLAR THREE HUNDRED SEVENTEEN AND CENTS SEVENTY-NINE ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE