

# 國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.  
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177  
Email: ktmotorwerk@hotmail.com  
Reg. No.: 53373462B

JN1MC2E2620030443

**Vehicle Number :** GBH6737C  
**Vehicle Model :** NISSAN NV350  
**Accident Date :** 05.04.2021  
**Original Reg Date :** 20.08.2018

**Date :** 07.04.2021  
**Chassis :** JN1MC2E2620030443  
**TP Ins. :** CHINA TAIPING

Justin.

## ESTIMATE

1	1 pc	Tailgate <i>Distorted</i>		2,648.50	1816
2	1 pc	Rear Bumper <i>Delnd</i>		798.50	667.
3	1 pc	End Panel (Outer) <i>Dented</i>		458.90	✓
4	1 pc	End Panel (Inner) <i>Dented</i>		585.60	✓
5	1 pc	Rear Floor Panel <i>Reps</i>		1,589.60	+
6	1 pc	Rear Floor Panel Top Insulator Cloth <i>new</i>		784.30	+
7	1 pc	Tailgate Badge		95.30	✓
8	1 pc	Tailgate Emblem (Urvan) <i>2</i>		98.70	✓
9	1 pc	Tailgate Emblem (NV350)		95.60	✓
10	1 pc	Tailgate Windscreen Inner Seal <i>new</i>		65.00	✓
11	1 pc	Tailgate Windscreen <i>cut</i>		785.80	✓
12	1 pc	Tailgate Outer Chrome Moulding <i>cut</i>		460.20	✓
13	1 set	Tailgate Outer Chrome Moulding Clip <i>new</i>		40.00	20.
14	2 pc	Tailgate number plate lamps <i>new</i>	85.90	171.80	X.
15	1 pc	Tailgate Inner Lock <i>Damaged</i>		325.90	261
16	1 pc	Tailgate lock cover <i>cut</i>		98.50	✓
17	1 pc	Tailgate Lock Catch <i>new</i>		68.70	+
18	1 pc	Tailgate Weatherstrip <i>cut</i>		236.50	✓
19	2 pcs	Tailgate Side Stopper (Male) <i>3pc</i>	38.20	76.40	X
20	2 pcs	Tailgate Side Stopper (Female) <i>2</i>	36.00	72.00	X
21	1 pc	Tailgate Inner Trim Board <i>Delnd</i>		385.90	131
22	1 set	Tailgate Inner Trim Board Clips <i>new</i>		40.00	20.
23	1 pc	Tailgate Inner Cover Plate <i>new</i>		98.50	X
24	2 pcs	Tailgate Hinges <i>3pc</i>	65.00	130.00	+
25	2 pcs	Tailgate Absorber <i>3m</i>	254.80	509.60	+
26	2 pcs	Taillamps <i>LH cut, RH covered</i>	356.30	712.60	449.60
27	2 pcs	Taillamps Inner Sealer <i>new</i>	45.00	90.00	+
28	2 set	Taillamps Clips <i>new</i>	25.00	50.00	20.
29	2 pcs	Rear Bumper Side Retainers <i>new</i>	69.80	139.60	✓
30	1 set	Rear Bumper Clips <i>new</i>		50.00	30
31	1 pc	Rear Bumper Step Panel <i>Dented</i>		358.90	✓
32	1 pc	End Panel Top Plate <i>Dented</i>		258.90	✓
33	1 pc	Rear Exhaust Pipe <i>new</i>		890.10	+
34	2 pcs	Rear Exhaust Mountings <i>2</i>	65.90	131.80	+
35	1 pc	Rear Exhaust Gasket <i>new</i>		59.80	+
36	1 pc	Spare Tyre Carrier		385.70	+

37	1 pc	Rear Air Vent RH <i>New</i>		85.30	X
				13,932.50	
				Less 10%	1,393.25
				<b>12,539.25</b>	

71,521.10  
64,368.89

**Special Nett**

1	1 pc	Rear Windscreen Sealant <i>New</i>		80.00	60
2	1 pc	Tailgate Sticker 70km/h <i>New</i>		20.00	10
3	1 pc	Tailgate Sticker 4 pax <i>New</i>		20.00	10
4	1 set	Body Panel Joint Sealant <i>New</i>		150.00	60
5	1 set	Rear Floor Panel carpet <i>Not New</i>		450.00	+
6	1 set	Rear Floor Panel Wooden Board <i>New</i>		800.00	+
7	1 set	Rear Floor Panel aluminium plate <i>Repeated</i>		600.00	+
8	1 pc	Rear number plate <i>New</i>		50.00	+
9	1 pc	spare tyre <i>New</i>		280.00	+
10	1 set	Reverse Sensor <i>Damaged</i>		250.00	200
				<b>2,700.00</b>	

*Rear Camera, Danged 640 total 400 300*

**Labour charge**

Panel Beating	2,000.00	800
Spray painting	1,800.00	800
Check Wiring on rear tailamps	120.00	30
Anti rust	100.00	60
Remove and install rear windscreen.	150.00	120
Remove and install tailgate parts.	150.00	80
Remove and install carpet and interior.	250.00	60
Remove and install reverse sensor	120.00	50
Remove and install rear exhaust	150.00	X
<b>total</b>	<b>\$ 4,840.00</b>	

**Grand total** *2000* **20,079.25**

Person Incharge: JOHN  
 Direct Contact: 98287487  
 Email: ktmotorwerk@hotmail.com

*Adrian King,  
 h/s 08/04/21.*

*06 Days.*

*total: 9076.89*

*L/S: 72K.  
 (72K)*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: