

Date: 06.04.2021
Vehicle No: SLT1444Z
Model: TOYOTA PRIUS HYBRID 1.8S
Chassis: ZVW506048674-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SKH3172U
Date of Accident: 06.04.2021

*Not Authorized
7 days
L1 Rep @ 8750/hr
Resurvey After Paint*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER <i>450.80</i>	1	<i>mgcmt</i>	\$616.00
2	FRONT BUMPER SIDE BRACKET RH	1	<i>dit</i>	\$82.00
3	FRONT HEADLAMP RH <i>2531.60</i>	1	<i>mgcmt</i>	\$2,637.00
4	FRONT FENDER RH	1	<i>R</i>	\$877.00
5	FRONT FENDER "HYBRID" EMBLEM RH	1	<i>na</i>	\$55.00
6	FRONT FENDER INNER LINER RH	1	<i>sn</i>	\$202.00
7	FRONT PILLAR GARNISH COVER RH	1	<i>sn</i>	\$88.00
8	FRONT SIDE MIRROR ASSEMBLY RH <i>1023</i>	1	<i>cm</i>	\$1,173.00
9	FRONT SIDE MIRROR COVER RH	1	<i>R</i>	\$90.00
10	SIDE SKIRT RH	1	<i>mgcmt</i>	\$594.00
11	FRONT DOOR RH <i>1128.60</i>	1	<i>net/warp</i>	\$1,249.00
12	FRONT DOOR FRAME RUBBER RH	1	<i>sn</i>	\$223.00
13	FRONT DOOR HANDLE RH	1	<i>sn</i>	\$378.00
14	FRONT RIM RH <i>1508.10</i>	1	<i>net</i>	\$1,555.00
15	FRONT ABSORBER RH	1	<i>sn</i>	\$472.00
16	FRONT KNUCKLE ARM RH <i>360.70</i>	1	<i>BY</i>	\$555.00
17	FRONT WHEEL BEARING RH <i>410.60</i>	1	<i>na</i>	\$554.00
18	FRONT CONTROL ARM RH	1	<i>sn</i>	\$631.00
19	FRONT TIE ROD END RH	1	<i>dit</i>	\$155.00
20	REAR DOOR RH <i>1181.75</i>	1	<i>net/warp</i>	\$1,243.00
21	REAR DOOR FRAME RUBBER RH	1	<i>sn</i>	\$175.00
22	REAR DOOR HANDLE RH	1	<i>sn</i>	\$278.00
23	REAR FENDER RH	1	<i>R</i>	\$900.00
24	REAR FENDER INNER LINER RH	1	<i>sn</i>	\$186.00
25	REAR BUMPER <i>497.50</i>	1	<i>mgcmt</i>	\$542.00
26	REAR BUMPER SIDE BRACKET RH	1	<i>sn</i>	\$112.00
27	REAR TAIL LAMP RH	1	<i>sn</i>	\$478.00
28	FRONT BONNET	1		REPAIR

SUB TOTAL	\$16,100.00
LESS 25%	-\$4,025.00
PARTS TOTAL	\$12,075.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date: 06.04.2021
Vehicle No: SLT1444Z
Model: TOYOTA PRIUS HYBRID 1.8S
Chassis: ZVW506048674-2016
Reg.Year: 2017

Third Party Insurer: AIG
Third Party Veh No: SKH3172U
Date of Accident: 06.04.2021

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
2	FRONT FENDER INNER LINER CLIPS RH	1		<i>na</i> \$30.00 X
3	FRONT DOOR INNER TRIM CLIPS RH	1		<i>na</i> \$40.00 X
4	REAR DOOR INNER TRIM CLIPS RH	1		<i>na</i> \$40.00 X
5	REAR FENDER INNER LINER CLIPS RH	1		<i>na</i> \$30.00 X
6	REAR BUMPER CLIPS	1		<i>na</i> \$50.00 ✓
			S/N TOTAL	\$240.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REIFX, REPAIR & READJUST ACCIDENT AREAS & ETC. \$1,600.00 *800*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER RH, FRONT BONNET, FRONT DOOR RH, SIDE SKIRT RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER & ETC. \$1,800.00 *1400*

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH. \$120.00 *60*

LABOUR CHARGES TO REMOVE & REINSTALLED REAR DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF REAR DOOR RH. \$120.00 *60*

LABOUR CHARGES TO REMOVE, REPLACE, REFIX FRONT RIM RH, FRONT ABSORBER RH, FRONT CONTROL ARM RH, FRONT KNUCKLE ARM & ETC. \$250.00 *150*

TO WHEEL ALIGNMENT & BALANCING. \$80.00 *60*

TO DIAGNOSIS FAULT CODE & RESET MEMORY. *na* \$150.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$100.00 *30*

TO TUFF KOTE & UNDERSEAL MATERIALS. \$200.00 *60*

LABOUR TOTAL \$4,420.00

TingAn **TOTAL \$16,735.00**

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

