

Date : 07/04/2021

TO: AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Our Customer : Tan Kok Boon
Vehicle No : SML5755E
Model : Mercedes Benz C180
Manufacture Year : 2013
Date of Accident : 06/04/2021

Total Estimate Repair Days : 10

Total Pages : 2

Attn : Motor Claims Department
Fax: 6415 3727

WDD2040312A8T7689.

Re: Repair Estimate For Third Party Claim against GBE815R

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper <i>Detached</i>	1	\$1,890.00	\$1,890.00 1350	
2	Rear bumper clip <i>new</i>	10	\$9.00	\$90.00 50	
3	Rear bumper side retainer RH <i>3mm</i>	1	\$88.00	\$88.00	✓
4	Rear bumper side retainer LH <i>3mm</i>	1	\$88.00	\$88.00	✓
5	Rear bumper tow hook cover <i>Detached</i>	1	\$68.00	\$68.00	✓
6	Rear bumper chrome RH <i>3mm</i>	1	\$188.00	\$188.00	✓
7	Rear bumper chrome LH <i>new</i>	1	\$188.00	\$188.00	✓
8	Rear bumper chrome centre	1	\$268.00	\$268.00	✓
9	Rear bumper reinforcement <i>Best.</i>	1	\$775.00	\$775.00	2
10	Rear bumper centre bracket <i>new</i>	1	\$162.00	\$162.00	7
11	Reverse sensor <i>2 pieces damaged</i>	4	\$360.00	\$1,440.00 500 (800)	
12	Reverse sensor cable <i>new</i>	1	\$298.00	\$298.00	+
13	Tail lamp RH <i>cracked</i>	1	\$950.00	\$950.00 680	
14	Tail lamp LH <i>new</i>	1	\$950.00	\$950.00	+
15	Tail lamp lower bracket RH <i>3mm</i>	1	\$89.00	\$89.00	+
16	Tail lamp lower bracket LH <i>3mm</i>	1	\$89.00	\$89.00	+
17	Boot lid <i>Detached</i>	1	\$2,170.00	\$2,170.00 2035	
18	Boot lid switch <i>new</i>	1		\$0.00	+
19	Boot lid lock <i>Detached</i>	1	\$285.00	\$285.00	✓
20	Boot lid lock cover <i>new</i>	1		\$0.00	+
21	Boot lid lock cover clip <i>new</i>	5	\$9.00	\$45.00	+
22	Boot lid weatherstrip <i>cut</i>	1	\$180.00	\$180.00	✓
23	Boot lid lower catch <i>new</i>	1	\$24.00	\$24.00	+
24	Boot lid trimboard <i>3mm</i>	1	\$348.00	\$348.00	+
25	Boot lid trimboard clip <i>new</i>	10	\$9.00	\$90.00	+
26	Boot lid chrome <i>cut</i>	1	\$172.00	\$172.00	✓
27	Boot lid "M/B" logo <i>3mm</i>	1	\$68.00	\$68.00	✓
28	Boot lid "7 G-Tronic" emblem <i>new</i>	1	\$98.00	\$98.00	✓
29	Boot lid "C180" emblem	1	\$85.00	\$85.00	✓
30	Boot lid hinge <i>new</i>	2	\$125.00	\$250.00	+
31	Boot lid insulator clip <i>new</i>	8	\$9.00	\$72.00	+
32	Rear license plate lamp <i>new</i>	2	\$38.00	\$76.00	+
33	Rear end panel <i>Detached</i>	1	\$1,235.00	\$1,235.00 3	✓
34	Rear end panel garnish <i>cracked</i>	1	\$156.00	\$156.00	✓

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
35	Rear end panel garnish clip <i>na</i>	7	\$9.00	\$63.00	20.
36	Rear fender top moulding RH <i>ruled</i>	1		\$138.00 \$0.00	20.
37	Rear fender top moulding LH <i>na</i>	1		\$138.00 \$0.00	20.
38	Rear fender top moulding clip <i>na</i>	10	\$9.00	\$90.00	20.
39	Rear fender inner trim RH <i>301</i>	1		\$0.00	+
40	Rear fender inner trim clip <i>301</i>	18	\$9.00	\$162.00	+
41	Spare tyre panel X R	1	R	\$0.00	
42	Spare tyre board X nn	1	\$265.00	\$265.00	
Sub-Total				\$13,555.00	
Less 10%				\$1,355.50	
Sub Total 1				\$12,199.50	
A. Spare Parts (S/Nett)					
1	Cycle & Carriage logo <i>na</i>	1	\$68.00	\$68.00	+
2	Rear number plate w/casing <i>na</i>	1	\$70.00	\$70.00	+
3	Reverse camera <i>na</i>	1	\$388.00	\$388.00	+
Sub Total 2				\$526.00	
Total for Parts				\$12,725.50	
B. Labour					
1	To check wiring.			\$120.00	30.
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,400.00	900.
3	Spray painting all affected parts & areas.			\$1,000.00	80.
4	To spray anti-rust undercoat.			\$90.00	60.
5	To reset head rest system.			\$350.00	
Total Labour				\$2,960.00	2140
Total Repair Cost				\$15,685.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Aun Teng
f Premium Carz Services Pte Ltd

Yours faithfully,

Surveyor's Details	
Name	Adnan Cj
Contact	96853735
Survey Date	08/04/21
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

Supplementary: 88.20 06 Days

total 10326.90

L/S: 8.2K

8.2K



Co. Reg. No: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 8/4/2021

TO: **AIG Asia Pacific Insurance Pte Ltd**
AIG Building
78 Shenton Way, #07-16
Singapore 079120

Our Customer : Tan Kok Boon
Vehicle No : SML5755E
Model : Mercedes Benz C180
Manufacture Year : 2013
Date of Accident : 06/04/2021
Total Estimate Repair Days : 10
Total Pages : 1

Attn : Motor Claims Department
Fax: 6415 3727

Re: Supplementary Repair Estimate For Third Party Claim against GBE815R

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Rear bumper lower bracket <i>1st only</i>	2	\$98.00	\$196.00	<i>98</i>
2	Rear bumper pad <i>new</i>	1	\$445.00	\$445.00	X
	Sub-Total			\$641.00	
	Less 10%			\$64.10	
	Total Supplementary Repair Cost			\$576.90	

Adrian Lj
08/04/21

98
Supplementary: 88.20

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No