

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Veh# : PC82H

Accident Date : 7/4/2021

Location : ANG MO KIO COLLEGE CENTRAL CARPARK

TRAIG.

Ceeilia.

KOH2010184330

Model:

TOYOTA HIACE

(26/4/2016)

3P:

SMA3150X (AIG)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front bumper <i>Repair</i>	845.20	x.	
2	1 pc	Front bumper n/s retainer <i>new</i>	181.40	+	
3	12 pcs	Front bumper n/s clips <i>MC</i>		30.00	+
4	1 pc	Front n/s B pillar (Repair) <i>Repair</i>			
5	1 pc	Front n/s door <i>Dented</i>	2234.57	1680	x.
6	1 pc	Front n/s door weather strip <i>new</i>	380.20	+	
7	1 pc	Front n/s tyre <i>new</i>		+	
8	1 pc	Front n/s tyre rim cap <i>cut</i>	378.17	80 (SN)	
9	1 pc	Rear bumper <i>Repair</i>	535.50	+	
10	1 pc	Rear bumper n/s retainer <i>new</i>	156.20	x.	
11	6 pcs	Rear bumper n/s clips <i>new</i>		18.00	x.
12	1 pc	Rear n/s sliding door <i>Dented</i>	2364.70	1712	
13	1 pc	Rear n/s 'PRIVATE BUS' sticker <i>new</i>		120.00	60 (SN)
14	1 pc	Rear n/s door weatherstrip <i>new</i>			x.
15	1 pc	Rear n/s door windscreen sealant <i>new</i>		80.00	60 (SN)
16	1 pc	Rear n/s door windscreen moulding <i>new</i>		120.00	+
17	1 pc	Rear n/s body panel (Repair) <i>Repair</i>			+
		Sub-Total:	7,075.94	368.00	0
			25%	0%	0%
		After Less %:	5,306.96	368.00	0
		Labour			
1		To remove and replace damaged parts	1,000.00		500
2		To spray painting	1,400.00		1100
3		To remove and refit rear n/s door <i>fitting</i>	120.00	NN	+
4		To remove and replace rear n/s door (Mechanism)	80.00	NN	X
5		To remove and refit front n/s door <i>fitting</i>	100.00	NN	x.
6		To remove and refit rear n/s door windscreen	150.00		80
7		To reset electrical system	100.00	NN	30
8		To check wiring	80.00		30
9		To re-seal anti rust	60.00		40
		Sub-Total:	3,090.00		
		Total:	8,764.96		

Chan San Choon
Director

List 3382
Len 25% : 2544
SN: 200

Labour: 1750
total: 4494
L/s: 3.5k

Adrian Luy.
L/s 08/04/21.
04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

bisSAFE
STAR

AL 8778 1999
24 hr accident call

Mobil 1

PC82H ESTIMATEPg1

