



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDH 9200R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	BUCKLED	1,231.50	1,206.20
2	REAR BUMPER TOW COVER @\$24.90	MISSING	49.80	49.80
1	REAR BUMPER REINFORCE	TO REPAIR SEE LABOUR	538.30	-
2	REAR BUMPER RETAINER @\$41.00	O/S DISTORTED	82.00	41.00
10	REAR BUMPER CLIPS @\$3.00	NECESSARY	30.00	30.00
	LESS 20% DISCOUNT		-386.32	-265.40
			1,545.28	1,061.60
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER SENSOR (SN)	SCRATCHED / DENTED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO PUTTY AND SPRAY PAINT.		380.00	220.00
	LABOUR.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCE.		350.00	200.00
			730.00	420.00
	GRAND TOTAL		2,475.28	1,681.60
	RECOMMENDED COST OF REPAIRS			1,681.60

Report Ref No. CS/SMR21004442/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.