



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21004443/Euf3n2	
			Date: 13/04/2021	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 308H	Veh. Inspected	SMR 6770Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/04/21/2010	Excess (\$)	0.00	
Assign From	HUA YAN	Assign Date	06/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PREVIA	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTEGD56M807173665	Colour	RED	
Odometer	16898 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	4 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	4 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	4 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2021	Inspection Date	07/04/2021	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	