



Borneo Motors

Inchcape
Co. Reg No. : 195700086Z
GST Reg No. : MR-8500000-9
No 2 PANDAN CRESCENT
SINGAPORE 128452 Tel no. 6631 1188



TOYOTA

6107 3848 - 5.2.21

ESTIMATE

Account Details		Customer Details	
THIRD PARTY CLAIM	Account No	Mdm Soong Mei Young 456 East Coast Road Singapore 429029 Mobile: 97351967	
	S1000020 / TPCLAIM		
	Document No		
	0		
	Document Date		
	05/04/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	17/01/2020	SMR6770Y	0	61155	72/DS/SMR6770Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD56M807173665	2AZ1B13366	60	Thomas Pang W T	-/-/-	0.00	-/-/-	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDARY-AJ TP INS: TP VEH SHB308H DATE OF ACC 03.04.2021				50 100.00
2	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR				180.00 ✓
3	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST				122.40 ✓
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00 ✓
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR 360 (photo)				720.00 X
6	B	BP-LAB2 REPLACE ACC DAMAGED PARTS 2 AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS 2				2160 3600.00
7	B	BP-RES2 RESPRAY ACC AFFECTED AREAS 2				1770 3540.00
8	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION				183.18 366.36
9	Z	BP-SLANT SUPPLY SEALANT (NETT) X nn				200.00
10	1	T52159-28959 COVER, RR BUMPER	1.00	596.90		596.90 ✓
11	2	T52155-28080 R/RR BUMPER SUPPORT, 1 X MM	1.00	57.70		57.70
12	3	T52155-28090 R/RR BUMPER SUPPORT, 1 X MM	1.00	40.40		40.40
13	4	T52156-28050 L/R SIDE BPR SUPPORT, 1 X MM	1.00	57.70		57.70
14	5	T52156-28060 L/RR BUMPER SUPPORT, 1 X MM	1.00	40.40		40.40
15	6	S52161-0K040 PIECE RR BUMPER / nlc	10.00	4.10		41.00 ✓

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



Borneo Motors

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462. Tel no: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mdm Soong Mei Yoong	
		Document No.	456 East Coast Road	
		0	Singapore 429029	
		Document Date	Mobile: 97351967	
		05/04/2021		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2019	ACR50R	GFXSK E1	17/01/2020	SMR6770Y	0	61155	72/DS/SMR6770Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD56M807173665	2AZ1B13366	60	Thomas Pang W T	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	7	T81910-13022 R/R BUMPER REFLECTOR, X N/A	1.00	59.80		59.80
17	8	T81920-13022 L/R BUMPER REFLECTOR, X N/A	1.00	59.80		59.80
18	9	T58307-28110 REAR LOWER FLR PANEL, X N/A	1.00	755.40		755.40
19	0	T90975-02064 EMBLEM, SYMBOL / N/A	1.00	72.20		72.20
20	1	T75441-28720 "PREVIA" EMBLEM, / N/A	1.00	57.20		57.20
21	2	T75441-28730 REAR "TOYOTA" EMBLEM, / N/A	1.00	44.10		44.10
22	3	T89341-60051 D1 SENSOR, ULTRASONIC, 1, X N/A	2.00	392.80		785.60

Steve (LKK) WHL N/A
5 days
7/4/21, 11.00am
P/P
My Bel SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd				11,676.96
Acknowledged by Repairer		Please acknowledge receipt of vehicle	Parts 2,668.20	GST 7.00% 817.39
Signature:			Labour 8,642.40	Less 0.00
Date:			Sublet 366.36	
			Lubrication/Fluid 0.00	
			Others 0.00	Amount Due 12,494.35

Customer Copy