

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD917P**AAD2104-***Not Authorized*
11 Sep 812006

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

08 APR 2021**SHD917P**

VF1ABL15AUC283422

RENAULT

LATITUDE

06/04/2021

III

29/12/2017

PART**LIST**

1 BUMPER COVER REAR	\$	<i>Buel cm</i>	561.70	✓
1 BUMPER LOWER REAR	\$	<i>ndl bn</i>	411.90	✓
1 BUMPER REFLECTOR LH	\$	<i>sn</i>	16.60	}
1 BUMPER REFLECTOR RH	\$	<i>sn</i>	16.60	
1 BUMPER BRACKET CTR REAR	\$	<i>sn</i>	98.10	
1 BUMPER BRACKET SIDE RH REAR	\$	<i>sn</i>	82.10	
1 BUMPER RETAINER RH REAR	\$	<i>sn</i>	59.80	
1 BUMPER BRACKET SIDE LH REAR	\$	<i>sn</i>	80.80	
1 BUMPER RETAINER LH REAR	\$	<i>sn</i>	54.20	
1 ABSORBER REAR	\$	<i>sn</i>	217.30	
1 BUMPER BEAM REAR	\$	<i>n</i>	547.80	
1 BUMPER BEAM BRACKET LH REAR	\$	<i>n</i>	114.50	
1 BUMPER BEAM BRACKET RH REAR	\$	<i>n</i>	114.50	}
1 OUTER PANEL REAR (End Panel)	\$	<i>n</i>	745.80	
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i>	404.56	
1 EXHAUST CAP REAR	\$	<i>n</i>	125.40	

\$ 3,651.66**10% \$ 365.17****\$ 3,286.49****Special Nett**

1SET PARKING AID	\$	<i>sn</i>	700.00	X
1SET REAR BUMPER CLIP	\$	<i>na</i>	66.00	✓
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i>	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i>	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i>	10.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD917P

1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET BUMPER LOWER REAR CLIP	\$	nn	66.00	✓
1 EXHAUST MOUNTING REAR	\$	sn	17.82	X
1 LICENSE PLATE WITH HOLDER FRT	\$	sn	120.00	X
2 WINDSCREEN SEALANT	\$	nn	150.00	X
1 WINDSCREEN MOULDING	\$	nn	200.00	X
1 WINDSCREEN INNER SPONGE SEAL	\$	nn	130.00	X

TOTAL \$ 1,029.82**TOTAL PARTS \$ 4,316.31****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 2201

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 3,000.00 2001

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

To reinstall rear bumper parking sensor.

\$ 170.00 601

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ nn 170.00 X

To repair and realign rear exhaust pipe.

\$ 170.00 X

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.

\$ 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 X

To transfer of rear windscreen fittings and conduct water seepage test.

\$ 170.00 X

Trans-cab Auto Services Pte Ltd

AAD2104-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD917P

To check steering geometry and computer wheel alignment

\$ *220.00* X

To Check Electrical Lighting Concerned.

\$ *170.00* X**TOTAL \$ 7,880.00****Over All Total \$ 15,482.81****(LUMP SUM)****Repair Days***10 DAYS**2 days*

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: