

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T

AAD2104-006

Not Authoised

Recovery B4 paint

8964.73

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

06 APR 2021

SHD9046T

JTDKB3FUX03076032

TOYOTA

PRIUS

02/04/2021

AIG

01/11/2018

- | | PART |
|---|--|
| 1 | LENS AND BODY, REAR LAMP, RH |
| 1 | LENS & BODY, REAR COMBINATION LAMP, RH |
| 1 | PANEL SUB-ASSY, QUARTER, RH |
| 1 | LINER, REAR WHEEL HOUSE, RH |
| 1 | COVER, REAR BUMPER |
| 1 | FILLER, REAR BUMPER EXTENSION, RH |
| 1 | GUARD, REAR BUMPER, CENTER |
| 1 | REINFORCEMENT SUB-ASSY, REAR BUMPER |

	LIST		
\$	<i>SL</i>	502.00	X
\$	<i>SL</i>	451.80	X
\$	<i>R</i>	871.50	X
\$	<i>SL</i>	139.80	X
\$	<i>MYOMA</i>	442.60	✓
\$	<i>MY CM</i>	123.70	✓
\$	<i>SL</i>	576.30	X
\$	<i>R</i>	332.70	X
TOTAL	\$	3,440.40	
25%	\$	860.10	
	\$	2,580.30	

Special Nett

- | | |
|---|------------------------------|
| 1 | FENDER LINER CLIP |
| 1 | FENDER CLIP |
| 1 | REAR BUMPER CLIP |
| 1 | END PANEL INNER TRIM CLIP |
| 1 | TYRE |
| 1 | RIM |
| 1 | HUM CAP |
| 2 | WINDSCREEN SEALANT |
| 1 | WINDSCREEN MOULDING |
| 1 | WINDSCREEN INNER SPONGE SEAL |

\$	<i>nn</i>	75.00	X
\$	<i>nn</i>	75.00	X
\$	<i>nn</i>	65.00	<i>50/2</i>
\$	<i>nn</i>	60.00	} X
\$	<i>SL</i>	350.00	
\$	<i>SL</i>	1,879.40	
\$	<i>SL</i>	211.50	
\$	<i>nn</i>	150.00	
\$	<i>nn</i>	200.00	
\$	<i>nn</i>	130.00	
TOTAL	\$	3,195.90	

TOTAL PARTS \$ 5,776.20

LABOUR

Trans-cab Auto Services Pte Ltd

AAD2104-006

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9046T

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>na</i> 250.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,800.00	<i>2801</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>↪</i> 380.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,800.00	<i>2001</i>
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	<i>X</i>
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	<i>↪</i> 170.00	<i>X</i>
TOTAL	\$	4,790.00	
Over All Total	\$	10,566.20	

(PART-BY-PART) Repair Days

10 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: