



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LEONG POH KEE Reg No/Reg Date SMW2681X / 12/11/202 Date In/Mileage 07/04/2021/ 0 Chassis No KNAF3416ML5065925 Engine No G4FGKH753342 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/04/2021/ 15:25	QUK	282 / Kevin Leong	31671			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000			1/2	1 1/2	600			1600.00
REPLACE FRT ¹ BUMPER, SUPPORT, FRT LH FENDER & AFFECTED AREA								700.00
E PNT98000								120.00
PAINT WORK ON FRT ¹ BUMPER & FRT LH ¹ FENDER								80.00
E PNT88000								40.00
REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR								30.00
M SUNDRY								120.00
TO TOP UP AIRCON GAS								50.00
M SUNDRY								50.00
PERFORM TUST PREVENTION								80.00
A 54900099								975.20
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								59.20
A 10028901								540.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								397.60
USING HI-SCAN PRO TEST								344.00
M SUNDRY								506.40
TO SUPPLY FRT NUMBER PLACE WITH FRAME								209.60
M SUNDRY								12.00
SUNDRIES								242.40
E PNT88000								262.40
REPLACE BODY KIT					1.00	1219.00	20.00	30.40
M LAMP ASSY-HEAD, LH	CUT				1.00	74.00	20.00	28.80
M HORN ASSY-LOW PITCH	? X NM				1.00	675.00	20.00	
M CARRIER ASSY-FRONT END MODULE	? X NM				1.00	497.00	20.00	
M BEAM COMPLETE-FR BUMPER	? X NM				1.00	430.00	20.00	
M PANEL-FENDER, LH	X R				1.00	633.00	20.00	
M COVER-FR BUMPER	OR				1.00	262.00	20.00	
M GRILLE-FRONT BUMPER	OR (Black)				1.00	15.00	20.00	
M COVER-FR BUMPER FOG LAMP, LH	? X NM				1.00	303.00	20.00	
M LAMP ASSY-FRONT FOG, LH	? X NM				1.00	328.00	20.00	
M GRILLE ASSY-RADIATOR	OR (centre chrome)				1.00	38.00	20.00	
M GARNISH-RADIATOR GRILLE	? OR				1.00	36.00	20.00	
M MOULDING-FRONT BUMPER, LH	CUT				1.00			

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LEONG POH KEE Reg No/Reg Date SMW2681X / 12/11/202 Date In/Mileage 07/04/2021/ 0 Chassis No KNAF3416ML5065925 Engine No G4FGKH753342 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	07/04/2021/ 15:25	QUK	282 / Kevin Leong	31671			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	ABSORBER-FRONT BUMPER ENERGY	✓	OR		1.00	84.00	20.00	✓ 67.20
M	LAMP ASSY-SIDE REPEATER, LH	✓	CNT		1.00	143.00	20.00	✓ 114.40
M	AIR DUCT-FR BUMPER, LH	?	X N/M		1.00	14.00	20.00	11.20
M	STIFFNER-FR BPR LWR	?	X N/M		1.00	114.00	20.00	91.20
M	BRACKET-FR BUMPER UPR SIDE MTG	?	X N/M		1.00	22.00	20.00	17.60
M	GUARD ASSY-FRONT WHEEL, LH	✓	TN		1.00	95.00	20.00	✓ 76.00
M	ORNAMENT-KIA NO.115	✓	APC		1.00	32.00	20.00	✓ 25.60
M	NEW K3 2020 AURORA BLK PEARL ABP		(Body Kit) ✓	OR	1.00	1721.00	00.00	✓ 1721.00

Estimate

Steve (LKK) 00-NH AL
7/4/21, 3:00pm Excess - ?
P/P
My Bel SH
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to approval from Insurance Company

Confirm & accepted by

Authorised by Repairer

Signature:

Date:

7% GST on Net 8,602.20 8,602.602
Total Payable 9,204

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of the rubber seal or other repair requiring the removal of the windscreen.