Our Ref: SMM8046T Your Ref: SHF77C

5

s/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP	27
1 2 3 4 5	1 1 1 1	PARTS REPLACEMENT - LIST ITEMS  FRONT BUMPER X R  FRONT FENDER LH X R  FRONT QUARTER GLASS LH SCR  SIDE MIRROR LH  FRONT DOOR LH  PD		\$ 919.70	429.10 856 1,205
6	1 1	REAR DOOR LH   ✓ K  REAR FENDER LH		REPAIR	
			SUB TOTAL	\$ 4,143.20	2/490.
			LESS 25%	\$ 1,035.80	-259
			TOTAL AMOUNT	\$ 3,107.40	1,867-

Our Ref: SMM8046T

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT BUMPER CLIPS	Xsvc	\$ 40.00
1	1	FRONT BUMPER LOWER SKIRTING LH	×src	\$ 250.00
2	1	SIDE SKIRTING LH (REPAIR)	xn	\$ 200.00
3	1 1		SCH	\$ 100.00
4	1	FRONT DOOR STRIPE RUBBER LH	10	\$ 100.00
5	1	REAR DOOR STRIPE RUBBER LH	5 CM	\$ 690.00
			SUB TOTAL	\$ 850.00
			TOTAL PARTS COST	\$ 3,797.40

Our Ref: SMM8046T Your Ref: SHF77C

/NO	DESCRIPTION		EST. BY WORKSHOP	
	LABOUR & PAINTWORK			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO CO	OMMENCE REPAIRS; PANEL		
1	BEAT & RESHAPE THE AFFECTED AREAS AND REPLA	CED THE DAMAGED PARTS	\$	700.00
	AND COMPONENTS			
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER			80.00
2	FUNCTIONS			120.00
3	TO CONDUCT WHEEL ALIGNMENT & BALANCING		\$	120.00
4	TO REMOVE & REFIT FRONT DOOR MECHANISM LH		\$	150.00
5	TO REMOVE & REFIT REAR DOOR MECHANISM LH		\$	150.00
6	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS		\$	1,200.00
7	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS		\$	50.00
8	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)		\$	50.00
9	TO VACUUM, WAXING & CLEAN		\$	50.00
10	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS		\$	40.00
10		TOTAL BEFORE GST	\$	6,387.40
		GST 7%	\$	447.12
	TO	OTAL (PARTS & LABOUR):	\$	6,834.52

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a <u>sum of \$ 6,800.00</u> for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng Claims Director Repair day days

LIS

Alto putt

Sun Pin(Urly)

OS/04/2021

L15 \$2,700 5 dus.

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: