

REG. NUMBER: SJP77175
 MAKE/MODEL: Toyota Wish
 CHASSIS NUMBER: JTDER12W403002206

7p china

Uchi in

14 days 1/3
[Signature]

QUANTITY	SPARE PARTS	COST PRICE/2	List
1 PC	Front Number Plate	CM 40 (S/N)	205a
PC			
1 PC	Front Bumper	Bu 601.90	
2 PC	- - Side Retainer (LH/RH)	63.40 X 2	X
1 PC	- - Reinforcement	R 336.30	
1 PC	- - Sponge	CM 128.20	
10 PC	- - Clips	ru 5 X 10	
1 PC	- - Lower Centre Grille	ru 145.70	X
2 PC	- - Fog Cover (LH/RH)	ru 60.70 X 2	X
2 PC	- - Reinforcement Bracket (LH/RH)	77.60 X 2	?
1 PC	Front Grille	ru 117.10	
2 PC	- - Side Stopper Clip (LH/RH)	20 X 2	ru
PC			
1 PC	Bonnet	Bu 665	
2 PC	- Hinge (LH/RH)	R 58 X 2	X
1 PC	- Lock	ru 90	
1 PC	- Outer Chrome	ru 215	
1 PC	- Logo	ru 55	
8 PC	- Insulator Clips	ru 5 X 8	
1 PC	- Inner Seal	ru 45	X
8 PC	- - - Clips	ru 5 X 8	X
PC			
2 PC	Headlamp Assy (LH/RH)	1014.30 X 2	?
PC			
1 PC	Front Brace Panel	R 95	
1 PC	Front Support Panel Assy	Bu 1000	
1 PC	- - - Top Garnish	ru 136	
6 PC	- - - - - Clips	5 X 6	ru

REG. NUMBER: SJP 7717S

MAKE/MODEL: _____

CHASSIS NUMBER: _____

2/3

QUANTITY	SPARE PARTS	COST PRICE	List
2 PC	Front Support Panel Air Guide (LH/RH)	Rm 66X2	X
PC			
2 PC	Horn (LH/RH)	Rm 149 X 2	X
PC			
1 PC	Air Con Condenser	1607	?
PC			
1 PC	Radiator Assy	1824	?
1 PC	- Coolant	48 (S/N)	50/ln
2 PC	- Top Bracket (LH/RH)	58.10 X 2	X
2 PC	- Bush (LH/RH)	38.30 X 2	X
2 PC	- Lower Bush (LH/RH)	38.30 X 2	X
1 PC	- Fan Motor	466	?
1 PC	- Blade	147	?
1 PC	- Cowling	218.70	?
PC			
1 PC	Rear Number Plate	Rm 40 (S/N)	✓
2 PC	- Lockup (LH/RH)	Rm 57.10 X 2	X
PC			
1 PC	Rear Bumper	Rm 500.30	✓
2 PC	- Side Retainer (LH/RH)	Rm 71.10 X 2	LT
2 PC	- Reflector (LH/RH)	Rm 66.60 X 2	X
10 PC	- Clips	Rm 5 X 10	✓
2 PC	- Inner Damper	60 X 2	?
PC			
1 PC	Tailgate	Rm 1275	✓
1 PC	- Glass Moulding (Set)	Rm 120	✓
1 PC	- Sealant	Rm 40 (S/N)	✓
1 PC	- Damping Seal	Rm 20 (S/N)	✓

REG. NUMBER: SJP 7717S

MAKE/MODEL: _____

CHASSIS NUMBER: _____

3/3

QUANTITY	SPARE PARTS	COST PRICE	LIST
1 PC	Tailgate Lock	470	✓
1 PC	- Catch	50	X
1 PC	- Outer Chrome	245	✓
1 PC	- Logo	68	✓
1 PC	- opening switch	165	?
1 PC	- Inner Pull Handle	50	✓
1 PC	- Trim Board	450	✓
13 PC	- - - Clips	5x13	✓
PC			
2 PC	Tail lamp Assy (L/RH)	497.70 x 2	✓
PC			
1 PC	Reverse Sensor Assy	220 (s/n)	✓
PC			
1 PC	N/S Rear Fender	900	✓
1 PC	N/S - - 1/4 Glass	512.10	✓
1 PC	N/S - - - Sealant	40 (s/n)	✓
1 PC	N/S - - - Damping Seal	20 (s/n)	✓
1 PC	N/S - - Inner Trim Board	850	?
1 PC	N/S - - - AIR Vent	114	X
PC			
1 PC	Rear End Panel	468	✓
1 PC	- - - Top Garnish	245	✓
PC			
PC			
PC	LKK Auto Consultants hence notify the Repairer of the following:	Labour K42	1600 1400
PC	• To resurvey before/after spray painting	rear w screen K08	120 ✓
PC	• To display damaged part(s) during resurvey	upholstery K09	120 100
PC	• Parts prices are subject to confirmation		
PC	• Third party survey is on a "Without Prejudice" basis	Air Con Gas K11	100 ✓
PC	• No illegal modification(s) is allowed		
	• Supplemental repair(s) must be resurveyed and is subject to final approval from Insurance Company	under Seating K15	150 ✓
	• Acknowledged by Repairer	tailgate fitting K35	80 60
		reverse sensor K40	60 50
		painting K41	1800 1600
		removing tailgate hardware K03	80 40

K. KIM HIN AUTO PTE LTD

FAX: 64583895