

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6257 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHB76S6U

AAD2104-007

Not Notified
Richard B. G. G. G.

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :
 Date of Registration:

06 APR 2021

SHB7686U
 JTDKB3FU703081687
 TOYOTA
 PRIUS
 02/04/2021
 AIG
 25/01/2019

		PART		LIST	
1	COVER, REAR BUMPER			<i>Bu</i> 442.60	✓
1	REINFORCEMENT SUB-ASSY, REAR BUMPER			332.70	?
1	COVER, REAR BUMPER, LOWER			<i>Lu</i> 15.40	✓
1	GUARD, REAR BUMPER, CENTER			<i>Bu</i> 576.30	✓
1	RETAINER, REAR BUMPER SIDE, LH			<i>Lu</i> 116.50	X
1	RETAINER, REAR BUMPER SIDE, RH			<i>Lu</i> 117.70	X
1	FILLER, REAR BUMPER EXTENSION, LH			<i>Lu</i> 123.70	X
1	FILLER, REAR BUMPER EXTENSION, RH			<i>Lu</i> 123.70	X
1	PANEL SUB-ASSY, BODY LOWER BACK			<i>R</i> 650.30	X
1	LENS AND BODY, REAR LAMP, RH			<i>Lu</i> 502.00	X
1	LENS & BODY, REAR COMBINATION LAMP, RH			<i>Lu</i> 451.80	X
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE			<i>Lu</i> 925.60	X
TOTAL		\$		4,378.30	
25%		\$		1,094.58	
		\$		3,283.73	

		Special Nett	
1SET	PARKING AID	\$	<i>Lu</i> 700.00 X
1SET	REAR BUMPER CLIP	\$	<i>Lu</i> 95.00 <i>Solar</i>
TOTAL		\$	795.00

TOTAL PARTS \$ 4,078.73

LABOUR
 To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.
 \$ *Lu* 380.00 X

Trans-cab Auto Services Pte Ltd

AAD2104-007

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7686U

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	X
Towing Fees	\$	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X

Trans-cab Auto Services Pte Ltd

AAD2104-007

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB76S6U

To transfer of tire, rim and on wheel balancing.	\$	220.00	X
To replace, refix and top up coolant for radiator	\$	170.00	X
To lift-up // out engine with gear box and refit.	\$	4 440.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	380.00	X
TOTAL	\$	9,610.00	
Over All Total	\$	13,688.73	

(PART-BY-PART) Repair Days

25 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To restore before a temporary painting
- To display damaged parts during restorey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault/No Choice" basis
- No illegal modifications is allowed
- Supplementary repair must be received and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date: