

AAD2104-007

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7686U**

*Not Notified*

*Repair B4 paint*

*\$1295.73*

**SHB7686U**

JTDKB3FU703081687

TOYOTA

PRIUS

02/04/2021

**AIG**

25/01/2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

06 APR 2021

	<b>PART</b>
1	COVER, REAR BUMPER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	RETAINER, REAR BUMPER SIDE, LH
1	RETAINER, REAR BUMPER SIDE, RH
1	FILLER, REAR BUMPER EXTENSION, LH
1	FILLER, REAR BUMPER EXTENSION, RH
1	PANEL SUB-ASSY, BODY LOWER BACK
1	LENS AND BODY, REAR LAMP, RH
1	LENS & BODY, REAR COMBINATION LAMP, RH
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE

	<b>LIST</b>	
\$	<i>Bu/Pa</i> 442.60	✓
\$	<i>R</i> 332.70	X
\$	<i>Pa</i> 15.40	✓
\$	<i>R</i> 576.30	✓
\$	<i>Pa</i> 116.50	X
\$	<i>Pa</i> 117.70	X
\$	<i>Pa</i> 123.70	X
\$	<i>Pa</i> 123.70	X
\$	<i>R</i> 650.30	X
\$	<i>Pa</i> 502.00	X
\$	<i>Pa</i> 451.80	X
\$	<i>Pa</i> 925.60	X
<b>TOTAL \$</b>	<b>4,378.30</b>	
<b>25% \$</b>	<b>1,094.58</b>	
<b>\$</b>	<b>3,283.73</b>	

	<b>Special Nett</b>
1SET PARKING AID	
1SET REAR BUMPER CLIP	

\$	<i>Pa</i> 700.00	X
\$	<i>Pa</i> 95.00	<i>50JAL</i>
<b>TOTAL \$</b>	<b>795.00</b>	

**TOTAL PARTS \$ 4,078.73**

**LABOUR**

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *Pa* 380.00 X

**Trans-cab Auto Services Pte Ltd****AAD2104-007**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7686U**

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,200.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>↪</i> 180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>↪</i> 480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>↪</i> 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	<i>↪</i> 380.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↪</i> 380.00	X
To check steering geometry and computer wheel alignment	\$	<i>↪</i> 220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>↪</i> 250.00	X
Towing Fees	\$	<i>↪</i> 150.00	X
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	<i>2201</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>501</i>
To Check Electrical Lighting Concerned.	\$	<i>↪</i> 170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>↪</i> 380.00	X

AAD2104-007

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7686U**

To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 220.00	X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00	X
To lift-up / out engine with gear box and refit.	\$	<i>4</i> 440.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>4</i> 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>9,610.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>13,688.73</b>	

**(PART-BY-PART) Repair Days**

*25 DAYS*

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature:  
Date: