

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0286/2021/HR
DATE : 4-Apr-21
WIP : 22128

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. CHAN PERRY
ADDRESS : 22 CHOACHU KANG ST 64
#02-04
SINGAPORE 689094
TELEPHONE : HP +65 92340491
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : -
VEHICLE NO : **SMA 9335 R**
MODEL CODE : A3 SPORTSBACK 1.0 TF
MODEL YEAR : 22/6/2018
ENGINE NO : CHZ 933727
CHASSIS NO : WAUZZZ8V5JA110102
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Apr-21
PLACE OF ACCIDENT : NEAR KJE HEADING TOWARDS TO PIE VIA BKE

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 9335 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00 ✓	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00 1000 ✓	✓
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,000.00 1100 ✓	✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00 ✓	✓
TOTAL LABOUR CHARGES		:	<u><u>\$ 3,872.00</u></u>	



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 9335 R

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Regis</i>	1	\$ 2,070.00	+	
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 193.00	+	
3	REAR WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	1	\$ 38.00	+	
4	REAR BUMPER GUIDE SECTION - RH ? NN	1	\$ 67.00	?	X
5	REAR WHEEL HOUSING LINER - RH ? NN	1	\$ 240.00	?	X
6	REAR WHEEL HOUSING LINER FIXING PARTS - RH ? NN	1	\$ 57.00	?	X
7	REAR NUMBER PLATE <i>new</i>	S/N	\$ 60.00	+	
8	SUNDRIES ? NN		\$ 200.00	?	X
TOTAL SPARE PARTS		:	\$ 2,925.00		
TOTAL LABOUR CHARGES		:	\$ 3,872.00		
GRAND TOTAL		:	\$ 6,797.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian*
SURVEYED DATE : *07/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *see authorized, 5 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT