

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0131/2021/TF
DATE : 11-Feb-21
WIP : 14770

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 9/2/21
YOUR INSURED VEH NO : SLT 8811 B

NTUC INCOME INSURANCE CO - CLAIMS DEPARTMENT

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSE

SINGAPORE 189556

ATTN: MOTOR CLAIMS DEPT

TEL: FAX: 6338 1504

OWNER'S NAME : MR. CHAN LEON CHI HONG
ADDRESS : 23 BALMORAL PARK
#02-04
SINGAPORE 259852
TELEPHONE : HP +65 94234238
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070151560
VEHICLE NO : **SJS 1912 T**
MODEL CODE : Q3 1.4 TFSI S-TRONIC
MODEL YEAR : 28/10/2020
ENGINE NO : CZD C05420
CHASSIS NO : WAUZZZF32M1011498
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Feb-21
PLACE OF ACCIDENT : HOLLAND ROAD TOWARDS ORCHARD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJS 1912 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HWADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
4	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00	1000
5	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, AND RHS FRONT DOOR.	\$ 3,400.00	1650
6	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	320 = 40 + 40 + 240
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,592.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 1912 T

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dehd</i>	1	\$ 2,161.00	✓
2	FRONT BUMPER CLOSING ELEMENT - RH <i>neu</i>	1	\$ 59.00	+
3	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER <i>neu</i>	2	\$ 190.00	+
4	FRONT BUMPER SPOILER <i>neu</i>	1	\$ 383.00	+
5	FRONT BUMPER AIR GRILLE - RH <i>neu</i>	1	\$ 153.00	+
6	FRONT BUMPER GUIDE SECTION - RH ?	1	\$ 39.00	?
7	FRONT FENDER <i>Dented</i>	1	\$ 1,286.00	✓
8	FRONT FENDER ATTACHMENT PARTS <i>neu</i>	1	\$ 63.00	+
9	FRONT FENDER BRACE - RH ?	1	\$ 88.00	?
10	FRONT FENDER BRACKET - RH ?	1	\$ 32.00	?
11	FRONT WHEEL HOUSING LINER - RH <i>neu</i>	1	\$ 240.00	+
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>neu</i>	1	\$ 101.00	+
13	FRONT WHEEL HOUSING LINER COVER - RH <i>neu</i>	1	\$ 16.00	+
14	FRONT HEADLIGHT MOUTING - RH <i>neu</i>	1	\$ 118.00	+
15	FRONT HEADLIGHT - RH <i>neu</i>	1	\$ 5,589.00	+
16	FRONT HEADLIGHT LIFT CYLINDER - RH <i>neu</i>	1	\$ 210.00	+
17	FRONT WHEEL ARCH TRIM - LH / RH <i>LH NEU RH ut</i>	2	\$ 536.00	✓
18	FRONT DOOR - RH <i>Regis</i>	1	\$ 2,805.00	+
19	FRONT DOOR OUTER SEAL - RH <i>neu</i>	1	\$ 166.00	+
20	FRONT DOOR ATTACHMENT PARTS <i>neu</i>	1	\$ 157.00	+
SUB TOTAL SPARE PARTS			\$ 14,392.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJS 1912 T

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	FRONT DOOR CATCH - RH <i>Not in</i>	1	\$ 120.00	+
22	FRONT DOOR TYRE PRESSURE STICKER - RH <i>Not in</i>	1	\$ 30.00	+
23	FRONT DOOR LOWER COVER - RH <i>Not in</i>	1	\$ 268.00	+
24	FRONT TYRE RIM - LH / RH <i>cut</i>	2	\$ 2,524.00	✓
25	FRONT TYRE - LH <i>cut</i>	1	TBC	✓
26	SUNDRIES <i>?</i>		\$ 300.00	?
TOTAL SPARE PARTS		:	\$ 17,634.00	
TOTAL LABOUR CHARGES		:	\$ 8,592.00	
GRAND TOTAL		:	\$ 26,226.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *07/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Xhe Authorized, 06 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT