

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG21004464/KQF3E2

Date: 26/08/2021

REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Policy No: 0999993660

Date of Loss: 17/03/2021

Nature of Claim: OD

Claim No: 3182609878SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLC487X	Engine No:	G4FGGH612574
Make & Model:	KIA FORTE K3, 1.6 (A)	Chassis No:	KNAFZ411MG5600406
Reg. Date:	29/04/2016 (Man. Year: 2016)	Odometer:	109969 km
Colour:	Metallic Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$51,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R17	Rear Tyre Size:	215/45 R17
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,141.60	2,069.00	1,072.60	34.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	2,980.00	1,240.00	1,740.00	58.39
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,121.60	3,309.00	2,812.60	45.95
- Excess (S\$)	1,700.00	1,700.00	0.00	0.00
(S\$)	4,421.60	1,609.00	2,812.60	63.61
+ GST 7.00/7.00% (S\$)	309.51	112.63	196.88	63.61
Nett Amount (S\$)	4,731.11	1,721.63	3,009.48	63.61

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 07/04/2021 Inspected At:

Tong Luck Auto Pte Ltd (HQ)
160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR - RH (WCP)	Bent / Warped	780.00 F	*780.00 F
2	1		*FRONT DOOR WEATHERSTRIP - RH (WCP)	Serviceable	85.00 F	*- F
3	1		*FRONT DOOR BLACK TAPE (TOP) - RH (WCP)	Necessary	13.00 F	*13.00 F
4	1		*FRONT DOOR BLACK TAPE (SIDE) - RH (WCP)	Necessary	12.00 F	*12.00 F
5	20		*FRONT DOOR TRIMBOARD CLIPS - RH	Necessary	77.00 FS	*50.00 FS
6	1		*REAR DOOR - RH (WCP)	Bent	680.00 F	*680.00 F
7	1		*REAR DOOR REGULATOR GEAR - RH (WCP)	Cracked	280.00 F	*280.00 F
8	1		*REAR DOOR REGULATOR MOTOR - RH (WCP)	Serviceable	120.00 F	*- F
9	1		*REAR DOOR WEATHERSTRIP - RH (WCP)	Serviceable	85.00 F	*- F
10	1		*REAR DOOR BLACK TAPE (TOP) - RH (WCP)	Necessary	13.00 F	*13.00 F
11	1		*REAR DOOR BLACK TAPE (SIDE) - RH (WCP)	Necessary	12.00 F	*12.00 F
12	2		*REAR DOOR HINGES - RH (WCP)	Repair	56.00 F	*- F
13	20		*REAR DOOR TRIMBOARD CLIPS - RH	Necessary	77.00 FS	*50.00 FS
14	1		*REAR SPORT RIM - RH (WCP)	Serviceable	580.00 F	*- F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	2,870.00	1,890.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	271.60	179.00
Total Parts (\$\$)	3,141.60	2,069.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	TO TRANSFER RH FRONT & REAR DAMAGED DOOR INTERIOR MECHANISM TO NEW DOOR	New	200.00	120.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT RH FRONT DOOR, RH CENTER PILLAR, RH REAR FENDER INCLUDING REPLACEMENT OF PARTS & ALIGN WHERE NECESSARY TO REFIT AND ADJUST THE SAME	New	1,200.00	500.00
4	TO PUTTY & SPRAY PAINT ON AFFECTED AREAS	New	1,500.00	600.00
Gross Labour Cost (\$)			2,980.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >