



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Daimler Fleet Management Singapore Pte Ltd 1 Gateway Drive #15-08 Westgate Tower Singapore 608531 Contact No Home: 88762075 AZMAN	Cust No/Name LA000197/Daimler Fleet Management Singap Reg No/Reg Date SLC487X / 29/04/201 Date In/Mileage / 0 Chassis No KNAFZ411MG5600406 Engine No G4FGGH612574 Make/Model KIA/FORTE K3 1.6 A SX ADR BROWN Colour/Trim ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	30/03/2021/ 09:13	EDW	261 / Edwin Caina	31264			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2560.00
RENEW RHF DOOR & RHR DOOR								
REPAIR RHR FENDER								
E PNT98000								1650.00
RESPRAY RHF DOOR , RHR DOOR & RHR FENDER								
E PNT88000								280.00
REMOVE & REFIT RHR DOOR COMPONENT								
E PNT88000								280.00
REMOVE & REFIT RHF DOOR COMPONENT								
A 54900099								50.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								280.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								50.00
Sundries								
M PANEL ASSY-REAR DOOR,RH					1.00	1361.00	00.00	1361.00
M PANEL ASSY-FRONT DOOR,RH					1.00	1542.00	00.00	1542.00
M BLACK TAPE-FR DR FRAME UPR,RH					1.00	13.00	00.00	13.00
M BLACK TAPE-FR DR RR,RH					1.00	12.00	00.00	12.00
M TAPE-RR DR FRAME BLACK RR,RH					1.00	8.00	00.00	8.00
M BLACK TAPE-RR DR FRAME UPR,RH					1.00	11.00	00.00	11.00
M HINGE ASSY-RHR DR UPP					1.00	28.00	00.00	28.00
M HINGE ASSY-RHR DR LWR					1.00	26.00	00.00	26.00
M REGULATOR ASSY-RR DR WDO RH					1.00	327.00	00.00	327.00
M MOTOR ASSY-POWER WDO REG RR,RH					1.00	155.00	00.00	155.00

Confirm & accepted by

	Nett	8,633.00
7% GST on	8633.00	604.31
Total Payable		9,237.31

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.