



FALCON-AIR

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Page 1 / 2

LIM QUI PING, JOAN
BLK 627 JURONG WEST STREET 65 #08-384
SINGAPORE 640627

Attention : Motor Claim Department
Contact : 86680777

Estimate : ES003766

Date : 07/04/2021
Vehicle Num. : SKZ1599R
Make/Model : MITSUBISHI ATTRAGE
Chassis/Eng# : MMBSTA13AFH015911
Accident Date : 07/04/2021
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	BOOTLID		828.00
2.	1	BOOTLID LOGO		41.00
3.	1	BOOTLID LOCK		206.00
4.	1	BOOTLID EMBLEM MIVEC		35.00
5.	1	BOOTLID EMBLEM ATTRAGE		38.00
6.	1	REAR END PANEL		402.00
7.	1	REAR END PANEL TOP GARNISH		65.00
8.	1	REAR END PANEL AIRDUCT		80.00
9.	1	REAR BUMPER		708.00
10.	2	REAR BUMPER SIDE RETAINER LH/RH	30.00	60.00
11.	2	TAIL LAMP LH/RH	276.00	552.00
12.	2	REAR FENDER LH/RH	715.00	1,430.00
Nett Total S\$:				4,445.00
10.00% Discount S\$:				444.50
				4,000.50
SPECIAL NETT ITEMS :				
1.	1	SEALANT		40.00
Special Nett Total S\$:				40.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

LIM QUI PING, JOAN
BLK 627 JURONG WEST STREET 65 #08-384
SINGAPORE 640627

Attention : Motor Claim Department
Contact : 86680777

Estimate : ES003766

Date : 07/04/2021
Vehicle Num. : SKZ1599R
Make/Model : MITSUBISHI ATTRAGE
Chassis/Eng# : MMBSTA13AFH015911
Accident Date : 07/04/2021
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO TRANSFER BOOTLID PARTS		50.00
		TO REMOVE/REFIX REAR WINDSCREEN GLASS		120.00
		TO REMOVE & REFIT REAR PETROL-TANK		100.00
		TO REMOVE/REFIX CUSHION SEAT,CARPET,GARNISH,WIRING		180.00
		TO RUSTPROOF & WATER LEAKAGE TEST		200.00
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING		100.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		1,500.00
		TO CUT/OUT REWELD REAR FENDERS LH/RH , REAR END PANEL		
		REPAIR REAR CHASSIS , SPARE TYRE PANEL INCLUDES		
		KNOCKING & REPLACEMENT OF PARTS		1,200.00
		Labour Total S\$:		3,450.00

SingDollars : Seven Thousand Four Hundred Ninety & Cents Fifty Only

E. & O.E.

Total S\$: 7,490.50



for FALCON AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 ▪ No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

INSURER ENQUIRY

Find
insurer

Vehicle reg. no.

SLU3551D

Date of Accident

07/04/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance China Taiping Insurance (Sing...

Period of Insurance 04/09/2020 - 03/09/2021

Requested By Andy Esperanza (FALCON-AIR ...

Requested Date 07/04/2021 11:25

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**