

FALCON-AIR

LIM QUI PING, JOAN
BLK 627 JURONG WEST STREET 65 #08-384
SINGAPORE 640627

Estimate : ES003766

Attention : Motor Claim Department
Contact : 86680777Date : 07/04/2021
Vehicle Num. : SKZ1599R
Make/Model : MITSUBISHI ATTRAGE
Chassis/Eng# : MMBSTA13AFH015911
Accident Date : 07/04/2021
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	NETT ITEMS:		
2.	1	BOOTLID <i>bt</i>		828.00 ✓
3.	1	BOOTLID LOGO <i>ne</i>		41.00 ✓
4.	1	BOOTLID LOCK <i>bt</i>		206.00 ✓
5.	1	BOOTLID EMBLEM MIVEC <i>ne</i>		35.00 ✓
6.	1	BOOTLID EMBLEM ATTRAGE <i>ne</i>		38.00 ✓
7.	1	REAR END PANEL <i>bt</i>		402.00 ✓
8.	1	REAR END PANEL TOP GARNISH <i>de</i>		65.00 ✓
9.	1	REAR END PANEL AIRDUCT <i>?cm</i>		80.00 ✓
10.	2	REAR BUMPER <i>de</i>		708.00 ✓
11.	2	REAR BUMPER SIDE RETAINER LH/RH <i>ne</i>	30.00	60.00 ✓
12.	2	TAIL LAMP LH/RH <i>LH-SEA, RH-XSU</i>	276.00 ✓	552.00 X
		REAR FENDER LH/RH <i>bt</i>	715.00	1,430.00 ✓
		Nett Total S\$:		4,445.00
		10.00% Discount S\$:		444.50
				4,000.50
1.	1	SPECIAL NETT ITEMS:		
		SEALANT		40.00 ✓
		Special Nett Total S\$:		40.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Accident report SHUT 18 11

LIM QUI PING, JOAN
BLK 627 JURONG WEST STREET 65 #08-384
SINGAPORE 640627

Attention : Motor Claim Department
Contact : 86680777

Estimate : ES003766

Date : 07/04/2021
Vehicle Num. : SKZ1599R
Make/Model : MITSUBISHI ATTRAGE
Chassis/Eng# : MMBSTA13AFH015911
Accident Date : 07/04/2021
Claim No. :
Reference : TP NTUC VS CHINA
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO TRANSFER BOOTLID PARTS
TO REMOVE/REFIX REAR WINDSCREEN GLASS
TO REMOVE & REFIT REAR PETROL-TANK
TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING
TO RUSTPROOF & WATER LEAKAGE TEST
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
TO CUT/OUT REWELD REAR FENDERS LH/RH, REAR END PANEL
REPAIR REAR CHASSIS, SPARE TYRE PANEL INCLUDES
KNOCKING & REPLACEMENT OF PARTS

Labour Total S\$:

Paul
Hp 9001068
10 days
08/04/21 @
1535

50.00	✓
120.00	✓
100.00	60
180.00	80
200.00	100
100.00	60
1,500.00	1000
1,200.00	1000
3,450.00	

Resin after repair

SingDollars : Seven Thousand Four Hundred Ninety & Cents Fifty Only



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total S\$: 7,490.50

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862
Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Accident report SF0H21470001