

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUAUTO.COM.SG / CLAIMS@PREMIUAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0291/2021/HR
DATE : 7-Apr-21
WIP : 22397

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

7 days exclude 1 Sunday

15 Jun 21 - Johnny Boo

OWNER'S NAME : MR. GOH SIN KOK
ADDRESS : 141 LOR 2 TOA PAYOH
#13-154
SINGAPORE 311141
TELEPHONE : HP +65 96329919
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800108579-02
VEHICLE NO : **SKC 9071 P**
MODEL CODE : SQ5 3.0 TFSI
MODEL YEAR : 17/8/2018
ENGINE NO : CWG 080523
CHASSIS NO : WAUZZZF2J2197092
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Apr-21
PLACE OF ACCIDENT : NEAR JALAN BUKIT MERAH

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 9071 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$	800.00	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	3,200.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS.	\$	4,800.00	\$ 2,050.00
5	Added labour - see attached	\$	3,800.00	\$ 2,900.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	13,272.00	\$ 6,122.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 3,364.00	\$	2,691.60
2	FRONT BUMPER FIXING PARTS	1	\$ 293.00		
3	FRONT BUMPER ULTRA SOUND SENSOR - LH / RH	2	\$ 180.00		
4	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 76.00		
5	FRONT BUMPER CLOSING ELEMENT - LH / RH	2	\$ 226.00		
6	FRONT BUMPER GRILLE - CENTER	1	\$ 173.00		
7	FRONT BUMPER SPOILER	1	\$ 807.00		
8	FRONT BUMPER GUARD TRIM	1	\$ 1,111.00		
9	FRONT BUMPER CLOSING ELEMENT	1	\$ 274.00		
10	FRONT BUMPER TRIM - LH / RH	2	\$ 82.00		
11	FRONT RADIATOR GRILLE	1	\$ 3,530.00	\$	2,824.00
12	FRONT RADIATOR STRIKER PLATE	1	\$ 244.00	\$	194.80
13	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 1,416.00	\$	566.40
14	FRONT BUMPER CARRIER	1	\$ 981.00		
15	FRONT BUMPER FOAM FILLER PIECE	1	\$ 177.00	\$	141.60
16	FRONT BUMPER BRACKET - LH / RH	2	\$ 512.00		
17	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 78.00		
18	FRONT BUMPER COVER	1	\$ 129.00		
19	"CAUTION" STICKER	1	\$ 14.00		
20	AIR CONDITIONER STICKER	1	\$ 20.00		
SUB TOTAL SPARE PARTS		:	\$ 13,687.00	\$	6,418.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY		S/NETT	REMARKS
		<i>c/f</i>		<i>\$</i>	<i>6,418.40</i>
21	WARNING SIGN	1	\$	30.00	
22	FRONT INNER PARKING AID SENSOR	2		TBC	
23	FRONT OUTER PARKING AID SENSOR	2		TBC	
24	FRONT PARKING AID SENSOR SEAL RING	4	\$	14.00	
25	FRONT HORN FANFARE - LOW / HIGH TONE - LH / RH	2	\$	390.00	
26	FRONT FENDER - LH / RH	2	\$	2,854.00	
27	FRONT FENDER BRACE - LH / RH	2	\$	450.00	
28	FRONT WHEEL HOUSING LINER - LH / RH	2	\$	542.00	
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$	38.00	
30	FRONT WHEEL SPOILER	2	\$	324.00	
31	FRONT WHEEL ARCH COVER	2	\$	1,330.00	<i>\$ 1,063.20</i>
32	"V6T" EMBLEM	2	\$	212.00	<i>\$ 169.60</i>
33	HEADLIGHT MOUNTING - LH / RH	2	\$	236.00	<i>\$ 188.80</i>
34	HEADLIGHT - LH / RH	2	\$	23,126.00	
35	HEADLIGHT LIFT CYLINDER - LH / RH	2	\$	280.00	
36	HEADLIGHT HOSE	1	\$	125.00	
37	FRONT RADIATOR UPPER AIR GUIDE	1	\$	48.00	
38	FRONT RADIATOR LOWER AIR GUIDE	1	\$	44.00	
39	FRONT RADIATOR LONG AIR GUIDE	2	\$	106.00	
40	FRONT RADIATOR SHORT AIR GUIDE	2	\$	118.00	
SUB TOTAL SPARE PARTS		:	\$	30,267.00	<i>\$ 7,840.00</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	<i>7,840.00</i>
41	FRONT NUMBER PLATE	S/N	\$ 60.00	\$	<i>60.00</i>
42	ADDED PARTS - SEE ATTACHED		\$ 1,375.00	\$	<i>1,099.52</i>
43	SUNDRIES		\$ 250.00		
TOTAL SPARE PARTS		:	\$ 45,639.00	\$	<i>8,999.52</i>
TOTAL LABOUR CHARGES		:	\$ 13,272.00	\$	<i>6,122.00</i>
GRAND TOTAL		:	\$ 58,911.00	\$	<i>15,121.52</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-18/05/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0291/2021/HR 26-Apr-21 CHANG 1 of 1 SKC 9071 P AUDI SQ5 3.0 TFSI	
Quantity	Description		Unit Price	Amount
Labours				
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS A/C SYSTEM.	S/N	\$ 1,400.00	\$ 1,400.00
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.		\$ 2,400.00	\$ 1,500.00
			\$ 3,800.00	\$ 2,900.00
Parts				
1	FRONT LOCK CARRIER		\$ 1,280.00	\$ 1,024.00
2	COOLANT		\$ 95.00	\$ 75.52
		Materials	\$ 1,375.00	\$ 1,099.52
		Labour	\$ 3,800.00	\$ 2,900.00
GRAND TOTAL			\$ 5,175.00	\$ 3,999.52

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT