

PREMIUM AUTOMOBILES



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0291/2021/HR

26-Apr-21

CHANG

1 of 1

SKC 9071 P

AUDI SQ5 3.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS A/C SYSTEM.	S/N \$ 1,400.00	✓ ✓
2	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.	\$ 2,400.00	1500 1250
Parts			
1	FRONT LOCK CARRIER <i>cracked</i>	\$ 1,280.00	✓ 1024
2	COOLANT <i>new</i>	\$ 95.00	✓ 75.52
GRAND TOTAL		\$ 5,175.00	

For Premium Automobiles Pte Ltd



Authorised Signature

+ 4 days.

Adrian Ling
27/04/21.
S.S.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 9071 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 3,200.00 ✓ 500	
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, <u>BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS.</u> ✓	\$ 4,800.00	3500 Bumper Acc - wheel Arch Trim x 2
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ <u>9,472.00</u>	Add 2 Fenders + 1100

H/S

Car-in

26/4/21

WIP-22397

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Kiam



Adrian

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>new</i>	1	\$ 3,364.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 293.00	+
3	FRONT BUMPER ULTRA SOUND SENSOR - LH / RH <i>new</i>	2	\$ 180.00	+
4	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 76.00	?
5	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2	\$ 226.00	+
6	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 173.00	+
7	FRONT BUMPER SPOILER <i>new</i>	1	\$ 807.00	+
8	FRONT BUMPER GUARD TRIM <i>new</i>	1	\$ 1,111.00	+
9	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 274.00	+
10	FRONT BUMPER TRIM - LH / RH <i>new</i>	2	\$ 82.00	+
11	FRONT RADIATOR GRILLE <i>new</i>	1	\$ 3,530.00	✓
12	FRONT RADIATOR STRIKER PLATE <i>new</i>	1	\$ 244.00	✓
13	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2	\$ 1,416.00	708.
14	FRONT BUMPER CARRIER	1	\$ 981.00	?
15	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	1	\$ 177.00	✓
16	FRONT BUMPER BRACKET - LH / RH	2	\$ 512.00	?
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2	\$ 78.00	+
18	FRONT BUMPER COVER <i>new</i>	1	\$ 129.00	+
19	"CAUTION" STICKER <i>new</i>	1	\$ 14.00	+
20	AIR CONDITIONER STICKER <i>new</i>	1	\$ 20.00	+
SUB TOTAL SPARE PARTS			\$ 13,687.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	WARNING SIGN <i>new</i>	1	\$ 30.00	+
22	FRONT INNER PARKING AID SENSOR	2	TBC	+
23	FRONT OUTER PARKING AID SENSOR	2	TBC	+
24	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 14.00	+
25	FRONT HORN FANFARE - LOW / HIGH TONE - LH / RH <i>new</i>	2	\$ 390.00	+
26	FRONT FENDER - LH / RH <i>new</i>	2	\$ 2,854.00	+
27	FRONT FENDER BRACE - LH / RH <i>new</i>	2	\$ 450.00	+
28	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 542.00	+
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 38.00	+
30	FRONT WHEEL SPOILER <i>new</i>	2	\$ 324.00	+
31	FRONT WHEEL ARCH COVER <i>new</i>	2	\$ 1,330.00	✓
32	V6T" EMBLEM <i>new</i>	2	\$ 212.00	✓
33	HEADLIGHT MOUNTING <i>new</i> LH RH	2	\$ 236.00	✓
34	HEADLIGHT - LH / RH	2	\$ 23,126.00	+
35	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 280.00	+
36	HEADLIGHT HOSE	1	\$ 125.00	+
37	FRONT RADIATOR UPPER AIR GUIDE	1	\$ 48.00	+
38	FRONT RADIATOR LOWER AIR GUIDE	1	\$ 44.00	+
39	FRONT RADIATOR LONG AIR GUIDE <i>new</i>	2	\$ 106.00	+
40	FRONT RADIATOR SHORT AIR GUIDE <i>new</i>	2	\$ 118.00	+
SUB TOTAL SPARE PARTS			\$ 30,267.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

Resurveyed.
27/04/21
Adrian King
H/S.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
41	FRONT NUMBER PLATE <i>Ind</i>	S/N	\$	60.00	✓
42	SUNDRIES		\$	250.00	?
TOTAL SPARE PARTS		:	\$	44,264.00	
TOTAL LABOUR CHARGES		:	\$	9,472.00	
GRAND TOTAL		:	\$	53,736.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.