

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0291/2021/HR
DATE : 7-Apr-21
WIP : 22397

Xiao Chen.
1512152.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. GOH SIN KOK
ADDRESS : 141 LOR 2 TOA PAYOH
#13-154
SINGAPORE 311141
TELEPHONE : HP +65 96329919
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800108579-02
VEHICLE NO : SKC 9071 P
MODEL CODE : SQ5 3.0 TFSI
MODEL YEAR : 17/8/2018
ENGINE NO : CWG 080523
CHASSIS NO : WAUZZZF2J2197092
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 6-Apr-21
PLACE OF ACCIDENT : NEAR JALAN BUKIT MERAH

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKC 9071 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING, ATD	S/N \$ 480.00 ✓	✓
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.	S/N \$ 800.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 3,200.00 500 ✓	
4	TO RESPRAY FRONT BUMPER, FRONT BUMPER LOWER SPOILER, BOTH FRONT FENDERS AND BOTH FRONT WHEEL ARCH TRIMS. ✓	\$ 4,800.00 550 2050	550: Bumper Arch = Wheel Arch Trim x 2
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>9,472.00</u>	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>2elnd</i>	1 S	3,364.00 ✓	2691.60	
2	FRONT BUMPER FIXING PARTS <i>new</i>	1 S	293.00 +		
3	FRONT BUMPER ULTRA SOUND SENSOR - LH / RH <i>new</i>	2 S	180.00 +		
4	FRONT BUMPER SECURING STRIP - LH / RH <i>Abel new</i>	2 S	76.00 ?	X	
5	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 S	226.00 +		
6	FRONT BUMPER GRILLE - CENTER <i>new</i>	1 S	173.00 +		
7	FRONT BUMPER SPOILER <i>new</i>	1 S	807.00 +		
8	FRONT BUMPER GUARD TRIM <i>new</i>	1 S	1,111.00 +		
9	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1 S	274.00 +		
10	FRONT BUMPER TRIM - LH / RH <i>new</i>	2 S	82.00 +		
11	FRONT RADIATOR GRILLE <i>crushed</i>	1 S	3,530.00 ✓	2824	
12	FRONT RADIATOR STRIKER PLATE <i>crushed</i>	1 S	244.00 ?	194.80 ✓	
13	FRONT BUMPER AIR GUIDE CRILLE - LH / RH <i>RH ut</i>	2 S	1,416.00 ?	566.40 ✓	
14	FRONT BUMPER CARRIER <i>Abel new</i>	1 S	981.00 ?	X	
15	FRONT BUMPER FOAM FILLER PIECE <i>crushed</i>	1 S	177.00 ?	141.60 ✓	
16	FRONT BUMPER BRACKET - LH / RH <i>Abel new</i>	2 S	512.00 ?	X	
17	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 S	78.00 +		
18	FRONT BUMPER COVER <i>new</i>	1 S	129.00 +		
19	"CAUTION" STICKER <i>3 new</i>	1 S	14.00 +		
20	AIR CONDITIONER STICKER <i>new</i>	1 S	20.00 +		
SUB TOTAL SPARE PARTS		:	\$ 13,687.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	WARNING SIGN <i>new</i>	1	\$ 30.00	+
22	FRONT INNER PARKING AID SENSOR <i>new</i>	2	TBC	+
23	FRONT OUTER PARKING AID SENSOR <i>new</i>	2	TBC	+
24	FRONT PARKING AID SENSOR SEAL RING <i>new</i>	4	\$ 14.00	+
25	FRONT HORN FANFARE - LOW / HIGH TONE - LH / RH <i>new</i>	2	\$ 390.00	+
26	FRONT FENDER - LH / RH <i>new</i>	2	\$ 2,854.00	+
27	FRONT FENDER BRACE - LH / RH <i>new</i>	2	\$ 450.00	+
28	FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>	2	\$ 542.00	+
29	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 38.00	+
30	FRONT WHEEL SPOILER <i>new</i>	2	\$ 324.00	+
31	FRONT WHEEL ARCH COVER <i>new</i>	2	\$ 1,330.00	✓ 1063.20
32	"V6T" EMBLEM <i>new</i>	2	\$ 212.00	✓ 169.60
33	HEADLIGHT MOUNTING - LH / RH <i>cracked.</i>	2	\$ 236.00	✓ 188.80
34	HEADLIGHT - LH / RH	2	\$ 23,126.00	+
35	HEADLIGHT LIFT CYLINDER - LH / RH <i>new</i>	2	\$ 280.00	+
36	HEADLIGHT HOSE	1	\$ 125.00	+
37	FRONT RADIATOR UPPER AIR GUIDE	1	\$ 48.00	+
38	FRONT RADIATOR LOWER AIR GUIDE	1	\$ 44.00	+
39	FRONT RADIATOR LONG AIR GUIDE <i>new</i>	2	\$ 106.00	+
40	FRONT RADIATOR SHORT AIR GUIDE <i>new</i>	2	\$ 118.00	+
SUB TOTAL SPARE PARTS		:	\$ 30,267.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKC 9071 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT NUMBER PLATE <i>Col</i>	S/N	\$ 60.00	✓
42	SUNDRIES <i>Nsl nec.</i>	\$	250.00	✗
TOTAL SPARE PARTS		:	\$ 44,264.00	
TOTAL LABOUR CHARGES		:	\$ 9,472.00	
GRAND TOTAL		:	\$ 53,736.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *07/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days. 07 Days. H.S.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT