



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KHOR SAW THENG			Ref: CC4/ASM21004471/Uba3q2 Date: 20/10/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XB 6988R		Veh. Inspected	SDT 5110E
Policy No.	GA554060		Coverage (\$)	0.00
Claim No.	S1M037ED		Excess (\$)	0.00
Assign From			Assign Date	08/04/2021
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 523i (A)		c.c	2497
Engine No.	HIDDEN		Year of Reg.	2010
Chassis No.	WBAFP32030C545335		Colour	BLACK
Odometer	242831 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		245/45 R18	PIRELLI	6 mm
L/H Front Tyre		245/45 R18	PIRELLI	6 mm
R/H Rear Tyre		245/45 R18	PIRELLI	6 mm
L/H Rear Tyre		245/45 R18	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	06/04/2021		Inspection Date	08/04/2021
Survey held at	Blk 15 Kaki Bukit Road 4, #01-53, S 417808			
Repairer	ZOOM AUTOWERKS PTE LTD			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	