



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

FIRST CAPITAL INS		NAME : Ms Lyn James		WIP : 45073			
		ADDRESS : 1 Elizabeth Drive #10-05 Singapore 669743		EXCESS :			
				DATE:			
ATTN. : MOTOR CLAIMS		TEL : 97306052					
FAX :							
VEH NO :	SLJ3600D	DATE IN :		CONTACT PERSON :	Ronald 63957875		
CHASSIS NO :	JM6BM4278G0339472	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM		
MODEL :	MAZDA 3	DATE REG.:	29-Apr-16	POLICY NO. :			
NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	FRONT BUMPER	MBHR3-50-031BBB	1				\$ 1,083.30
2	RETAINER RHS	MBHN1-50-0T1F	1				\$ 19.70
3	GROMMET, FRONT BUMPER	MGHP9-50-0Z5	2				\$ 5.80
4	CLIP, FRONT BUMPER	MC274-50-133	14				\$ 51.80
5	FASTENER, FRONT BUMPER	MB45A-56-146A	2				\$ 6.00
6	STIFF.'A', FRONT BUMPER	MB45A-50-0S0C	1				\$ 141.40
7	CHROME COVER RHS, FOGLAMP	MBJE1-50-C12	1				\$ 112.10
8	COVER RHS, FOGLAMP	MBJE1-50-C11A	1				\$ 48.80
9	HOLDER, LICENSE PLATE	MBHR1-50-170	1				\$ 54.30
10	FRONT REINFORCEMENT	MB45A-50-070A	1				\$ 466.80
11	CHROME LHS	MBHN1-50-7K1A	1				\$ 185.60
12	CHROME RHS	MBHN1-50-7J1A	1				\$ 185.60
13	FRONT GRILLE	MBJE1-50-712B	1				\$ 610.70
14	BRACKET LHS, FRONT GRILLE	MBHN1-50-163	1				\$ 15.90
15	BRACKET RHS, FRONT GRILLE	MBHN1-50-153	1				\$ 15.90
16	PIN LOCATOR, FRONT GRILLE	MKD45-50-1K5A	2				\$ 5.80
17	GROMMET, FRONT GRILLE	MKD45-50-ES1	2				\$ 5.80
18	RIVET, FRONT GRILLE	MEA01-50-037	2				\$ 16.00
19	MASCOT, FRONT	MC235-51-731A	1				\$ 46.50
20	GRILLE TOP	MBHN1-50-033 62	1				\$ 351.80
21	RIVET, GRILLE TOP	MS51S-51-833	6				\$ 24.00
22	RIVET, GRILLE TOP	MTK21-50-355	4				\$ 36.80
23	BRACKET TOP, GRILLE	MBHN1-50-717D	1				\$ 107.60
24	FASTENER, GRILLE	MGD7A-50-EA1	8				\$ 25.60
25	NOZZLE RHS,WASHER	MBHT4-51-8G1 62	1				\$ 89.40
26	ACTU CLEANER RHS, HEADLAMP	MBHT4-51-82X	1				\$ 254.60
27	CLAMP, ACTU CLEANER	MTK33-51-829	2				\$ 34.60
28	PIPE, NOZZLE	MBHT4-51-4J0	1				\$ 128.90
29	HEADLAMP RHS	MBHT6-51-031A	1				\$ 2,357.30
30	CLIP, HEADLAMP	MFB01-50-133C	2				\$ 8.00

31	RIVET, HEADLAMP	MB092-51-833	1				\$ 3.50
32	FOGLAMP RHS	MTK21-51-680A	1				\$ 369.00
33	BRACKET RHS, FOGLAMP	MBHR1-51-684A	1				\$ 18.20
34	LAMP RHS, SIDE TURN	MB45A-51-350A	1				\$ 165.20
35	PLATE SET, FRONT BUMPER	MBHN1-50-1C0B	1				\$ 166.40
36	FASTENER, PLATE SET	MGD7A-50-EA1	4				\$ 12.80
37	GRILLE UNDER, FRONT BUMPER	MBJD6-50-R10A	1				\$ 728.30
TOTAL PARTS							\$ 7,959.80
TOTAL PARTS COST							\$ 7,959.80

SUPPLEMENTARY							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

Labour Description						
1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR FRONT FENDER RH,BONNET AND ALL AREAS AFFECTED BY THE ACCIDENT.				\$ 3,300.00
2	MZ-SP-SFRT06	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, BONNET AND FRONT FENDER RH.				\$ 3,780.00
3	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.			NETT	\$ 70.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
16	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)				\$ 250.00
17	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 350.00
19	MZ-BR-SUNDRI	SUNDRIES.			NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 8,100.00
TOTAL PARTS	\$ -	\$ 7,959.80
TOTAL	\$ -	\$ 16,059.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1		#N/A		
2		#N/A		
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorized Signature