



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIMS		NAME: Ms Lyn James ADDRESS: 1 Elizabeth Drive #10-05 Singapore 669743 TEL: 97306052		WIP: 45073 EXCESS: DATE: 9-Jan-21	
FAX:		CONTACT PERSON: Ronald 63957875			
VEH NO:	SLI3600D	DATE IN:		TYPE OF CLAIM:	THIRD PARTY CLAIM
CHASSIS NO:	JM6BM4278G0339472	MILEAGE:		POLICY NO.:	
MODEL:	MAZDA 3	DATE REG.:	29-Apr-16		

NATURE OF WORKS							
Parts Description							
NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	FRONT BUMPER <i>de /</i>	MBHR3-50-031BBB	1				\$ 1,083.30
2	RETAINER RHS <i>X su</i>	MBHN1-50-0T1F	1				\$ 19.70
3	GROMMET, FRONT BUMPER <i>nee /</i>	MGHP9-50-0Z5	2				\$ 5.80
4	CLIP, FRONT BUMPER <i>nee /</i>	MC274-50-133	14				\$ 51.80
5	FASTENER, FRONT BUMPER <i>nee /</i>	MB45A-56-146A	2				\$ 6.00
6	STIFF.'A', FRONT BUMPER <i>X su</i>	MB45A-50-0S0C	1				\$ 141.40
7	CHROME COVER RHS, FOGLAMP <i>act X su</i>	MBJE1-50-C12	1				\$ 112.10
8	COVER RHS, FOGLAMP <i>X su</i>	MBJE1-50-C11A	1				\$ 48.80
9	HOLDER, LICENSE PLATE <i>X su</i>	MBHR1-50-170	1				\$ 54.30
10	FRONT REINFORCEMENT <i>? X su</i>	MB45A-50-070A	1				\$ 466.80
11	CHROME LHS <i>X su</i>	MBHN1-50-7K1A	1				\$ 185.60
12	CHROME RHS <i>act /</i>	MBHN1-50-7J1A	1				\$ 185.60
13	FRONT GRILLE <i>X su</i>	MBJE1-50-712B	1				\$ 610.70
14	BRACKET LHS, FRONT GRILLE <i>X su</i>	MBHN1-50-163	1				\$ 15.90
15	BRACKET RHS, FRONT GRILLE <i>? X su</i>	MBHN1-50-153	1				\$ 15.90
16	PIN LOCATOR, FRONT GRILLE <i>nee /</i>	MKD45-50-1K5A	2				\$ 5.80
17	GROMMET, FRONT GRILLE <i>nee /</i>	MKD45-50-ES1	2				\$ 5.80
18	RIVET, FRONT GRILLE <i>nee /</i>	MEAO1-50-037	2				\$ 16.00
19	MASCOT, FRONT <i>X m</i>	MC235-51-731A	1				\$ 46.50
20	GRILLE TOP <i>repair</i>	MBHN1-50-033 62	1				\$ 351.80
21	RIVET, GRILLE TOP <i>X m</i>	MS51S-51-833	6				\$ 24.00
22	RIVET, GRILLE TOP <i>X m</i>	MTK21-50-355	4				\$ 36.80
23	BRACKET TOP, GRILLE <i>X m</i>	MBHN1-50-717D	1				\$ 107.60
24	FASTENER, GRILLE <i>X m</i>	MGD7A-50-EA1	8				\$ 25.60
25	NOZZLE RHS, WASHER <i>mis /</i>	MBHT4-51-8G1 62	1				\$ 89.40
26	ACTU CLEANER RHS, HEADLAMP <i>mis /</i>	MBHT4-51-82X	1				\$ 254.60
27	CLAMP, ACTU CLEANER <i>nee /</i>	MTK33-51-829	2				\$ 34.60
28	PIPE, NOZZLE <i>? X su</i>	MBHT4-51-4J0	1				\$ 128.90
29	HEADLAMP RHS <i>X su</i>	MBHT6-51-031A	1				\$ 2,357.30
30	CLIP, HEADLAMP <i>X m</i>	MFB01-50-133C	2				\$ 8.00

31	RIVET, HEADLAMP <i>X nn</i>	MB092-51-833	1				\$ 3.50
32	FOGLAMP RHS <i>X svc</i>	MTK21-51-680A	1				\$ 369.00
33	BRACKET RHS, FOGLAMP <i>X nn</i>	MBHR1-51-684A	1				\$ 18.20
34	LAMP RHS, SIDE TURN <i>X svc</i>	MB45A-51-350A	1				\$ 165.20
35	PLATE SET, FRONT BUMPER <i>X nn</i>	MBHN1-50-1C0B	1				\$ 166.40
36	FASTENER, PLATE SET <i>X nn</i>	MGD7A-50-EA1	4				\$ 12.80
37	GRILLE UNDER, FRONT BUMPER <i>X svc</i>	MBJD6-50-R10A	1				\$ 728.30
TOTAL PARTS							\$ 7,959.80
TOTAL PARTS COST							\$ 7,959.80

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
TOTAL PARTS							\$ -
TOTAL PARTS COST							\$ -

Labour Description

1	MZ-BR-FRONT3	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT AND GRILLE TOP. REPAIR FRONT FENDER RH, BONNET AND ALL AREAS AFFECTED BY THE ACCIDENT.	660		\$ 3,300.00
2	MZ-SP-SFRT06	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, BONNET AND FRONT FENDER RH.	630		\$ 3,780.00
3	MZ-BR-PLATE1	TO SUPPLY NUMBER PLATE.	nn X	NETT	\$ 70.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150		\$ 250.00
16	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION. (INCLUDING NEW PARTS AND CAOUTCHOUC)	100 X nn		\$ 250.00
17	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180		\$ 350.00
19	MZ-BR-SUNDRI	SUNDRIES.	10	NETT	\$ 100.00

TOTAL LABOUR	\$ -	\$ 8,100.00
TOTAL PARTS	\$ -	\$ 7,959.80
TOTAL	\$ -	\$ 16,059.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	\$ -
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1		#N/A		
2		#N/A		
			TOTAL LABOUR	\$ - \$ -
			TOTAL PARTS	\$ - \$ -
			TOTAL	\$ - \$ -
			LESS EXCESS	\$ - \$ -
			TOTAL AFTER EXCESS	\$ -
			GST 7%	\$ - \$ -
			GRAND TOTAL	\$ - \$ -

TRANS EUROKARS PTE LTD

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Authorized Signature

Resu
Hp 90010068
3 days
15/04/21 @ 1610
Resu before paint

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: