



# 友尼摩多公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

Not Approved  
2800  
27/4/21  
2 days.

DATE: 29/04/2021 OUR REF: UAPL1458

REPAIR ESTIMATE THE ABOVE VEHICLE CHEVROLET CAPTIVA NO: SDX6777D

1 REAR BUMPER FACE	3 re 200 1105	\$ 1,451.00	X
1 REAR R/H BUMPER RETAINER	11	\$ 84.00	X
1 REAR BUMPER LOWER CENTRE GARNISH	ols cur	\$ 475.00	—
6 REAR BUMPER CLIPS	11	\$ 30.00	—
1 REAR R/H FENDER OUTER GARNISH	3 re 200 490	\$ 544.00	—
7 REAR R/H FENDER OUTER GARNISH CLIPS	11	\$ 35.00	X
1 REAR R/H DOOR OUTER GARNISH	3 re 200 425	\$ 512.00	—
7 REAR R/H DOOR OUTER GARNISH CLIPS	11	\$ 35.00	X
1 REAR R/H SPORT WHEEL	cur	\$ 1,142.00	600 s/w
		\$ 4,308.00	
	LESS 10%.....	\$ 430.80	
		\$ 3,877.20	

## LABOUR CHARGES:-

TO DISM/REWIRE REAR DAMAGED PORTION	\$ 80.00	20
TO PANEL BEAT DAMAGED PORTION AND RENEW PARTS	\$ 800.00	300
TO PUTTY AND RESPRAY DAMAGED PORTION	\$ 800.00	300
TO SEND VEHICLE FOR COMPUTER ALIGHTMENT	\$ 120.00	60
TO SPRAY UNDERCOATING IN REPAIR	\$ 11 80.00	X
TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING	\$ 11 120.00	X
	\$ 5,877.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2525  
102  
P-2272.50  
SA-600  
L-680  
3552.50  
202  
2842