

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/AIG21004483/KGS3Q2

Date:

06/07/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100464616

Claimant Vehicle No : SLD504A

Insured Vehicle No :

SJT8338A

Date of Loss: 04/04/2021

Nature of Claim:

TP

Claim No:

2528094434SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD504A**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)
 Reg. Date: 01/06/2016 (Man. Year: 2016)
 Colour: Metallic Blue
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZR406592
 Chassis No: JTDKD3B3101127856
 Odometer: 156534 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,230.42	4,729.67	1,500.75	24.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,835.00	2,300.00	535.00	18.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,065.42	7,029.67	2,035.75	22.46
Approved Total (Overridden) (S\$)		5,600.00		

(S\$)	9,065.42	5,600.00	3,465.42	38.23
+ GST 7.00/7.00% (S\$)	634.58	392.00	242.58	38.23
Nett Amount (S\$)	9,700.00	5,992.00	3,708.00	38.23
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
(S\$)		6,892.00		
Liabe Amount (80.00%) (S\$)		5,513.60		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,515.60		

INSPECTION

Date of Assignment: 08/04/2021

Date Inspected: 08/04/2021

Estimated Period of Repair: 7.0 days

Inspected At:

Alan's United Auto Pte Ltd (HQ)
 Blk 7 Sin Ming Industrial Estate, #01-76
 Singapore 575642

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER	Bent	708.90 FL	*682.00 FL
2	1		*FRONT N/S FENDER HYBRID EMBLEM	Necessary	43.80 FL	*43.80 FL
3	1		*FRONT N/S DOOR	Bent	1,079.80 FL	*1,079.80 FL
4	2		*FRONT N/S DOOR FRAME STICKER	Necessary	217.60 FL	*217.60 FL
5	2		*FRONT N/S DOOR HINGE	Repair	171.60 FL	*- FL
6	1		*FRONT N/S DOOR GLASS REGULATOR GEAR	Distorted	270.60 FL	*191.40 FL
7	1		*FRONT N/S DOOR GLASS REGULATOR MOTOR	Jammed	530.80 FL	*530.80 FL
8	1		*REAR N/S DOOR	Bent	806.70 FL	*806.70 FL
9	2		*REAR N/S DOOR FRAME STICKER	Necessary	148.80 FL	*148.80 FL
10	1		*REAR N/S FENDER	Repair	1,132.50 FL	*- FL
11	1		*N/S ROCKER PANEL	Repair	395.10 FL	*- FL
12	1		*FRONT N/S SHOCK ABSORBER	Bent	425.50 FL	*425.50 FL
13	1		*FRONT N/S KNUCKLE ARM	Bent	451.80 FL	*451.80 FL
14	1		*FRONT N/S KNUCKLE BEARING HUP	Bent	239.70 FL	*239.70 FL
15	1		*FRONT N/S LOWER ARM	Distorted	989.50 FL	*843.00 FL
16	1		*FRONT N/S LOWER BEARING	Necessary	161.20 FL	*112.00 FL
17	1		*FRONT N/S SPORT RIM	Dented	400.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,173.90	6,172.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,943.48	1,443.23
Total Parts (\$\$)	6,230.42	4,729.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE AND LOWER FRONT UNDERCARRIAGE	New	250.00	180.00
2	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	60.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	1,300.00	1,200.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,100.00	800.00
5	TO REMOVE ROOF LINING ,FRONT AND REAR SEATS ,TRIM BOARD AND CARPET	New	120.00	60.00
Gross Labour Cost (S\$)			2,835.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >