

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SIM CHENG HUAT
 310 HOUGANG AVE 5
 #08-259
 SINGAPORE 530310

Estimate No: MC1901873
 Date: 08 Apr 2021
 Policy No: P10066276R02
 Veh Reg No: SJF5815H
 Make/Model: TOYOTA WISH 1.8X LIMITED A

ATTN:

Your Ref No: SJF5815H
 Claim Type: Third Party → *AG*
 Accident Date: 01/04/2021
 TP Veh Reg No: SMS597R

*L111e
 3pm*

*Not with out
 Recovery After Painting
 1 day*

Estimate Repair Cost to Vehicle No :SJF5815H

Description	Quantity	List Price	Amount
		SS	SS
SPARE PARTS			
1 HEADLAMP LH	1 PC	<i>Sm</i> 1,211.00	X
2 HEADLAMP LOWER BEAM LH	1 PC	<i>Sm</i> 161.00	X
3 RADIATOR GRILLE	1 PC	<i>Sm</i> 148.40	X
4 RADIATOR GRILLE CLIP	2 PC	<i>un</i> 39.80	X
5 FRONT BUMPER	1 PC	<i>R</i> 601.90	X
6 FRONT BUMPER LOWER GRILLE	1 PC	<i>Sm</i> 165.40	X
7 FRONT BUMPER SIDE RETAINER LH	1 PC	<i>Sm</i> 62.80	X
8 FRONT BUMPER CLIPS	12 PC	<i>un</i> 50.40	X
9 FRONT BUMPER SPONGE	1 PC	<i>Sm</i> 128.20	X
10 FRONT BUMPER REINFORCEMENT	1 PC	<i>R</i> 336.30	X
11 FOGLAMP COVER LH	1 PC	<i>Sm</i> 49.60	X
		2,954.80	
	Less 25%	738.70	2,216.10
Special Nett			
12 NUMBER PLATE	1 PC	<i>Net</i> 35.00	✓
		35.00	35.00
LABOUR			
13 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	<i>100</i>
14 TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	<i>un</i> 30.00	X
15 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	<i>500</i>
16 TO SPRAY FRONT BUMPER	1 PC	250.00	<i>2000</i>
		620.00	620.00



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : SIM CHENG HUAT
310 HOUGANG AVE 5
#08-259
SINGAPORE 530310

Estimate No: MC1901873
Date: 08 Apr 2021
Policy No: P10066276R02
Veh Reg No: SJF5815H
Make/Model: TOYOTA WISH 1.8X LIMITED A

ATTN:

Your Ref No: SJF5815H
Claim Type: Third Party
Accident Date: 01/04/2021
TP Veh Reg No: SMS597R

Estimate Repair Cost to Vehicle No :SJF5815H

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
		Total	S\$ 2,871.10
		Add GST @ 7%	200.98
		Total Amount Payable	<u>S\$ 3,072.08</u>

TOTAL: SINGAPORE DOLLAR THREE THOUSAND SEVENTY TWO AND CENTS EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.
Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE