



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21004487/Dtf3n2 Date: 29/12/2021	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SJQ 1224G		<b>Veh. Inspected</b>	SHC 3373T
<b>Policy No.</b>			<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10009744		<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA		<b>Assign Date</b>	08/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	TOYOTA PRIUS		<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN		<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JTDKB3FUX03079920		<b>Colour</b>	BLUE
<b>Odometer</b>	257550 KM		<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER		<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>L/H Front Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>R/H Rear Tyre</b>	195/65 R15	WEST LAKE	5 mm
	<b>L/H Rear Tyre</b>	195/65 R15	WEST LAKE	5 mm
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
	<b>Accident Date</b>	07/04/2021	<b>Inspection Date</b>	08/04/2021
	<b>Survey held at</b>	BLK 9 SECTOR C #01-42, SIN MING INDUSTRIAL ESTATE		
	<b>Repairer</b>	BIFROST AUTO PTE LTD		
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>6 Working Days</b>	