



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							7200.00
RENEW FRT FENDER, FRT DOOR LH, REAR DOOR LH, A-PILLAR LH, ROOF PANEL							4680
ROCKER PANEL LH, SIDE SILL LH, SIDE AIRDAM LH, CENTER PILLAR LH,				11 1/2	80		
INNER PANEL A-PILLAR LH, REPAIR REAR FENDER LH, BONNET,							300.00
E PNT88000							3500.00
REMOVE & INSTALL ROOF GLASS							
E PNT98000							3150
SPRAY PAINT FOR BONNET, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH,							
A-PILLAR LH, SIDE AIRDAM LH, SIDE SILL LH, CENTRE PILLAR LH, ROOF PANEL				9			
REAR FENDER LH,							120
E PNT88000							180.00
REMOVE & INSTALL FRT DOOR TRIMS, GLASS, LOCK, SPEAKER, WIRING AND							
OTHER RELATED MECHANISMS							120
E PNT88000							180.00
REMOVE & INSTALL REAR DOOR TRIMS, GLASS, LOCK, SPEAKER, WIRING AND							
OTHER RELATED MECHANISMS							240.00
E PNT88000							240.00
RENEW FRT WINDSCREEN							
E PNT88000							240.00
REMOVE & INSTALL REAR WINDSCREEN							160.00
M SUNDRY							160.00
APPLY SEALANT FOR FRT & REAR WINDSCREEN				80 + 80			
M SUNDRY							220.00
APPLY SOLAR FILM FOR FRT WINDSCREEN							150
M SUNDRY							180.00
APPLY SOLAR FILM FOR FRT DOOR GLASS SOLAR FILM							
B WHEEL ALIGNMENT							120.00
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							30
TRANSFER FRT LEFT RIM & REAR RIGHT RIM							60.00
A 90000001							400.00
RENEW SIDE AIRBAG AND SEAT AIRBAG							
A 90000001							200
							400.00

8/4/21, 3:00pm

Steve CLKK

00-AL AL

EXCERS - ?

P/P

\$370

Confirm & accepted by

Authorized signatory and company stamp

8/4/21, 3:00pm \$370
 Steve CLKK)
 00-AL AL
 EXCER -?
 PIP
 24 days

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, by card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage. The rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
RENEW FRT BOTH SEAT BELTS AND IMPACT SENSORS				400.00
A 90000001				80.00
REMOVE & INSTALL ROOFLINING				400.00
E PNT88000				800.00
TO CLEAN AND VACUUM SHATTERED GLASS				400.00
E PNT88000				400.00
REMOVE & INSTALL ALL THE SEATS AND CARPET TO FACILITATE REPAIR				30.00
A 90000001				120.00
RENEW DASHBOARD AND COWL CROSS BAR				500.00
A 90000001				120.00
RENEW FRT UNDER CARRIAGE				400.00
E PNT88000				80
REMOVE & INSTALL ALL THE PILLAR TRIMS TO FACILITATE REPAIR				?
A 90000001				820
CHECK WIRING & ELECTRICAL SYSTEM				
A 10028901				
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				
USING HI-SCAN PRO TEST				
E PNT88000				
TO CONDUCT FLOOR BENCH TO PULL THE BODY ALIGNMENT				
M SUNDRY				
APPLY SEALANT FOR ACCIDENT PORTION				
A 90000001				
RENEW FLOOR WIRING ASSY				
M SUNDRY				
Sundry				
M SUNDRY				
PANEL ASSY- PILLAR OUTER LH -- 71110M6A10	1.00	✓	430.00	00.00
M PANEL-FENDER, LH	1.00	✓	27.00	00.00
M INSULATOR-FENDER LH	1.00	✓	1277.00	00.00
M PANEL ASSY-FRONT DOOR, LH	1.00	✓	30.00	00.00
M HINGE ASSY-FRONT DOOR, LH	1.00	✓	27.00	00.00
M HINGE ASSY-DOOR LOWER, LH				

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Payment for this may be made in cash or by cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage. The rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax. 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / Cocolu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M LABEL-TIRE PRESSURE	✓ APC				1.00	7.00	00.00	7.00
M PANEL ASSY-REAR DOOR, LH	✓ DO				1.00	1377.00	00.00	1377.00
M HINGE ASSY-REAR DOOR UPPER, LH	✓ ? BT				1.00	33.00	00.00	33.00
M HINGE ASSY-DOOR UPPER, LH	✓ ? X AN				1.00	26.00	00.00	26.00
M PILLAR ASSY-CENTER INNER, LH	✓ ? DO				1.00	257.00	00.00	257.00
M PANEL ASSY-SIDE SILL INNER, LH	✓ DO				1.00	172.00	00.00	172.00
M PANEL COMPLETE-DASH	✓ CRU				1.00	1156.00	00.00	1156.00
M PANEL-ROOF	✓ DO				1.00	843.00	00.00	843.00
M RAIL ASSY-ROOF FR	✓ ? X AN				1.00	112.00	00.00	112.00
M RING ASSY-SUNROOF REINF	✓ DO				1.00	406.00	00.00	406.00
M GUARD ASSY-FRONT WHEEL, LH	✓ CRU				1.00	95.00	00.00	95.00
M GLASS-WINDSHIELD	✓ OR				1.00	821.00	00.00	821.00
M MOULDING-WINDSHIELD GLASS	✓ APC				1.00	56.00	00.00	56.00
M BAR ASSY-COWL CROSS	✓ BT (center bar)				1.00	750.00	00.00	750.00
M CRASH PAD ASSY-MAIN	✓ CRU				1.00	1279.00	00.00	1279.00
M COVER ASSY-C/PAD SIDE LH	✓ OR				1.00	34.00	00.00	34.00
M HUB ASSY-FR WHEEL	✓ ? X AN				1.00	436.00	00.00	436.00
M GEAR ASSY-STEERING	✓ BT				1.00	770.00	00.00	770.00
M WHEEL ASSY-ALUMINIUM	✓ (FR LH) - CNT				1.00	926.00	00.00	926.00
M TORSION AXLE COMPLETE	✓ ? X AN				1.00	1031.00	00.00	1031.00
M PAD-FRONT DOOR SIDE IMPACT, LH	✓ APC				1.00	13.00	00.00	13.00
M HANDLE ASSY-DOOR INSIDE, LH	✓ CNT				1.00	71.00	00.00	71.00
M PANEL ASSY-FRONT DOOR TRIM, LH	✓ CRU				1.00	699.00	00.00	699.00
M SWITCH ASSY-P/WDO MAIN	✓ ? X AN				1.00	295.00	00.00	295.00
M SWITCH-POWER WINDOW	✓ ? X AN				1.00	250.00	00.00	250.00
M SWITCH ASSY-IMS CONTROL	✓ ? CNT				1.00	82.00	00.00	82.00
M TRIM ASSY-FR PILLAR LH	✓ ? X AN				1.00	52.00	00.00	52.00
M TRIM ASSY-COWL SIDE LH	✓ ? OR				1.00	23.00	00.00	23.00
M-TRIM-FR STEP PLATE, LH	✓ CNT				1.00	18.00	00.00	18.00
M-TRIM ASSY-FR DR SCUFF LH	✓ ? CNT				1.00	19.00	00.00	19.00
M TRIM ASSY-CTR PILLAR LWR LH	✓ ? X AN				1.00	52.00	00.00	52.00
M TRIM ASSY-RR DR SCUFF LH	✓ ? X AN				1.00	19.00	00.00	19.00
M TRIM-RR STEP PLATE LH	✓ ? AN				1.00	12.00	00.00	12.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage. Please be informed that the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	TRIM ASSY-CTR PILLAR UPR LH	X nn			1.00	39.00	00.00	39.00
M	CLIP-TRIM MTG STEEL	nc			10.00	✓ 1.00	00.00	10.00
M	CLIP-TRIM MTG	nc			6.00	✓ 1.00	00.00	6.00
M	CLIP-TRIM MTG	nc			4.00	✓ 1.00	00.00	4.00
M	RUN ASSY-FR DR WDO GLASS LH	CHT			1.00	✓ 126.00	00.00	126.00
M	GLASS ASSY-FRONT DOOR, LH	OR			1.00	✓ 207.00	00.00	207.00
M	CHANNEL ASSY-FRONT DOOR LOWER,	CHT			1.00	✓ 15.00	00.00	15.00
M	PANEL ASSY-FRONT DR MODULE, LH	OR (pylote)			1.00	✓ 241.00	00.00	241.00
M	PLUG	?			1.00	5.00	00.00	5.00
M	MOTOR ASSY-FRONT POWER WDW, LH	?			1.00	165.00	00.00	165.00
M	TAG-BURGLAR ALARM	nc			1.00	✓ 3.00	00.00	3.00
M	HEADLINING ASSY	CRH			1.00	✓ 1584.00	00.00	1584.00
M	MOULDING ASSY-FRT DR FRAME, LH	OR			1.00	✓ 72.00	00.00	72.00
M	W/STRIP ASSY-FR DR BELT O/S LH	CHT			1.00	✓ 80.00	00.00	80.00
M	W/STRIP ASSY-FR DR SIDE LH	CHT			1.00	✓ 102.00	00.00	102.00
M	W/STRIP-FR DR BODY SIDE LH	CHT			1.00	✓ 125.00	00.00	125.00
M	W/STRIP-FR DR BELT I/S LH	CHT			1.00	✓ 43.00	00.00	43.00
M	HANDLE ASSY-DOOR OUTSIDE, LH	OR			1.00	✓ 164.00	00.00	164.00
M	COVER-FR DR O/S HDL LH	OR			1.00	✓ 14.00	00.00	14.00
M	PAD-FR DR O/S HDL HINGE, LH	nc			1.00	✓ 5.00	00.00	5.00
M	PAD-FR DR O/S HDL COVER, LH	nc			1.00	✓ 5.00	00.00	5.00
M	STRIKER ASSY-DR	X nn			1.00	14.00	00.00	14.00
M	BASE ASSY-FR DR O/S HANDLE LH	OR			1.00	✓ 52.00	00.00	52.00
M	LATCH ASSY-FRONT DOOR, LH	OT (lock)			1.00	✓ 400.00	00.00	400.00
M	CHECKER ASSY-FRONT DOOR, LH	OT			1.00	✓ 44.00	00.00	44.00
M	MOULDING ASSY-RR DR FRAME, LH	nc			1.00	✓ 50.00	00.00	50.00
M	MOULDING ASSY-RR DR FRAME, LH	X Reported			1.00	50.00	00.00	50.00
M	COVER ASSY-COWL TOP	?			1.00	247.00	00.00	247.00
M	COVER-AFTER SERVICE, LH	X nn			1.00	11.00	00.00	11.00
M	BLACK TAPE-FR DR RR, LH	nc			1.00	✓ 13.00	00.00	13.00
M	BLACK TAPE-RR DR FR, LH	nc			1.00	✓ 13.00	00.00	13.00
M	BLACK TAPE-RR DR FRAME RR OTR,	nc			1.00	✓ 8.00	00.00	8.00
M	MIRROR ASSY-OUTSIDE RR VIEW, LH	OR			1.00	✓ 559.00	00.00	559.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
ELDORA KOK YING ZHI	Cust No/Name LCV13863/Ms Kok Ying Zhi Eldora
BLK 423 CLEMENTI AVENUE 1	Reg No/Reg Date SMY195K / 09/02/202
#14-327	Date In/Mileage / 0
SINGAPORE 120423	Chassis No KNAF5416MM5100880
Contact No	Engine No G4FGLH711854
	Make/Model KIA/CERATO 1.6 A GT LINE H370
	Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV13863	CRDVCH	08/04/2021/ 13:06	BLC	442 / CocoLu	31674			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M COVER ASSY-FR DR QDRNT INR,LH	BR	1.00	✓	57.00	00.00	✓	57.00	
M SAB MODULE ASSY-FR,LH	X NN	1.00	✓	357.00	00.00	✓	357.00	
M BACK ASSY-FR SEAT,LH	BR	1.00	✓	1975.00	00.00	✓	1975.00	
M SHIELD COVER-FR SEAT OTR,LH	REC	1.00	✓	30.00	00.00	✓	30.00	
M S/BELT ASSY-FR RH	damaged	1.00	✓	317.00	00.00	✓	317.00	
M S/BELT ASSY-FR LH	damaged	1.00	✓	315.00	00.00	✓	315.00	
M ADJUSTER ASSY-HEIGHT	X NN	1.00	✓	37.00	00.00	✓	37.00	
M WIRING ASSY-FR DR(PASS)	BR	1.00	✓	403.00	00.00	✓	403.00	
M-SENSOR ASSY-PRESS SIDE IMPACT	REC	1.00	✓	89.00	00.00	✓	89.00	
M MODULE ASSY-AIR BAG CONTROL	REC	1.00	✓	1025.00	00.00	✓	1025.00	
M-SENSOR ASSY-A TYPE CRASH	REC	1.00	✓	54.00	00.00	✓	54.00	
M UNIT ASSY-IBU	X NN	1.00	✓	564.00	00.00	✓	564.00	
M CURTAIN AIR BAG MODULE,LH	BR	1.00	✓	1166.00	00.00	✓	1166.00	
M WIRING ASSY-FLOOR	X NN	1.00	✓	1574.00	00.00	✓	1574.00	
M GLASS & MOULDING ASSY-QUARTER	REC	1.00	✓	252.00	00.00	✓	252.00	
M-NOZZLE ASSY-DEFROSTER,LH	CUT	1.00	✓	12.00	00.00	✓	12.00	
M-DUCT ASSY-SIDE AIR VENT,LH	CUT	1.00	✓	128.00	00.00	✓	128.00	
M-GARNISH-C/PAD,LH	CUT	1.00	✓	117.00	00.00	✓	117.00	
M CONNECTOR ASSY-HEATER TO AIR V	X NN	1.00	✓	232.00	00.00	✓	232.00	
M GLOVE BOX ASSY	X NN	1.00	✓	166.00	00.00	✓	166.00	
M PANEL ASSY-LOWER CRASH PAD	X NN	1.00	✓	153.00	00.00	✓	153.00	
M HOSE ASSY-SIDE DEFROSTER,LH	X NN	1.00	✓	44.00	00.00	✓	44.00	
M SUNROOF ASSY	CRU	1.00	✓	3172.00	00.00	✓	3172.00	
M-MOULDING ASSY-SIDE SILL,LH	(body kit) - BR	1.00	✓	279.00	00.00	✓	279.00	
M WHEEL ASSY-ALUMINIUM	X Replaced	1.00	✓	926.00	00.00	✓	926.00	
M BRACKET, IU ADHESIVE	REC	1.00	✓	26.00	00.00	✓	26.00	
M ARM COMPLETE-FR LWR,LH	X NN	1.00	✓	286.00	00.00	✓	286.00	

Confirm & accepted by

7% GST on **Nett** 49,245.00
49245.00
3447.15
Total Payable 52,692.15

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you in advance. Payment for this may be made by deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made by credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage or renewal of the rubber seal or other repair requiring the removal of the windscreen.