



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21004490/Eqf3e2	
			Date: 04/05/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	PC 995Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D20000410LPUL	Excess (\$)	0.00	
Assign From	SHELLY LIM	Assign Date	08/04/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLVO B7R	c.c	7140	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	YV3R6R620HA186892	Colour	RED	
Odometer	241898 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	295/80 R22.5	LING LONG	4 mm	
L/H Front Tyre	295/80 R22.5	LING LONG	4 mm	
R/H Rear Tyre	295/80 R22.5 (D)	LING LONG	4 mm	
L/H Rear Tyre	295/80 R22.5 (D)	LING LONG	4 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	08/12/2020	Inspection Date	21/04/2021	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	