

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBJ2634G

MAKE & MODEL : NISSAN NV350 PANEL VAN 5DR 2.5 5AT

CHASSIS NO : JN1MC2E26Z0030822

DATE : 07 APR 2021

CLAIM TYPE : TP CLAIM

D.O.A : 02 APR 2021

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	TAIL LAMP RH		\$ 120.00	\$ X 120.00
2	1	REAR BUMPER		\$ 280.00	\$ R X 280.00
3	3	REAR BUMPER SIDE CLIP RH		\$ 5.00	\$ X 15.00
4	1	REAR FENDER RH		\$ 1,150.00	\$ 68 1,150.00
5	1	REAR FENDER MUDGUARD RH		\$ 75.00	\$ 68 75.00
6	1	RH SLIDE DOOR		\$ 750.00	\$ X 750.00
7	1	RH SLIDE DOOR ROLLER LOWER		\$ 65.00	\$ X 65.00
8	1	FUEL LID COVER		\$ 90.00	\$ X 90.00
9	1	RH REAR WHEEL HUB CAP		\$ 120.00	\$ 049 120.00
10	1	FRT DOOR RH		\$ 700.00	\$ X 700.00
				\$ 3,355.00	\$ 3,365.00

TOTAL PRICE	\$ 3,365.00
PLUS 10%	\$ 336.50
SUB TOTAL PRICE	\$ 3,701.50

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	REAR BUMPER CLIPS SET		\$ 50.00	\$ X 50.00
2	1	FRONT DOOR CO.REG. STICKER		\$ 30.00	\$ X 30.00
3	1	REAR TYRE		\$ 120.00	\$ X 120.00
				\$ 200.00	\$ 200.00

Labour Charges

1	To cut/weld rear fender, panel beat other panels, remove & replace damaged parts.	\$ 1,000.00	600
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 50.00	X
4	To Spray painting for RH SIDE Portions & affected areas.	\$ 1,000.00	500
5	To do wheel alignment.	\$ 150.00	80
6	To remove & transfer door components.	\$ 150.00	X
7	To do artwork company sticker.	\$ 750.00	300

TOTAL LABOUR	\$ 3,200.00
Total Cost of Repairs	\$ 7,101.50

(Total parts + Total S/Nett + Total Labour Cost)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpik 97495749
 WP 4/8/21 4:15pm
 2/s Resurvey after repair
 Tanpik 11/11/21 04 days