


### Yong Sing Estimate Repair

Section A - To be completed by Claims Advisor

Vehicle Registration Number : GBD3339J  
 Make / Model : NV350  
 Chassis No : JN1MC2E26Z0003024  
 Year of Manufacture : \_\_\_\_\_  
 Registration Date : \_\_\_\_\_  
 Type of Repair (TP/OD/WS) : OD  
 Date/Time of Accident : \_\_\_\_\_  
 Rental Vehicle : Yes / No  
 Remark :

Case Ref. : \_\_\_\_\_  
 No. \_\_\_\_\_

The damages on the vehicle are as indicated in the following diagram :



|                             | Yong Sing estimate breakdown cost | Adjusted by Surveyor, if applicable |
|-----------------------------|-----------------------------------|-------------------------------------|
| Total Labour Cost :         | \$ <u>3,500.00</u>                | \$ <u>-</u>                         |
| Total Spray Painting Cost : | \$ <u>2,100.00</u>                | \$ <u>-</u>                         |
| Total Spare Parts Cost :    | \$ <u>39,484.70</u>               | \$ <u>-</u>                         |
| Other Charges :             | \$ <u>880.00</u>                  | \$ <u>-</u>                         |
| <b>TOTAL</b> :              | \$ <u>45,964.70</u>               | \$ <u>-</u>                         |
|                             | Lump Sum Repair, if any :         | \$ <u>-</u>                         |
| No. of Repair Days :        | [ 20 ] days                       | [ ] days                            |

### Surveyor Remark:

**Part 1 - Labour & Panel Beating Related Works**

| Job Scope                                                                                 | Yong Sing Estimate | Surveyor Adjustment |
|-------------------------------------------------------------------------------------------|--------------------|---------------------|
| REMOVE AND REFIT DAMAGED ITEMS, PULL AND REALIGN VEHICLE FRAME. WELD AND REFIT NEW PARTS. | \$3,500.00         |                     |
|                                                                                           |                    |                     |
| <b>Total Labour Cost</b>                                                                  | \$3,500.00         | <b>\$0.00</b>       |

**Part 2 - Spray Painting Related Works**

| Job Scope                        | Yong Sing Estimate | Surveyor Adjustment |
|----------------------------------|--------------------|---------------------|
| SPRAY PAINT FRONT BUMPER         | \$300.00           |                     |
| SPRAY PAINT FRONT PANEL          | \$300.00           |                     |
| SPRAY PAINT RH CORNER PANEL.     | \$250.00           |                     |
| SPRAY PAINT RH DOOR              | \$300.00           |                     |
| SPRAY PAINT RH FLOOR BOARD       | \$300.00           |                     |
| SPRAY PAINT RH DOOR FRAME.       | \$300.00           |                     |
| SPRAY PAINT INTERIOR FIREWALL    | \$350.00           |                     |
|                                  |                    |                     |
|                                  |                    |                     |
| <b>Total Spray Painting Cost</b> | \$2,100.00         | <b>\$0.00</b>       |

**Part 3 - Other Costs - Accident Repair Related Expenses**

| Job Scope                         | Yong Sing Estimate | Surveyor Adjustment |
|-----------------------------------|--------------------|---------------------|
| REMOVE AND REFIT FRONT WINDSCREEN | \$120.00           |                     |
| PULL AND REALIGN FRONT CHASSIS.   | \$400.00           |                     |
| CONDUCT SYSTEM WIRING CHECK.      | \$120.00           |                     |
| CONDUCT LEAKAGE TEST.             | \$120.00           |                     |
| CONDUCT BRAKE BLEEDING TEST.      | \$120.00           |                     |
|                                   |                    |                     |
|                                   |                    |                     |
|                                   |                    |                     |
|                                   |                    |                     |
| <b>Total Other Costs</b>          | \$880.00           | <b>\$0.00</b>       |

**Part 4 - Spare Parts / Material Usage**

| Item | Part Name                                | Part No    | Qty | Cost Price (\$) | Mark up (10%) | Final Price (\$) | Repair @ Replace (/) (Yong Sing) | Repair @ Replace (/) (Surveyor) |
|------|------------------------------------------|------------|-----|-----------------|---------------|------------------|----------------------------------|---------------------------------|
| 1    | PANEL-FRONT,CENTER                       | F12023XAMA | 1   | \$748.00        | 10%           | \$ 822.80        | REPLACE (/)                      |                                 |
| 2    | FRONT EMBLEM                             |            | 1   | \$88.00         | 10%           | \$ 96.80         | REPLACE (/)                      |                                 |
| 3    | FRONT PANEL-INNER LOWER,RH               | 612103XA1D | 1   | \$286.00        | 10%           | \$ 314.60        | REPLACE (/)                      |                                 |
| 4    | FRONT PANEL-INNER LOWER,LH               | 612113XA0A | 1   | \$286.00        | 10%           | \$ 314.60        | REPLACE (/)                      |                                 |
| 5    | PANEL ASSY-FRONT CORNER,RH               | 612603XA0A | 1   | \$253.00        | 10%           | \$ 278.30        | REPLACE (/)                      |                                 |
| 6    | FRONT INNER CORNER PANEL-SIDE,RH         | 612203XA0A | 1   | \$93.50         | 10%           | \$ 102.85        | REPLACE (/)                      |                                 |
| 7    | PANEL ASSY-FRONT CORNER,LH               | 612613XA0A | 1   | \$297.00        | 10%           | \$ 326.70        | REPLACE (/)                      |                                 |
| 8    | FRONT INNER CORNER PANEL-SIDE,LH         | 612213XA0B | 1   | \$104.50        | 10%           | \$ 114.95        | REPLACE (/)                      |                                 |
| 9    | REINFORCE-FRONT PANEL                    | 612403XA0A | 1   | \$418.00        | 10%           | \$ 459.80        | REPLACE (/)                      |                                 |
| 10   | FASCIA-FRONT BUMPER                      | 620223XA0H | 1   | \$385.00        | 10%           | \$ 423.50        | REPLACE (/)                      |                                 |
| 11   | FRONT BUMPER REINFORCEMENT               | 620303XA0B | 1   | \$528.00        | 10%           | \$ 580.80        | REPLACE (/)                      |                                 |
| 12   | BRACKET-FRONT BUMPER SIDE,RH             | 622203XA0A | 1   | \$104.50        | 10%           | \$ 114.95        | REPLACE (/)                      |                                 |
| 13   | BRACKET-FRONT BUMPER SIDE,LH             | 622213XA0A | 1   | \$104.50        | 10%           | \$ 114.95        | REPLACE (/)                      |                                 |
| 14   | GRILLE ASSY-FRONT                        | 623103XA0C | 1   | \$324.50        | 10%           | \$ 356.95        | REPLACE (/)                      |                                 |
| 15   | COVER ASSY-COWL TOP                      | 668623XA0A | 1   | \$154.00        | 10%           | \$ 169.40        | REPLACE (/)                      |                                 |
| 16   | MOTOR ASSY-WINDSHIELD WIPER              | 288103XA0A | 1   | \$225.50        | 10%           | \$ 248.05        | REPLACE (/)                      |                                 |
| 17   | LINK ASSY-WIPER                          | 288403XA0A | 1   | \$335.50        | 10%           | \$ 369.05        | REPLACE (/)                      |                                 |
| 18   | ARM ASSY-WINDSHIELD WIPER LH             | 288813XA0A | 1   | \$88.00         | 10%           | \$ 96.80         | REPLACE (/)                      |                                 |
| 19   | ARM ASSY-WINDSHIELD WIPER RH             | 288813XA0A | 1   | \$88.00         | 10%           | \$ 96.80         | REPLACE (/)                      |                                 |
| 20   | FRONT RH STEP PANEL INNER PANEL          | G62403XAMA | 1   | \$286.00        | 10%           | \$ 314.60        | REPLACE (/)                      |                                 |
| 21   | FRONT LH STEP PANEL INNER PANEL          | G62413XAMA | 1   | \$286.00        | 10%           | \$ 314.60        | REPLACE (/)                      |                                 |
| 22   | FLOOR PANEL -FRONT                       | 743103XA2B | 1   | \$1,815.00      | 10%           | \$ 1,996.50      | REPLACE (/)                      |                                 |
| 23   | FRONT,INNER UPPER PILLAR- LH             | 762313XA0A | 1   | \$396.00        | 10%           | \$ 435.60        | REPLACE (/)                      |                                 |
| 24   | FRONT VERTICAL PILLAR,LOWER LH           | 762253XA0A | 1   | \$319.00        | 10%           | \$ 350.90        | REPLACE (/)                      |                                 |
| 25   | FRONT OUTER DOOR FRAME PANEL LH          | G74133XAMB | 1   | \$880.00        | 10%           | \$ 968.00        | REPLACE (/)                      |                                 |
| 26   | FRONT,INNER UPPER PILLAR- RH             | 762303XA0A | 1   | \$462.00        | 10%           | \$ 508.20        | REPLACE (/)                      |                                 |
| 27   | FRONT VERTICAL PILLAR,LOWER RH           | 762243XA0A | 1   | \$198.00        | 10%           | \$ 217.80        | REPLACE (/)                      |                                 |
| 28   | FRT PILLAR ASSY-CENTER,INNER LOWER RH    | G65403XAMB | 1   | \$286.00        | 10%           | \$ 314.60        | REPLACE (/)                      |                                 |
| 29   | FRT PILLAR-CENTER,INNER UPPER RH         | 765303XA0A | 1   | \$264.00        | 10%           | \$ 290.40        | REPLACE (/)                      |                                 |
| 30   | FRONT OUTER DOOR FRAME PANEL RH          | G74123XAMA | 1   | \$990.00        | 10%           | \$ 1,089.00      | REPLACE (/)                      |                                 |
| 31   | FRT PANEL-SIDE,OUTER CENTER SLIDING RH   | G74183XBMA | 1   | \$1,045.00      | 10%           | \$ 1,149.50      | REPLACE (/)                      |                                 |
| 32   | FRT RH INNER DOOR MOULDING               | 769213XA0A | 1   | \$115.50        | 10%           | \$ 127.05        | REPLACE (/)                      |                                 |
| 33   | GARNISH ASSY-FRONT PILLAR,RH             | 769113XA0A | 1   | \$115.50        | 10%           | \$ 127.05        | REPLACE (/)                      |                                 |
| 34   | PLATE-KICKING,FRONT RH                   | 769513XK1A | 1   | \$159.50        | 10%           | \$ 175.45        | REPLACE (/)                      |                                 |
| 35   | DOOR ASSY-FRONT,RH                       | H010M3XAMB | 1   | \$858.00        | 10%           | \$ 943.80        | REPLACE (/)                      |                                 |
| 36   | OUTER MOULDING STRIP ASSY-FRONT DOOR ,RH | 808203XA0A | 1   | \$126.50        | 10%           | \$ 139.15        | REPLACE (/)                      |                                 |
| 37   | HINGE ASSY-FRONT DOOR,UPPER RH           | 80401AX000 | 1   | \$71.50         | 10%           | \$ 78.65         | REPLACE (/)                      |                                 |
| 38   | HINGE ASSY-FRONT DOOR,LOWER RH           | 80420AX000 | 1   | \$71.50         | 10%           | \$ 78.65         | REPLACE (/)                      |                                 |
| 39   | WEATHERSTRIP-DOOR,LOWER FRONT RH         | 80836VW000 | 1   | \$60.50         | 10%           | \$ 66.55         | REPLACE (/)                      |                                 |
| 40   | SASH ASSY-FRONT DOOR,REAR RH             | 802163XA0B | 1   | \$60.50         | 10%           | \$ 66.55         | REPLACE (/)                      |                                 |
| 41   | SEAL ASSY-FRONT DOOR INSIDE RH           | 808343XA0A | 1   | \$71.50         | 10%           | \$ 78.65         | REPLACE (/)                      |                                 |
| 42   | WEATHERSTRIP-FRONT DOOR,RH               | 808303XA0C | 1   | \$104.50        | 10%           | \$ 114.95        | REPLACE (/)                      |                                 |
| 43   | GLASS RUN RUBBER-FRONT DOOR,RH           | 803303XA0A | 1   | \$104.50        | 10%           | \$ 114.95        | REPLACE (/)                      |                                 |
| 44   | GLASS ASSY-FRONT DOOR WINDOW,RH          | 803003XA0A | 1   | \$528.00        | 10%           | \$ 580.80        | REPLACE (/)                      |                                 |
| 45   | REGULATOR ASSY-DOOR WINDOW,RH            | 807203XA0A | 1   | \$176.00        | 10%           | \$ 193.60        | REPLACE (/)                      |                                 |
| 46   | MOTOR ASSY-REGULATOR,RH                  | 807301HH1B | 1   | \$385.00        | 10%           | \$ 423.50        | REPLACE (/)                      |                                 |
| 47   | HANDLE ASSY-FRONT DOOR OUTSIDE,RH        | 806063XA0B | 1   | \$176.00        | 10%           | \$ 193.60        | REPLACE (/)                      |                                 |
| 48   | ROD-KEY LOCK,RH                          | 805143XA0A | 1   | \$214.50        | 10%           | \$ 235.95        | REPLACE (/)                      |                                 |
| 49   | STRIKER ASSY-FRONT DOOR LOCK             | 80570AA20A | 1   | \$71.50         | 10%           | \$ 78.65         | REPLACE (/)                      |                                 |
| 50   | LOCK & REMOTE CONTROL ASSY-FRONT DOOR,RH | 805003XY1A | 1   | \$214.50        | 10%           | \$ 235.95        | REPLACE (/)                      |                                 |
| 51   | HANDLE ASSY-DOOR INSIDE,RH               | 806703XA0B | 1   | \$82.50         | 10%           | \$ 90.75         | REPLACE (/)                      |                                 |
| 52   | FINISHER ASSY-FRONT DOOR,RH              | 809003XA0A | 1   | \$291.50        | 10%           | \$ 320.65        | REPLACE (/)                      |                                 |

[illegible]