

Date: 06.04.2021
 Vehicle No: SMS3962A
 Model: PORSCHE MACAN 2.0 PDK
 Chassis: QR25291683L
 Reg. Year: 2016

Third Party Insurer: C. TAIPING
 Third Party Veh No: SCK8280L
 Date of Accident: 31.03.2021

*Not Notched
 Repair After Paint
 3 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR LH	1		2,700.00 X
2	FRONT DOOR PROTECTOR LH	1	NN	\$684.00 X
4	REAR DOOR LH	1		2,700.00 X
5	REAR DOOR PROTECTOR LH	1	NN	\$648.00 X
6	REAR FENDER LH	1		REPAIR
SUB TOTAL				\$6,732.00
LESS 10%				-\$673.20
PARTS TOTAL				\$6,058.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT DOOR PROTECTOR CLIPS LH	1	NN	\$95.00 X
2	REAR DOOR PROTECTOR CLIPS LH	1	NN	\$95.00 X
S/N TOTAL				\$190.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX & REPAIR AT ACCIDENT AREA. \$1,000.00 *800*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR FENDER LH, REAR DOOR LH & FRONT DOOR LH. \$1,200.00 *750*

LABOUR CHARGES TO DISMANTLE & RE-INSTALL FRONT DOOR MECHANISM / GLASS. *nn* \$200.00 X

LABOUR CHARGES TO DISMANTLE & RE-INSTALL REAR DOOR MECHANISM / GLASS. *nn* \$200.00 X

TO TUFF KOTE & UNDERSEAL MATERIALS. *nn* \$150.00 X

TO CHECK WIRING & ELECTRICAL SYSTEM & ETC. \$150.00 *20*

TO DAIGNOSIS FAULT CODE & RESET MEMORY. *nn* \$150.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

LABOUR TOTAL \$3,050.00

TOTAL \$9,298.80

Vic

Acknowledged by Repairer
 Signature:

Date:

Branch (Motor Insurance Claims)

Head office
 6 Rung Chang Road Singapore 152143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch
 9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9010 | Fax: (+65) 6481 1093

Branch 10 Ang Mo Kio Rd Park 2A #01-08 Singapore 608047
 Tel: (+65) 6461 1522 | Fax: (+65) 6461 1011

