



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GSTReg. No. 351915/00A

GST Regn No. 35191500A

08/04/2021

China Taiping Ins (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBF 9342 Z
MODEL: NISSAN CABSTAR
DATE OF ACCIDENT: 06/04/2021
YOUR INSURED VEHICLE NO. YP 8308 E

1 pc	Tailgate	\$	1,499.70	N
2 pcs	Taillamps @ \$265.30 N each		530.60	N
1 pc	Front windscreen		991.00	N
2 pcs	Front windscreen side mouldings @ \$95.30 N each		190.60	N
1 pc	Wiper panel		494.60	N
1 pc	CABSTAR logo		65.10	N
1 pc	Front grille		578.60	N
1 pc	Front grille logo		65.70	N
2 pcs	Headlamps @ \$473.40 N each		946.80	N
		\$	<u>5,362.70</u>	
	Less: 10% discount		536.27	
		\$	<u>4,826.43</u>	
1 pc	Rear bumper		400.00	SN
1 pc	Front windscreen inner seal		30.00	SN
1 roll	Front windscreen gum		40.00	SN
1 pc	ERP bracket		26.00	SN
1 pc	70 km/hr sticker		20.00	SN
1 pc	13 PAX sticker		20.00	SN

LABOUR CHARGES:

To writing of company logo (front & rear)	450.00
To dismantle and reassemble of front windscreen	120.00
To knocking of straightening of all necessary damaged parts.	
To changing of the above parts.	1,200.00
To putty and spray painting on accident damaged parts.	1,000.00
	\$ <u><u>8,132.43</u></u>

Yours faithfully,