



萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

GST Regn No. 35191500A

08/04/2021

China Taiping Ins (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Attn: Motor Claims Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBF 9342 Z
MODEL: NISSAN CABSTAR
DATE OF ACCIDENT: 06/04/2021
YOUR INSURED VEHICLE NO. YP 8308 E

1 pc	Tailgate	✓	00	
2 pcs	Taillamps @ \$265.30 N each	✓	OR	
1 pc	Front windscreen	✓	CRA	
2 pcs	Front windscreen side mouldings @ \$95.30 N each	✓	MC	
1 pc	Wiper panel	X	R	
1 pc	CABSTAR logo	✓	MC	
1 pc	Front grille	✓	OR	
1 pc	Front grille logo	✓	CRA	
2 pcs	Headlamps @ \$473.40 N each	✓	OR	
Less: 10% discount				

\$	1,499.70	
	530.60	
	991.00	
	190.60	130
	494.60	X
	65.10	
	578.60	461
	65.70	
	946.80	
\$	5,362.70	
	536.27	
\$	4,826.43	
300	400.00	SN
	30.00	SN
	40.00	SN
20	26.00	SN
	20.00	SN
	20.00	SN

1 pc	Rear bumper	✓	00	
1 pc	Front windscreen inner seal	✓	MC	
1 roll	Front windscreen gum	✓	MC	
1 pc	ERP bracket	✓	MC	
1 pc	70 km/hr sticker	✓	MC	
1 pc	13 PAX sticker	✓	MC	

LABOUR CHARGES:

To writing of company logo (front & rear)
To dismantle and reassemble of front windscreen
To knocking of straightening of all necessary damaged parts.
To changing of the above parts.
To putty and spray painting on accident damaged parts.

450.00	400
120.00	
1,200.00	600
1,000.00	600
8,132.43	

Yours faithfully,

Redindaga

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

L/S - 5096.72
= 5100