

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X**AAD2104-036***Not Authorized
11 Sep @ 2250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

08 APR 2021

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD317X

VF1ABL15AUC282370

RENAULT

LATITUDE

06/04/2021

LONPAC

04/03/2016

PART**LIST**

1 BUMPER COVER FRT	\$	<i>Per / m3cm</i>	747.20	✓
1 BUMPER ABSORBER FRT	\$	<i>SL</i>	394.68	X
1 BUMPER BEAM FRT	\$	<i>R</i>	663.70	X
1 BUMPER BRACKET KIT FRT RH	\$	<i>Dis</i>	101.40	✓
1 DOOR PANEL FRT RH	\$	<i>R</i>	2,844.66	X
1 DOOR HINGE UPPER FRT RH	\$	<i>R</i>	261.28	X
1 DOOR HINGE LOWER FRT RH	\$	<i>R</i>	300.55	X
1 DOOR REGULATOR FRT RH	\$	<i>SL</i>	505.19	X
1 DOOR REGULATOR MOTOR FRT RH	\$	<i>SL</i>	796.46	X
1 DOOR WEATHERSTRIP FRT RH	\$	<i>SL</i>	410.27	X
1 FENDER PANEL FRT RH	\$	<i>B</i>	437.10	✓
1 WHEELARCH FRT RH	\$	<i>Dis</i>	191.40	✓
1 HEADLAMP RH	\$	<i>SL</i>	743.60	X
1 BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i>	207.21	X
1 WIPER RESERVOIR	\$	<i>SL</i>	179.60	X
	\$		8,784.30	
	10% \$		878.43	
	\$		7,905.87	

Special Nett

1SET FENDER CLIP	\$	<i>nn</i>	65.00	✓ X
1SET FENDER LINER CLIP	\$	<i>nn</i>	60.00	✓
1 DOOR STICKER TRANSCAB	\$	<i>nn</i>	100.00	605AL
1 DOOR STICKER CLASSIC	\$	<i>nn</i>	100.00	155AL
1 BUMPER CLIP FRT	\$	<i>nn</i>	85.00	685AL
1 BUMPER RETAINER CLIP FRT	\$	<i>nn</i>	70.00	X
1SET BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00	X

Trans-cab Auto Services Pte Ltd**AAD2104-036**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X

1SET BUMPER BRACKET SIDE CLIP RH RR	\$	nn	10.00	}	X
1SET BUMPER RETAINER RH CLIP RR	\$	nn	20.00		
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00		
1SET BUMPER RETAINER CLIP LH RR	\$	nn	20.00		
1 BUMPER CLIP FRT	\$	nn	85.00		
1 BUMPER GRILLE LOWER CLIP	\$	nn	70.00		
TOTAL	\$		480.00		
TOTAL PARTS	\$		8,385.87		

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	6601
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	5001
To Rust-Proofing Of The Affected Areas.	\$		170.00	301
To reinstall rear bumper parking sensor.	\$	nn	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn	170.00	X
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD317X

AAD2104-036

To check steering geometry and computer wheel alignment

\$

220.00 60%

To Check Electrical Lighting Concerned.

\$

170.00 15%

TOTAL \$

7,880.00

Over All Total \$

24,171.74

(LUMP SUM)

Repair Days

20 DAYS

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: