

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST: 201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY #07-16

AIG BUILDING, SINGAPORE 079120

TEL: 64193000

FAX: 68357416

ATTN: Motor Claim Department

Claim Type: Third Party

Accident Date: 05/04/2021

TP Veh Reg No: SKC1170P

Estimate No: EST2100088

Date: 06 Apr 2021

Veh Reg No: SGP5470B

Make/Model: HONDA JAZZ 1.4A

Chasis No: JHMGD18507S201190

Reg. Date: 19/12/2006

Your Ref No: SKC1170P

Justin.

Estimate Repair Cost to Vehicle No :SGP5470B

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	List Price		
1	1 PC REAR BUMPER <i>Distorted</i>	561.20 ✓	
2	1 PC REAR BUMPER RETAINER LH <i>new</i>	38.40 ✓	
3	1 PC REAR AIR DUCT LH <i>could</i>	43.90 ✓	
4	1 PC REAR COWLING LH <i>to go</i>	168.10 ✓	
5	1 PC REAR PANEL <i>Distorted</i>	441.10 ✓	
6	1 PC REAR PANEL TRIM <i>could</i>	144.30 ✓	
7	1 PC BOOT LID RUBBER <i>new</i>	162.20 +	
8	1 PC TAIL LAMP LH <i>could</i>	332.80 ✓	
9	1 PC TAIL LAMP PANEL LH <i>Regis</i>	145.60 +	
10	1 PC REAR FENDER LH <i>Bushed.</i>	756.40 ✓	
11	1 PC REAR FENDER QUARTER GLASS LH <i>new in</i>	188.50 +	
12	1 PC REAR FENDER TRIM LH <i>could</i>	189.60 ✓	
		3,172.10	
	Less 20%	634.42	2,537.68
	Special Net		
13	1 SET REAR LH COWLING CLIPS <i>new</i>	30.00 <i>20</i>	
14	1 SET REVERSE SENSORS <i>Damaged</i>	250.00 <i>200</i>	
15	1 SET REAR BUMPER CLIPS <i>new</i>	40.00 <i>30</i>	
16	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00 <i>20</i>	
17	1 PC REAR FENDER QUARTER GLASS SEALANT <i>new</i>	60.00 <i>30</i>	
18	1 PC REAR FENDER QUARTER GLASS SEAL	60.00 <i>30</i>	
19	1 SET REAR LH FENDER TRIM CLIPS <i>new</i>	50.00 <i>30</i>	
		530.00	530.00
	Labour		
20	1 TO CHECK WIRING	50.00 <i>30</i>	
21	1 TO REMOVE AND REFIT SEAT CUSHION	250.00 <i>60</i>	
22	1 TO REMOVE AND REFIT PETROL TANK	150.00 <i>80</i>	
23	1 TO REMOVE AND REFIT REVERSE SENSOR	80.00 <i>50</i>	
24	1 TO REMOVE AND REFIT QUARTER GLASS	120.00 <i>40</i>	
25	1 TO SPRAY UNDERSEAL	180.00 <i>60</i>	

2675.80

2140.64

360

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 05/04/2021
TP Veh Reg No: SKC1170P

Estimate No: EST2100088
Date: 06 Apr 2021
Veh Reg No: SGP5470B
Make/Model: HONDA JAZZ 1.4A
Chasis No: JHMGD18507S201190
Reg. Date: 19/12/2006
Your Ref No: SKC1170P

Estimate Repair Cost to Vehicle No :SGP5470B

Quantity	Description	List Price	Amount
		SS	SS
26	1 (REAR) TO SPRAY PAINTING	1,200.00 600	
27	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 1000	
	1920	3,530.00	3,530.00
	Total		S\$ 6,597.68
	Add GST @ 7%		461.84
	Total Amount Payable		S\$ 7,059.52

TOTAL: SINGAPORE DOLLAR SEVEN THOUSAND FIFTY NINE AND CENTS FIFTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
h/s 07/04/21

07 Days.

total: 4420.64

h/s: 3.5K ✓