

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Auto & General Insurance (S) Pte Ltd

Accident Date : 05.04.2021

Not Authorized
L/Ping @ 5650/h
Penny After Point
4 days

Policy No: Third Party

Date: 08.04.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Honda Shuttle" Reg. No. SLK8337B Claiming Against Your Insured Veh. No. SFU8028L			
1pc	Front Bumper 1020-20	1,152.00	✓
12pcs	Front Bumper Clips	5.50	66.00 ✓
2pcs	Front Bumper Brackets	38.40	76.80 ✓
2pcs	Front Bumper Top Retainers	15.40	30.80 2+
1pc	Front Bumper Reinforcement		297.50 ✓
1pc	Front Bumper Tow Cover		25.60 ✓
1pc	Front Bumper Center Air Grille		95.20 ✓
1pc	Front Bumper Fog Lamp		347.00 X
1pc	Front Bumper Fog Lamp Cover		45.20 X
1pc	Front Bumper Fog Lamp Top Cover		35.20 ✓
2pcs	Front Bumper Corner Retainers	21.00	42.00 4+
1pc	Grille Emblem		28.90 ✓
1pc	Grille Emblem Base Reflective Sticker		110.00 305N
1pc	Grille Badge "Mugen"		165.00 355N
1pc	Grille Sticker "Mugen"		120.00 305N
1pc	Grille Garnish (Mugen Black)		450.00 320N
2pcs	Grille Center Brace Brackets	65.00	130.00 4+
2pcs	Grille Side Top Retainers	95.00	190.00 2+
2pcs	Headlamps (LED) 2250-40	2,250.40	4,500.80 4+
2pcs	Headlamps Film	150.00	300.00 205N
1pc	Condensor 981.00		985.20 ✓
1pc	Radiator		1,350.20 X
	Less 20%		8,208.00
			1,641.60
			6,566.40
	Front Number Plate (Chrome) Chrome type		120.00 SN 305N
	Front Bumper Day Light		350.00 SN X
	Front Bumper Lower Lip (Carbon) P.T.		250.00 SN X
	Grille "Mugen"		850.00 SN 2
	To Conduct Electrical Check, Focus Headlamp		30.00 200
	To Remove / Refit, Radiator System, Bleed, Refill Coolant.		120.00 X
	To Remove / Refit Air Con Condenser & Refill Air Con Gas		140.00 1000
		C/F	8,426.40

源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: Auto & General Insurance (S) Pte Ltd

Policy No: Third Party

Date: 08.04.2021

Accident Date : 05.04.2021

Used in Car Painting, Welding,
Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

量 ity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Shuttle" Reg. No. SLK8337B Claiming Against Your Insured Veh. No. SFU8028L		
		B/F	8,426.40
	To Provide Transportation (Towing)		60.00
	Labour Charge - Panel Beating, Repairing Of Support Panel, Bonnet and Parts Replacement		600.00
	To Respray Affected Areas		700.00
	To Reseal Paint Protection (Diamondbrite) to Spray Paint Areas		350.00
		Total :	10,136.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to resurvey
- Third party survey is subject to final decision
- No illegal modification
- Supplementary repair is subject to final decision

Acknowledged by Repairer:

Signature:

Date:

趙 源 摩 哆
Chew Goon Motor

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)
Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint
Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀ 修理各种汽车敲焊打吗咭喷漆等 ▶

Auto & General Insurance (S) Pte Ltd

Accident Date : 05.04.2021

12.04.2021

Estimate Cost of Repair to "Honda Shuttle" Reg. No. SLK8337B
Claiming Against Your Insured Veh. No. SFU8028L

Supplementary

Front Bumper Electromagnetic Distance Sensor

Mu 450.00 SN 20052

Grand Total :

450.00