



Section A - Accident Details

Registration Number	SHB5487R
Case Reference Number	TAX/04/21/2017
Registration Date	30/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG KEE THIN
Type of Accident	Head to Rear
Accident Date and Time	7/4/2021 11:57 AM
Accident Reported Date and Time	7/4/2021 3:44 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110400
Special Instruction to ARC, if any	tp
Prepared Date and Time	8/4/2021 10:19 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$200.00
Total Spray Cost	\$1,476.00	\$200.00
Total Spare Part Cost	\$5,568.19	\$779.59
Total Other Cost	\$600.00	\$50.00
TOTAL COST	\$8,320.19	\$1,229.59
Lump Sum Total	\$8,300.00	\$1,250.00 (L/S)
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / III
ARC / Surveyor Sign Off Date	13/04/2021 11:39 AM	13/04/2021 11:06 AM
Signature		
Remarks	Total number of repair days = 3 days. SUP = + 1 day.	L/S, after paint photo.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0364	Invoice Number	
Quotation Date	22.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$676.00	\$200.00 /
Total Labour	\$676.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER LH	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,476.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$600.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		5215947913	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace	CR4
		5202347030	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Check	X SUC
		5246247030	PAD, RR BUMPER, RH & LH, 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/ Nec
		5246247020	PAD, RR BUMPER, RH & LH, 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/ Nec
		5246247010	PAD, RR BUMPER, RH & LH, 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace	/ Nec
		5246147010	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace	/ Nec
		5219147030	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Check	X SUC
		5257547040	RETAINER, RR BUMPER, RH	1.00	\$112.70	25.00	\$84.53	Replace	Replace	/ BR
		5257647040	RETAINER, RR BUMPER, LH	0.00	\$111.50	0.00	\$0.00	Replace	Not Given	X SUC
		5259147050	SEAL, RR BUMPER, RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X SUC
		5259247040	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X SUC
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	/ Nec

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 22/04/2021

User ID PohSuan

	52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$558.30	0.00	\$0.00	Replace	Check	X
	52565479 00	FILLER, RR BUMPER , RH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
	52566479 00	FILLER, RR BUMPER , LH	0.00	\$119.90	0.00	\$0.00	Replace	Not Given	X
	52169470 20	COVER, GUARD RR BUMPER LOWER	0.00	\$14.80	0.00	\$0.00	Replace	Not Given	X
		PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
	89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$60.30	0.00	\$0.00	Replace	Not Given	X
	81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Check	X
	81561471 51	LENS & BODY, REAR COMBINATION LAMP , LH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
	81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Check	X
	81591470 10	LENS & BODY ASSY , RR BUMPER , LH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
	81497470 20	COVER, REAR COMBINATION LAMP, RH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
	81498470 20	COVER, REAR COMBINATION LAMP, LH	0.00	\$54.00	0.00	\$0.00	Replace	Not Given	X
	58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
	58399470 30	COVER, REAR FLOOR UNDER , LH	0.00	\$234.30	0.00	\$0.00	Replace	Not Given	X
	66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given	X
	61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
	42611474 50	WHEEL, DISC	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
	43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X
		TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
	42602471 80	CAP SUB-ASSY, WHEEL	0.00	\$175.80	0.00	\$0.00	Replace	Not Given	X
Total				\$8,097.44		\$555.76			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
Total					558.30		418.73		

974.49 /

- 20%

779.59 /

+ 200.00 /

+ 250.00 /

1229.59 /

LIS \$1250 /
3 days

SHB 5487R