

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21004521/GQF3E2

Date: 30/05/2022

REFERENCE

Insured/Claimant: WING SOON FOOD
MANUFACTURER PTE LTD

Policy No: DMCVSNA00120712001

Date of Loss: 04/04/2021

Nature of
Claim: OD

Claim
No: SNM21D201963/C01/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBJ1106X**

Make & Model: NISSAN NV200, 1.6 DX (A)

Engine No: HR16137185D

Reg. Date: 27/12/2018 (Man. Year: 2018)

Chassis No: VM20130163

Colour: Silver

Odometer: 0 km

Engine Capacity: 1597 cc

Market Value/New Car Price: S\$54,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 165/80 R14

Rear Tyre Size: 165/80 R14

Front Left Side: Toyo 6 mm

Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,835.00	16,760.00	-14,925.00	-813.35
Miscellaneous Items	0.00	690.00	-690.00	
Labour	0.00	3,114.57	-3,114.57	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,835.00	20,564.57	-18,729.57	-1,020.69
- Excess (S\$)	450.00	450.00	0.00	0.00
(S\$)	1,385.00	20,114.57	-18,729.57	-1,352.32
+ GST 7.00/7.00% (S\$)	128.45	1,408.02	-1,279.57	-996.16
Nett Amount (S\$)	1,513.45	21,522.59	-20,009.14	-1,322.09

INSPECTION

Date of Assignment: 09/04/2021 Present Location: Car City Auto Centre Pte Ltd (HQ)
Date Inspected: 09/04/2021 Inspected At: Car City Auto Centre Pte Ltd (HQ)
Blk 9006 #01-198, Tampines Street 93
Singapore 528840
Estimated Period of Repair: 14.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 May 2022)	
Parts:	N/A	NISSAN NV200 1.6 DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ1106X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*TOTAL PARTS		-	*14,925.00 F	
Supplementary #1							
2	1		*ALTERNATOR BRACKET -8425	Bent	100.00 F	*100.00 F	
3	1		*BATTERY FUSE - 1013	Not Working	80.00 F	*80.00 F	
4	1		*R/SIDE MEMBER--1014	Bent	50.00 F	*50.00 F	
5	1		*L/SIDE MEMBER--1015	Bent	50.00 F	*50.00 F	
6	1		*R/AIR GUIDE PANEL--1006	Deformed	50.00 F	*50.00 F	
7	1		*R/F CTR WIND DEFLECTOR--1004	Torn	50.00 F	*50.00 F	
8	1		*WHEELHOUSE BRACKET--1124	Bent	90.00 F	*90.00 F	
9	1		*L/F WHEELHOUSE--1117	Buckled	90.00 F	*90.00 F	
10	1		*R/F W-HOUSE REINF--1180	Bent	230.00 F	*230.00 F	
11	1		*R/S MEMBER CLOSING PNL--1276	Bent	220.00 F	*220.00 F	
12	1		*L/S-MEMBER CLOSING PNL--1275	Bent	220.00 F	*220.00 F	
13	1		*AUTO GEAR BOX HOSE--1009	Bent	55.00 F	*55.00 F	
14	1		*R/F WHEELHOUSE--1118	Buckled	305.00 F	*305.00 F	
15	1		*R/F ENGINE BRACKET--8664	Bent	95.00 F	*95.00 F	
16	1		*FRONT ENGINE SUPPORT--8666	Bent	75.00 F	*75.00 F	
17	1		*RR ENGINE MOUNTING--8641	Bent	75.00 F	*75.00 F	
					Total Parts (\$)	1,835.00	16,760.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRAS	-	690.00
			Sub Total (\$\$)	0.00
				690.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	-	1,714.80
2	Total Paint Including Material	New	-	1,399.77
			Gross Labour Cost (\$\$)	0.00
				3,114.57

Report was unsubmitted during this print-out.

< END OF ESTIMATES >